

**Douglas County Surveyor's Record of  
Government Corners Renewed**

T 25      T. S.      R 2      R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

SE 1/16 corner in Section 24  
 Found - Hosford's BT's a 14" Cedar, now 16", scribing visible, N.74°E.,  
 25.9 ft. to face.  
 A 30" Cedar scribing visible, S.48°W, (Rec. S.47 1/2°E), 19.0 ft.  
 Set - 3/4" Pipe by Hosford's  
 Accessories Added:  
 38" Cedar, N.07°E., 13.7 ft. with "W" nail and plate.

Frank O. Williams  
 Glen McChensney  
 For: Weyerhaeuser Co.  
 Feb. 26, 1975  
 C.S. 59/11

2/26/75

Closing Corner for Secs. 24 and 25 only. East side.  
 Found - A 1 1/2" Iron pipe with steel cap. Ren. #11  
 A fir, 32" now 38" stump bears S.78 1/2°W., 37.0 ft. to center  
 & 35.7 ft. to face. (rec. 35.9 ft.) Stump is scribed "T25S R2W  
 S 25 P.S. 253 BT".  
 Set - I removed iron pipe and steel cap and replace with a Brass Cap at  
 1/4 Corner stamped: "Douglas County Surveyors Office"

99

L. E. Monrean  
 K. Cheney  
 Doug. Co. Surveyors  
 Office  
 June 10, 1976  
 C.S. 59/15

R	T 25 S	R
2	S 24	S 30 1
W	S 25	W
	1976	

New BT - A 10" Hemlock bears S.50°W., 121.9 ft. Tree double blazed & scribed  
 "T25S R2W S25 CS BT"  
 Mag. Declination 20° East.

6/10/76

Section corner for Secs. 2, 1, 11, and 12  
 Found - 1951 GLO brass cap properly stamped.  
 Orig. Corner stone set firmly on Northwest edge of cap. 5 notches  
 on West face, 1 notch on South face.  
 48" now 50" Fir stump, bears N.45°E., 7.2 ft. to center, 5.6 ft.  
 to face (orig. 1900, N.30°E., 5.9 ft; Rec. 1951, N.54 1/2°E.,  
 7.3 ft.) Stump has well healed blaze with Weyerhaeuser tag and  
 nail. I do not open for scribing.  
 A 6" now 21" I. Cedar, bears S.65°E., 33.0 ft. (Rec. 1900, S.68°E.,  
 33.0 ft; Rec. 1951, S.61°E.) Tree has well healed blaze with  
 Weyerhaeuser tag and nail, I do not open blaze.  
 A 36" now 42" D. Fir, bears N.22°W., 9.2 ft. to center, (Rec. 1900.  
 N.24°W; Rec. 1951, N.13°45'W) Tree has well healed blaze with Weyerhaeuser tag  
 and nail, I do not open blaze.  
 The SW BT is gone.

New BT - A 16" D. Fir (broken top) bears S.17 1/2°W., 46.3 ft. Tree double  
 blazed and scribed "T25S R2W S11 CS BT".

9/21/76

L.E. Monrean, Doug. Co. Surveyors  
 P. L. Earle  
 Sept. 21, 1976  
 C.S. 59/24

Center 1/4 Corner for Sec. 30  
 Set - 5/8" Iron Rod  
 From Which  
 A 36" Cedar bears N.31°30'W., 49.7 ft. scribed C1/4 S30 BT.  
 A 30" D. Fir bears S.74°30'E., 13.6 ft. scribed C1/4 S30 BT.

101

Glenn S. Baughman  
 For: Weyerhaeuser Co  
 Nov. 1976  
 M 56 - 58

1/4 Corner for Secs. 23 and 24.  
 Found - 1962 BLM brass cap, dislodged by uprooted orig. N.E. BT.  
 Orig. stone and I.P. per Ren. #25 not found.  
 Found - Orig. 65" now a 66" Fir is uprooted. Record bearing N.69°E., 11.9 ft.  
 Tree has well healed blaze. Root wad of tree now lies North of  
 corner position.  
 Orig. 30" Fir, now a badly decayed stump, (Rec. bears N.37°W.,  
 17.2 ft. Scribing found "1/4".  
 A 12" Hemlock now 15" stump bears S.43°E., 25.7 ft. (Rec. S.48°E.,  
 26.0 ft.) Stump scribed on open blaze "1/4 S24 CS BT". Ren. #59  
 A 7" Hemlock now 9" stump bears N.54 1/2°W., 82.3 ft. (Rec. N.57°W.,  
 83.6 ft. ) Stump scribed on open blaze "1/4 S23 CS BT".

102

Larry E. Monrean  
 Pete Earle  
 Douglas Co. Surveyors Office  
 Dec. 20, 1976  
 C.S. 59/26

No other bearing tree found.  
 Renewal - I reset 1962 BLM monument at 1/4 corner and add "Reset 1976"  
 to the cap.  
 New BT's- Set bridge spike in a Fir stump 64". Spike bears S.42 1/2°W.,  
 32.6 ft., spike is stamped "B.O. 1".  
 Set bridge spike in a Fir stump 54". Spike bears S.18 1/2°E.,  
 16.6 ft., spike is stamped "B.O. 2".