

Douglas County Surveyor's Record of
Government Corners Renewed

T 25 T. S. R 2 R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

113

Glen Mc Chesney
For: Weyerhaeuser Co.
April 5, 1977
(filed 12/80)
C.S. 58/8

1/4 Corner for Secs. 14 and 13.
Found - Orig. stone not found.
Orig. 36" now 44" Fir bears N.54°E., 9.2 ft. face overgrown.
Orig. 14" now 16" down rotted Hemlock bears N.58°W., 11.5 ft.
V. W. Hosford's 1 1/2" iron pipe. Ren. #23
24" Hemlock, scribing visible, bears N.28°W., 26.6 ft. Ren. #23
1962 GLO brass cap alongside I.P.
1962 11" now 12" Hemlock, bears N.66°W., 23.8 ft. scribing visible.
BT's referenced with Weyerhaeuser nails and plates in 1967.
New BT's -40" Fir, bears S.32°E., 15.7 ft.
58" Fir stump, bears S.10°W., 26.3 ft.

4/5/77

114

Glen Mc Chesney
For: Weyerhaeuser
July 13, 1976
(Filed 12/80)
C.S. 58/8

N 1/4 Corner for Sec. 4.
Found - 1951-63 GLO brass cap.
42" Hemlock, (1951) scribing visible. This tree will be removed
by current road construction. Tree bears N. 11 1/4°W., 27.4 ft.
14" Red Cedar, (1963), scribing visible bears S.35°W., 52.6 ft.
Tree is at westerly edge of R/W but should survive road
construction.

BRASS CAP TO BE RESET AFTER ROAD CONSTRUCTION.

Accessories added this date:

48" Fir, S.49°E., 71.2 ft. with W nail and plate.
40" Fir, S.71°W., 69.0 ft. with W nail and plate.
38" Fir, N.36°W., 72.9 ft. with W nail and plate.

54" Fir Stump N31°W 50.2 ft. " " " " " " 7/13/76

Info. Rec'd
6/81 J.R.

ADDED 2/24/78

W.C.

115

1/4 Corner for Sections 23 and 26.
Because of logging, road work and stream in area, the 1962 BLM
remonumentation by F.A. Brooks is destroyed and after a thorough search
of the locale, no evidence of the brass cap and I.P., or the orig.
monument stone is found.

Found - An orig. 12" Hemlock, now a 30" Hemlock stump, uprooted and
loose from ground, lies close to record bearing and distance
from orig. monument location (as determined from the other
orig. BT). This stump has good evidence of a blaze.
An orig. 9" Hemlock now a 13" DBH 6 ft. tall Hemlock snag, bears
S.25°E., 20.5 ft. Tree has partially opened double blaze. We
open further to find good "1/4" scribing marks.
From 1962 remonumentation, a 26" Hemlock now a 26" DBH 4 ft. tall
Hemlock snag bears S.03°E., 46.1 ft. (slope distance) (Rec.
S.03°E., 46.2 ft.) Tree has opened single blaze with scribing
1/4 S26 BT visible.

Because bearing and distances to evidence or orig. trees agree & the bearing
to the remonumentation tree agrees, we accept a monument location as deter-
mined by this evidence ^{and disregard the slope distance discrepancy} by assuming the dist. to the 1962 BT was measured
on the slope. HOWEVER, this orig. position is now virtually in a creek be-
cause of nearby road work.

Therefore we set - A witness corner is placed 10.0 ft. due East of orig.
monument location. This witness corner is monumented with a
DCSO 2 1/2" brass cap on a 1 1/2" I.P. 30" long., set firmly
and protrudes 2" from soil. Cap mkd. "Douglas County Surveyor"
T25S WC S23 S26 1/4 R2W 1981.

New BT's- The orig. SE BT now a 13" DBH Hemlock snag as previously described
bears S.04°W., 18.3 ft.
The 1962, 26" Hemlock as prev. described bears S.10°W., 46.8 ft.
A boat spike in a 47" Fir stump bears N.19°E., 6.38 ft. and is
stamped "WC BO 1"
A boat spike in a 49" Fir stump bears S.82 1/2°E., 35.87 ft. &
is stamped "WC BO 2".

All four bearing objects are tagged with new DCSO BT tags. 1/27/81

Stephen J. Flause
Deputy, Doug. Co.
Surveyors Office
Witness: Colleen
O'Toole
Jan. 27, 1981
C.S. 61/19

C O N T. N E X T P A G E