

Douglas County Surveyor's Record of
Government Corners Renewed

25 T. S. 3 R. W. W. M.

COLE CHAPMAN CO., EUGENE, ORE. 91002

Cont. ✓ 40" Fir bears South 78.0 ft. on slope marked S 8 T 25 S
R 3 W C. S. B. T.
and marked to a/c logging operation and barked blazed and scribed

1/4 CORNER 8 and 9
Renewed from original B. T. N. 55° E., 21 lks. which is in
good shape, original scribe marks are on bark.
Set 4"x4" Fir Post for corner and marked new B. T.
14" Maple bears S. 73° W., 40.0 ft. (on slope) Marked
1/4 S. 8 T 25 S R 3 W C. S. B. T.

SEC. COR. ON N. LINE OF TOWNSHIP FOR SECS. 32 and 33 T 24 S
R 3 W, 5 and 4 T 25 S R 3 W.

Renewed from Original B. T.'s.
A 16" Fir N. 75° W., 19 lks.
A 24" Cedar S. 60° E., 9 lks.
Set 4"x4" Fir Post for Corner from which New B. T's.
A 40" Cedar bears N. 10° E., 26.0 ft. marked
C. S. B. T.
A 15" Hemlock bears S. 58° W., 17.0 ft. marked S 5, T 24
S., R 3 W., C. S. B. T.

SECTION CORNER COMMON TO SECTIONS 25-36 T. 25 S., R. 3 W.

Set corner from fir tree scribe marks plain for the S. and
E., rest burned out. This tree was probably old tree in Sec.
30. The other trees were all down but evidence of cut marks
on same but no scribe mark. I set a Yew wood post for
corners and marked
10" Fir S 80° W., 5.5 ft.
6" Fir N. 15° W., 15.0 ft.

SEC. CORNER 29, 28, 32 and 33

Position identified from 4 original B. T.'s. as recorded in
office of Dist. Cadastral Engr. Set 4"x36" Cedar Post for
new corner.

SEC. COR. 32, 33, 5 and 4 T. 25 and 26 S., R 3 W

Location identified from 4 original B. T.'s. as recorded in
Gov't field notes. One B. T. now down and badly rotted.
Most of figures scaled off bark of tree in Sec. 4. Blazed
and scribed an
8" Yew N. 30° W., 28 lks. T. 25 S., R. 3 W. S 32 C. S. B. T.
and remarked in bark original B. T. in Sec. 4.

N 1/4 COR. SEC. 5

Located Cor. from Fir B. T. N. 28° W., 12 links
Set squared 3" ced. Post and Scribed new B. T.
30" Fir S. 2° W., 14.7 ft. marked 1/4 S 5, T 25 R 3, C. S. B. T.

S 1/4 COR. SEC. 5

Located by running line from SW. Cor. to SE. Cor Sec. 5.
3" Sq. Yew post and scribed (Blazed and Scribed on bark).
30" Fir S 12 1/2° E., 38.5 ft.
28" Fir marked 1/4 S 5, T. 25 R 3., C. S. B. T.
30" Fir marked 1/4 S 8, T. 25 R. 3., C. S. B. T.
28" Fir N 85 1/2° E., 23 ft.

North 1/4 corner to section 6 only.

Found Brass Cap. Pipe bent. We broke pipe when we attempted to straighten
it.

Set new brass cap mkd 1/4 S 6 T 25 S, R3W., Co. Sur. Office, 1954.
From which I blaze and scribe:

10 inch R. Fir, S. 29° W., 27.0 feet mkd. 1/4 S 6 T 25 S, R3W., CS BT.
NOTE: I found 24" Fir, S. 73° E., 16.5 feet dist. partly grown over with some
some scribing visible. Also found original BT, now a 36" stump. Some
scrib marks visible.

FO. O.K. SEPT. 1966 V.R.T.

(#8)

9

10

11

12

13

40

14

15

16

A. Boyer D. C. S.
Wit.
Floyd Norris
Clint Bember
June 1939

Wit.
N. E. Richardson
Larkin Rice
Jan. 1929
H. L. Eppstein Co. Sur.

Ben B. Irving Dep. Co. Sur.
Wit.
J. A. Irving
Joseph Brown
Jeff Palouse
April 26, 1930

Jan. 25, 1939
A. Boyer Dep. CS
Wit.
Tom Leatherwood
Ted Shelebarger
Carl Thornton
Ted Shelebarger

James W. Byron,
Dep. Co. Surveyor
Ray Irving
John Fee
Jan. 6, 1955.
C. S. File No. 469.

CDR. RENEWALS #1 THROUGH #15 MADE PRIOR TO GOVT SURVEY OF 1904

D. S. 35/38 i Vol. 4

P 80

SEE CORNER NO. 105

SEE CORNER NO. 19

RE-NEWED, SEE CORNER NO. 50

RE-NEWED, SEE CORNER NO. 53

RE-NEWED, SEE CORNER NO. 40

SEE GOV'T NOTES 14

SEE CORNER NO. 129