

Douglas County Surveyor's Record of
Government Corners Renewed

25 T. S. 3 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

August 15, 1958

$\frac{1}{4}$ Section Corner to Sections 29 and 30. 17
Found - Brass Cap & Orig. S. E. BT., now badly burned stump.
Orig. N.W. BT., now partly burned snag. No scribing on
either BT., both check for size, bearing, & distance..
Note - 1944 Notes (Norman Price) reversed distances to BT's. 58
New BT's: I scribe now 40" Cedar Snag N.40°W. 14.5 ft. $\frac{1}{4}$ S30 CS BT.
48" R. Fir bears N.61°E. 365.7 ft. scribed $\frac{1}{4}$ S29 CS BT.
Note - This area clear cut, no live trees near corner.
Lookout on Mt. Scott bears N.82°E.

March 24, 1960

$\frac{1}{4}$ Section Corner to Sections 22 and 23. 18
Found - Brass Cap, bent & partly out of the ground.
Burned 48" Fir Snag S.86°W. 27.1 ft. that shows good scribing "BT S".
No trace of S. E. BT. It would be in logging road.
Steel Fence Post at Corner. 60
I straighten & Reset Brass Cap at Corner.
New BT's: 18" Hemlock bears S.82°E. 49.0 ft. scribed $\frac{1}{4}$ S23 CS BT.
48" R. Fir bears N.24°W. 4.0 ft. scribed $\frac{1}{4}$ S22 CS BT.

Section Corner to Sections 4 & 5, T25-3W & Secs. 32 & 33 T24-3W. 19
Found - Scribed Stake & Steel Fence Post at Corner. REN. #10
Brass Cap, out of position & covered by downfall.
I reset Brass Cap at Corner & scribe New BT's. All existing BT's.
are now downfalls. All check record.
New BT's: 11" W. Fir bears N.45 $\frac{1}{2}$ °E. 19.7 ft. scribed S33 T24S R3W CS BT.
14" R. Cedar " S.61 $\frac{1}{2}$ °E. 30.3 ft. scribed S 4 T25S R3W CS BT.
7" W. Fir bears S.26°W. 6.0 ft. scribed S 5 T25S R3W CS BT.
5" Cedar bears N.36°W. 27.5 ft. scribed S32 CS BT.

$\frac{1}{4}$ Section Corner to Sections 3 and 2. 20
Found - Brass Cap at Corner & N. W. BT., now stump, shows good
scribing "B". N. E. BT. gone.
New BT's: Note - No Trees Near. 107
67" Fir Stump bears N.74°W. 35.3 ft. scribed $\frac{1}{4}$ S 3 CS BT.
60" Fir Stump bears S.68°E. 134.0 ft. scribed $\frac{1}{4}$ S 2 CS BT.

M 12-62
B. B. Irving
For: Doug. Co.
Lbr. Co.
May-June 1948
C.S. File
39/170

Center $\frac{1}{4}$ to Section 25. 21
Set - 1" G. I. P. with Brass Cap Mkd: County Surveyor's Office
C $\frac{1}{4}$ S25 T25S R3W
Bearing Trees: 8" Hemlock N.42°E. 18.6 ft. Mkd. C $\frac{1}{4}$ S25 CSBT.
8" Hemlock S.46°E. 24.4 ft. Mkd. C $\frac{1}{4}$ S25 CS BT.
July, 1966 - Cor. FOUND O.K. C.S. FILE NO. 54/27 V.R.T. xx

V. W.
Hosford
Dec. 29,
1960
C.S. File
No. 51/161

$\frac{1}{4}$ Corner to Sec. 36, T25-3W. & Sec. 1, T26-3W. 22
At this $\frac{1}{4}$ corner, I found the brass cap monument destroyed &
the two bearing trees had been felled.
I determined the true point of the corner from the stumps of
these trees, and at this point I drove a 2" iron pipe 30" long,
18" in the ground, from which:
30" Hemlock bears N.53°E. 17.6 ft. mkd: $\frac{1}{4}$ S36 253 B.T.
6" Tan-Oak bears S.19°E. 20.9 ft. mkd: $\frac{1}{4}$ S 1 253 B.T.

Miloe E.
Godfrey
Vernon Tracy
Clete Putnam
June 6, 1962
C.S. File No.
49/102

Closing Corner for Sections 18 and 19, T25S-2W. 23
Found - Iron Pipe with Brass Cap Mkd: U.S. General Land Office Survey, 1943
T25S T25S
Found - 13" R. Cedar N.70°E. 18.6 ft. scribing S24 R3W S18 C.
visible on still open scar. S19 C. 45
54" D. Fir S.70°E. 35.6 ft., shows good scars.
New BT's: 14" Hemlock S.28°E. 55.2 ft. Mkd: T25S R2W CC S19 CS BT.
8" Hemlock S.82 $\frac{1}{2}$ °W. 20.8 ft. mkd: T25S R3W S24 CS BT.

James W. Byron, Deputy
Milo Godfrey
Clete Putnam
C. S. File No. 49/78