

Douglas County Surveyor's Record of
Government Corners Renewed

T. 25 S. T. S. R. 3 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21081

24

$\frac{1}{4}$ Corner to Sec. 31, T25-3W. & Sec. 6, T26-3W.

Found - Iron Pipe with Brass Cap Mkd: "US General Land Office
1943 $\frac{1}{4}$ S31 S6 38

Fir Stump, 21", S.61°W. 4 ft., scribing still visible
in partly closed scar "S6 BT".

20" Fir Stump N.26°E. 7.3 ft., scribing visible in
open scar " $\frac{1}{4}$ S31 BT".

New BT's: 11" D.Fir S.11°E. 12.8 ft. Mkd: " $\frac{1}{4}$ S6 CS BT".

13" D.Fir N. 4°W. 17.4 ft. Mkd: " $\frac{1}{4}$ S31 CS BT".

Corner is 70 feet North of a fence line running E. & W.

Milo E.
Godfrey
& Crew
July 31, 1962
C.S. File
No. 49/102

Section Corner to Sections 17 - 18 - 19 - 20.

Found - G.L.O. Pipe & Brass Cap set in 1944.

22" Cedar S.43°W. 8.6 ft. Tree dead. Old face showing,
but scribing burned off. Rescribe Dead Cedar "T25SR3WS19CS BT.

No other Bearing Trees found.

Blaze & Scribe: 16" Red Cedar N.8 $\frac{1}{2}$ °E. 150.5 ft. Mkd: T25SR3WS17CSBT.

No other trees available.

Corner lies approx. 30 ft. North of Slide Creek Road & 50 ft.
South of Creek.

Nov. 7, 1962

25

Township Corner T24SS36 | S31 T24S

T25S R4WS 1 | S 6 R3W T25S

Found - Brass Cap set by Norman Price in 1944, buried under fill
on West side of logging railroad.

18" D.Fir S.58°E. 71.9 ft. Cut open & found traces of
scribing on badly rotted face.

Stump of 50" Fir S.69°W. 219.8 ft. (across Calapooia from
corner) Shows good scar.

No trace remains of N. E. or N. W. Bearing Trees.

Dig around & Straighten Up Brass Cap - Drive Cedar Stake Alongside.

Blaze & Rescribe: 18" D.Fir S.58°E. 71.9 ft. Mkd: T25S R3W S6 CS BT.

New BT's: 9" D.Fir N.82 $\frac{1}{2}$ °E. 66.1 ft. Mkd: T24S R3W S31 CS BT.

10" D.Fir S.81°W. 34.5 ft. Mkd: T25S R4W S1 CS BT.

18" D.Fir N. 4° W. 50.4 ft. Mkd: T24S R4W S36 CS BT.

Milo E.
Godfrey &
Crew.
May 27,
1963
C. S. File
No. 53/9

26

Section Corner to Secs. 19 - 20 - 29 - 30.

Found - Gov't. Brass Cap set in 1944.

Stump of 42" Fir N.80°E. 23.1 ft., scribing "S R 3 W".

Stump of 42" fir S.65 $\frac{1}{2}$ °E. (not S.74 $\frac{1}{2}$ °E) 29.0 ft., face badly
burned, no scribing visible.

Part of 10" Cedar S.73°W. 15.8 ft, mashed into ground.

42" Fir N.85°W. 43.6 ft., uprooted, butt end 8 ft. in the air.,
shows scar.

New BT's: 6" Red Cedar S.83 $\frac{1}{2}$ °W. 100.6 ft. Mkd: T25S R3W S30 CS BT.

24" D.Fir N.80°W. 108.7 ft. Mkd: T25S R3W S19 CS BT.

Rescribe - 42" Fir Stump S.65 $\frac{1}{2}$ °E. 29.2 ft. Mkd: S20 CS BT.

42" Fir Stump N.80°E. 24.6 ft. Mkd: S R 3W S29 BT.

No live trees available in N.E. & S.E. Quadrants.

FO. O.K.
July '66
e.g. 54/27

Milo E. Godfrey, Deputy
Wm. Stoffel & Mike Ston
December 1963
C. S. File No. 49/102

27

$\frac{1}{4}$ Section Corner to Secs. 19 & 20.

Found - G.L.O. Brass Cap, bulldozed out of position.

Stump of 14" Fir N.80°E. 31.7 ft., fd. scribing "20 BT".

Stump of 30" Fir S.77°W. 16.5 ft., face burned, no scribing.

Reset - Gov't. Brass Cap in proper position.

Rescribe - 34" Fir Stump S.77°W. 16.5 ft. Mkd: $\frac{1}{4}$ S19 CS BT.

New BT: 42" Fir Stump N.26°E. 39.0 ft. Mkd: $\frac{1}{4}$ S20 CS BT.

Note - Clear cut area, no live trees available - Corner lies just
North of top of spur ridge E. & W.

FO. O.K. July 1966

122