

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 25 S. T. S. R. 3. W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

47

$\frac{1}{4}$  Corner to Section 30 only, T25-2W.  
Found - 1943 GLO Brass Cap mkd.  
24" Fir, down & out of place, N. 49° E. 87.8 ft., scribe visible on burned face.  
30", now 57" Fir, S. 43° E. 104.9 ft, face burned, scribe barely visible, Rescribe " $\frac{1}{4}$ S CS". Tree is almost dead.  
New BT's: 12" D. Fir N. 44° E. 87.7 ft. Mkd:  $\frac{1}{4}$  S30 CS BT.  
4" Pine S. 12° E. 75.5 ft. Mkd: " $\frac{1}{4}$  S BT" (only)  
Note - This corner lies on N.W. edge of small clearing approximately 150 x 300 ft. on south slope.

48

$\frac{1}{4}$  Corner to Sections 36 only, T25-3W.  
Found - 1943 GLO Brass Cap Mkd: & in good condition.  
9" Fir, now stump 2' high, S. 8 $\frac{1}{2}$ ° W. 4.6 ft. (face), " $\frac{1}{4}$ S36 BT" on burned face.  
13" Fir, turned out, N. 38° W. 5.9 ft., face burned, fragmentary scribe visible.  
New BT's: 5" D. Fir S. 73° W. 38.9 ft. Mkd:  $\frac{1}{4}$  S36 CS BT.  
7" Hemlock N. 23° W. 22.4 ft. Mkd:  $\frac{1}{4}$  S36 CS BT.  
Note - Corner lies 25 ft. north of top of small spur sloping S. 60° E.

AMND. CORNER - (NOT  $\frac{1}{4}$  COR - SEE 1972-74 49  
BLM RESURVEY)

$\frac{1}{4}$  Corner to Section 31 only, T25-2W.  
Found - 1943 GLO Brass Cap mkd. & firmly set in good condition.  
6", now 9" Fir S. 52° E. 5.9 ft., shows good scar. Alive.  
36" Fir, now stump, N. 6 $\frac{1}{2}$ ° E. 62.0 ft., scribe visible on unhealed blaze. (recorded as 26" Fir)  
New BT: 6" D. Fir N. 67° E. 41.3 ft. Mkd:  $\frac{1}{4}$  S31 CS BT.  
Note - Corner lies approximately 650 ft. North of  $\frac{1}{4}$  Sec. 36 (See Above)

50

Sec. Cor. to Sections 25 & 36, R3W.  
Found - 1943 GLO Brass Cap mkd.  
Orig. 24" Hemlock N. 61 $\frac{1}{2}$ ° W. 20.5 ft., alive, shows scar.  
Other Orig. BT's. are now snags or gone.  
30", now 32" R. Cedar S. 43° W. 56.8 ft., scribe visible on unhealed blaze. Tree alive & in good condition.  
12", now 16" W. Fir Snag, N. 39° W. 31.7 ft., shows good scar. No trace of BT's. recorded in Ren. #11.  
New BT: 6" Yew N. 41° W. 25.4 ft. Mkd: T25S R3W S25 CS BT.  
Note - This corner lies 50 ft. north of Rock Creek Road, course E-W.

51

$\frac{1}{4}$  Corner to Sections 27 and 26.  
Found - 1943 GLO Brass Cap mkd.  
50", now 53" Fir south 35.6 ft., shows good scar. Alive.  
50", now 55" Fir S. 60 $\frac{1}{2}$ ° W. 104.9 ft., shows good scar. Alive.  
Orig. 1883 Hemlock S. 85° E. 44.9 ft., now shattered stump, no scribe found.  
New BT's: 9" Hemlock S. 54° W. 27.9 ft. Mkd:  $\frac{1}{4}$  S27 CS BT.  
10" R. Cedar N. 48° E. 32.5 ft. Mkd:  $\frac{1}{4}$  S26 CS BT.  
Note - Section Line is well blazed N. & S.

52

$\frac{1}{4}$  Corner to Sections 23 and 26.  
Found - 1943 GLO Brass Cap Mkd:  
24", now 26" Fir Snag, N. 73° E. 56.1 ft. Healed blaze, do not open. Snag approx. 60 ft. high.  
32", now 36" Fir S. 29 $\frac{1}{2}$ ° E. 35.6 ft. Alive, shows good scar.  
New BT: 8" Hemlock N. 34° E. 7.2 ft. Mkd:  $\frac{1}{4}$  S23 CS BT.  
Note - This corner lies on southerly slope of spur approx. 150 ft. North of small creek, course S. E.

Vernon "Ray" Tracy  
Joe Brady and Jack Heritage  
June 1966  
C. S. File No. 54/27