

Douglas County Surveyor's Record of
Government Corners Renewed

T. 25 S. T. S. R. 3 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21801

59

Sec. Corner to Sections 29 - 30 - 31 - 32.
Found-1943 GLO Brass Cap mkd.
30", now 42" Fir N. $77\frac{3}{4}^{\circ}$ E. 76.6 ft. Alive, shows very good
scar, we do not open. (1943 BT)
Orig. 1883 BT: 32", now 42" Fir N. $85\frac{1}{4}^{\circ}$ E. 63.4 ft. Alive, shows
frag. bark scribe.
All other BT's. are stumps or turnouts.
New BT's: 8" Maple S. 6° E. 7.7 ft. Mkd: T25S R3W S32 CS BT.
5" D. Fir S. 74° W. 18.9 ft. Mkd: S31 CS BT.
14" Laurel N. 84° W. 25.1 ft. Mkd: T25S R3W S30 CS BT.
7" D. Fir N. 11° E. 7.7 ft. Mkd: T25S R3W S29 CS BT.
Note - This corner lies on very steep south slope on E. edge
of cut off area.

60

$\frac{1}{4}$ Corner to Sections 22 and 23.
Found - 1943 GLO Brass Cap & BT's. as recorded Ren. #18.
Burned 48" Fir Snag, S. 86° W. 27.1 ft., scribe visible. (1943)
18" Hemlock, now stump, S. 82° E. 49.0 ft. scribed $\frac{1}{4}$ S23 CS BT.
48" Fir, now stump, N. 24° W. 4.0 ft. scribed $\frac{1}{4}$ S22 CS BT.
New BT's: 6" D. Fir N. 53° E. 50.2 ft. Mkd: $\frac{1}{4}$ S CS BT.
5" D. Fir S. 68° W. 39.8 ft. Mkd: $\frac{1}{4}$ S CS BT.
Note - Steel Fence Post alongside Brass Cap. Corner of timber
bears south approximately 200 ft.

61

$\frac{1}{4}$ Corner to Sections 14 and 13.
Found - 1943 GLO Brass Cap mkd.
Orig. 22" Hemlock, rotted & burned, N. $76\frac{1}{4}^{\circ}$ E. 20.5 ft.,
no scribe found.
Orig. 11" Hemlock S. 83° W. 7.9 ft., down & burned, no scribe.
1943-36" Fir, now stump S. 59° E. 37.0 ft., shows "T" scribe.
" 48" Fir, now burned & shattered snag, N. 77° W. 16.5 ft.,
shows " $\frac{1}{4}$ S14 BT" scribe in poor condition.
New BT's: 4" D. Fir S. 76° W. 12.6 ft. Mkd: $\frac{1}{4}$ S14 CS BT.
8" Hemlock S. $88\frac{1}{2}^{\circ}$ E. 61.0 ft. Mkd: $\frac{1}{4}$ S13 CS BT.
Note - Brass Cap lies on west side of 30" log 60 ft. west of
cutting line, course N. & S. in heavy reproduction.
Also has steel fence post alongside Brass Cap.

62

$\frac{1}{4}$ Corner to Section 14 and 23.
Found - 1943 GLO Brass Cap mkd.
36" Hemlock N. $56\frac{1}{2}^{\circ}$ E. 33.7 ft., now snag approximately
50 ft. high, face badly burned, no scribe found.
42" Fir, now shattered Snag 15' high, S. 79° W. 207.9 ft.,
frag. scribe visible on burned face.
New BT's: 7" D. Fir N. 6° W. 6.5 ft. Mkd: $\frac{1}{4}$ S14 CS BT.
9" D. Fir S. $20\frac{1}{2}^{\circ}$ W. 53.1 ft. Mkd: $\frac{1}{4}$ S23 CS BT.
Note - Steel fence post has been placed alongside Brass Cap.

63

$\frac{1}{4}$ Corner to Sections 12 and 13.
Found - 1943 GLO Brass Cap mkd.
48", now 52" Fir N. 4° W. 44.2 ft. Alive, shows good
scar. We do not open.
42" Fir, now rotted snag, S. 14° W. 52.8 ft., shows scribe.
New BT's: 9" Hemlock S. 63° W. 13.4 ft. Mkd: $\frac{1}{4}$ S13 CS BT.
8" Hemlock N. 24° E. 22.7 ft. Mkd: $\frac{1}{4}$ S12 CS BT.
Note - This corner lies on gentle S.E. slope in heavy fir &
hemlock timber.

Vernon "Ray" Tracy
 Joe Breach
 June & July, 1966
 C. S. File No. 54/27