

Douglas County Surveyor's Record of
Government Corners Renewed

T. 25 S. T. S. R. 3 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Vernon "Ray" Tracy
Jack Heritage
July 1966
C. S. File No. 54/ 27

$\frac{1}{4}$ Corner to Sections 13 and 24. 64
Found - 1943 GLO Brass Cap mkd.
Orig. 54" Fir, dead & rotted snag, N. $11\frac{1}{4}^{\circ}$ E. 24.4 ft., shows
fragmentary bark scribe.
Orig. 14", now 15" W. Fir Dead Snag, S. 11° E. 28.8 ft., shows
old scar. We do not open.
36", now 51" D. Fir N. 32° E. 77.9 ft., alive & shows good scar.
New BT's: 15" Maple N. 33° W. 8.9 ft. Mkd: $\frac{1}{4}$ S13 CS BT.
18" D. Fir S. 29° E. 52.6 ft. Mkd: $\frac{1}{4}$ S24 CS BT.
Note - This corner lies in area strewn with large boulders & heavy
Fir timber. Line well blazed E. & W.

$\frac{1}{4}$ Corner to Sections 17 and 20. 65
Found - 1943 GLO Brass Cap mkd.
14", now 20" Fir N. $87\frac{1}{2}^{\circ}$ W. 70.0 ft. Alive & in good condition,
shows very good scar. Do not open.
38", now 40" Fir, now turned out stump, S. 72° W. 34.3 ft., shows
healed blaze on bottom side.
New BT's: 11" D. Fir S. 28° E. 36.5 ft. Mkd: $\frac{1}{4}$ S20 CS BT.
6" D. Fir N. 55° E. 23.1 ft. Mkd: $\frac{1}{4}$ S17 CS BT.
Note - This corner lies on rolling top of spur, sloping N. W.
Find steel fence post set alongside Brass Cap.

$\frac{1}{4}$ Corner to Sections 7 and 18. 66
Found - 1944 GLO Brass Cap mkd. & stumps of 1944 resurvey BT's.
36", now 40" I. Cedar Stump, N. 65° W. 85.8 ft., shows scribe
up the unhealed face.
14", now 20" I. Cedar Stump, S. 25° E. 81.8 ft., scribe visible on
nearly healed blaze.
New BT's: 5" D. Fir N. 80° W. 35.7 ft. Mkd: $\frac{1}{4}$ S 7 CS BT.
14" D. Fir S. 60° E. 21.0 ft. Mkd: $\frac{1}{4}$ S18 CS BT.
Note - Corner lies on fairly steep S. W. slope approx. 100 ft.
N. 75° E. of old unused logging road, course NE. - SW.

$\frac{1}{4}$ Corner to Sections 19 and 30. 67
Found - No trace of Brass Cap called for.
14", now 20" Hemlock N. 22° E. 51.5 ft., shows " $\frac{1}{4}$ S19BT" on
partially healed blaze. Alive & in good condition. #141
8", now 11" Fir S. 51° W. 11.9 ft., healed blaze, chopped out,
scribe marks visible on pitched face. Alive.
Set - Brass Cap at Cor. Mkd: County Surveyor's T25S R3W $\frac{1}{4}$ S 19
Office, 1966 S 30
New BT: 16" D. Fir S. 12° W. 19.8 ft. Mkd: $\frac{1}{4}$ S30 CS BT.
Note - Brass Cap lies 1 ft. North & 2 ft. West of east end of 54"
corrugated steel culvert under new Gassy Creek access road,
course E., curving to S.W. - Fo. O.K. Feb 1968 - BUILD MOUND of STONE AROUND BRASS CAP.

Sec. Corner to Sections 21 - 22 - 27 - 28. 68
Found - 1943 Brass Cap mkd. with steel fence post alongside.
Orig. 28", now 32" Hemlock S. 55° E. 18.5 ft., with 1943 scribe
visible on partially healed blaze.
N.E. & N.W. BT's. are now stumps with scribe showing.
Both BT's. to S.W. are gone due to Cat. Road.
New BT's: 7" Hemlock N. 60° E. 13.8 ft. Mkd: T25S R3W S22 CS BT.
8" Hemlock S. 28° W. 58.5 ft. Mkd: T25S R3W S28 CS BT.
5" Hemlock N. 73° W. 42.1 ft. Mkd: S21 CS BT.
Note - This corner lies in old, logged unit, approx. 600 ft. West
of N.-S. cutting line.

Sec. Cor. to Sections 17 - 18 - 19 - 20. 69
Found - 1944 GLO Brass Cap mkd. See Ren. No. 25.
22" Cedar Snag S. 43° W. 8.6 ft. scribed T25SR3WS19 CS BT.
16" Red Cedar N. $8\frac{1}{2}^{\circ}$ E. 150.5 ft., scribed and alive.
New BT: 6" Maple N. 75° W. 15.2 ft. Mkd: T25S R3W S18 CS BT.
Note - Fence Corner bears S. 5° W. 65.3 ft., course S. & W.