

Douglas County Surveyor's Record of
Government Corners Renewed

T. 25 S. T. S. R. 3 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

70

$\frac{1}{4}$ Corner to Sections 27 and 28.

Found - 1943 GLO Brass Cap mkd:

48" Fir, now stump & turned out, S. 42° E. 42.2 ft.,
no scribe found.

42", now 46" Fir, now stump, S. 44° W. 38.9 ft., frag.
scribe visible on partially healed blaze.

New BT's: 5" Hemlock S. 33° E. 27.8 ft. Mkd: $\frac{1}{4}$ S27 CS BT.

5" Red Cedar N. 86° W. 47.2 ft. Mkd: $\frac{1}{4}$ S28 CS BT.

Note - This corner lies approx. 200 ft. north of small creek,
course east.

Brass Cap in middle of small blowdown Hemlock.

71

$\frac{1}{4}$ Corner to Sections 29 and 28.

Found - 1943 GLO Brass Cap Mkd.

Orig. 1883 48", now 50" Stump, S. $71\frac{1}{2}^{\circ}$ E. 25.1 ft., shows
old bark scribe " $\frac{1}{2}$ " S BT".

Orig. 60" Fir, turned out & badly broken up, N. 54° W.
11.2 ft., frag. bark scribe found.

22", now 42" Fir stump, S. 94° E. 29.7 ft., shows scribe
on unhealed blaze.

12" Fir, now stump S. 5° W. 41.6 ft., no scribe found.

New BT's: 24" D. Fir S. 30° W. 63.3 ft. Mkd: $\frac{1}{4}$ S29 CS BT.

26" D. Fir N. $38\frac{1}{2}^{\circ}$ W. 84.7 ft. mkd: $\frac{1}{4}$ S29 CS BT.

Note - Corner lies on N. - S. cutting line cut off to East.

72

Sec. Cor. to Sections 21 - 20 - 28 - 29.

Found - 1943 GLO Brass Cap mkd.

All BT's as of 1943 resurvey, are gone, down or stumps,
badly burned & rotted, no scribe marks found.

Corner lies approx. 100 ft. north of corner of timber in dense
reproduction of D. Fir & Hemlock.

New BT's: 3" Hemlock N. 42° W. 3.5 ft. Mkd: S20 CS BT.

4" Hemlock S. $9\frac{1}{2}^{\circ}$ E. 25.5 ft. Mkd: S28 CS BT.

4" D. Fir S. 74° W. 6.0 ft. mkd: S29 CS BT.

4" D. Fir N. 34° E. 25.4 ft. Mkd: S21 CS BT.

Note - Steel Fence Post set alongside Brass Cap.

73

$\frac{1}{4}$ Corner to Sections 20 and 29.

Found - 1944 GLO Brass Cap mkd.

26", now 27" R. Cedar S. 33° W. 15.2 ft., burned face, nearly
dead, no scribe found.

No trace of N.E. BT. due to old cat. logging.

New BT's: 18" I. Cedar N. 36° E. 49.4 ft. Mkd: $\frac{1}{4}$ S20 CS BT.

20" Red Cedar S. 35° W. 36.9 ft. Mkd: $\frac{1}{4}$ S29 CS BT.

27" Red Cedar (1943 BT) S. 33° W. 15.2 ft. Mkd: $\frac{1}{4}$ S29 CS BT.

Note - This corner lies on nearly E-W cutting line, cut off to
north. Steel Fence Post alongside Brass Cap.

74

$\frac{1}{4}$ Corner to Sections 22 and 27.

Found - 1943 GLO Brass Cap mkd. with steel fence post alongside.

Orig. 1883 BT's remarked in 1943, as follows:

36", now 42" Red Cedar N. 42° W. 12.5 ft. mkd: $\frac{1}{4}$ S22 BT,
showing on partially healed blaze. Alive.

42", now 48" Fir S. 20° E. 10.6 ft., alive with 50" log lying
against healed blaze. Due to size we mark new BT's.

New BT's: 9" Hemlock N. 80° W. 32.2 ft. mkd; $\frac{1}{4}$ S22 CS BT.

9" Hemlock S. 50° E. 26.2 ft. mkd: $\frac{1}{4}$ S27 CS BT.

Note - This corner lies on E. - W. cutting line, cut off to
North several years ago.

Vernon "Ray" Tracy
Jack Heritage
July 1966
C. S. File No. 54/27

RE-REVIEWED SEE CORNER NO. #138

RE-REVIEWED SEE CORNER NO. #142