

Douglas County Surveyor's Record of
Government Corners Renewed

T. 25 S. T. S. R. 3 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

87

1/4 Corner to Sec. 2, T25-3W. & Sec. 35, T24-3W.
Found - GLO Brass Cap mkd., 1944 with steel fence post alongside.
S.W. BT., now stump & N.W. BT. down, scribe visible.
New BT's: 12" Hemlock N. 5 1/2° W. 39.6 ft. mkd. 1/4 S35 CS BT.
Rescribe Orig. BT. to S. W.: 44" D. Fir Stump S. 5° W. 34.3 ft. mkd:
" 1/4 S 2 CS BT".

Note - Corner lies approx. 200 ft. E. of road, course N. & S., curving to east passing approx. 100 ft. north of corner.

88

Section Corner to Sections 10 - 11 - 14 - 15.
Found - GLO Brass Cap mkd, 1943, with steel fence post alongside.
All BT's. in very poor condition or gone completely.
Find scribe on 1943 resurvey BT. to N. E.
New BT's: 5" D. Fir N. 13° E. 10.6 ft. mkd: S 11 CS BT.
4" D. Fir N. 42° W. 12.6 ft. mkd: S10 CS BT.
7" D. Fir S. 14° W. 16.4 ft. mkd: T25S R3W S15 CS BT.
No other trees available.

Note - This corner lies on very steep, west slope approx. 300 ft. E. of branch of S. Fork of Hinkle Creek in Greasewood brush.

89

1/4 Corner to Sections 9 and 16.
Found - GLO Brass Cap mkd., 1944, with steel fence post alongside.
8", now 16" D. Fir N. 10° E. 17.2 ft., prev. opened & shows "B" scribe. Alive.
12", now 21" W. Fir S. 42° W. 41.6 ft., frag. scribe visible on badly injured blaze.
New BT's: 8" R.Cedar N. 22° E. 9.2 ft. mkd. "1/4 S 9 CS BT."
7" D. Fir S. 15° E. 16.9 ft. mkd: 1/4 S16 CS BT.

Note - Brass Cap lies between two rotted logs in young fir and hemlock timber

90

Section Corner to Sections 9 - 10 - 15 - 16.
Found - GLO Brass Cap mkd. 1943, with steel fence post alongside.
14", now 20" Hemlock S. 88 1/2° E. 6.6 ft., shows partial scribe on nearly healed blaze.
All other BT's. destroyed by logging, now stumps, turnouts, etc.
New BT's: 12" Hemlock S. 75° W. 60.7 ft. mkd: T25S R3W S16 CS BT.
6" Hemlock N. 56° W. 33.5 ft. mkd: S 9 CS BT.
6" D. Fir N. 4 1/2° E. 48.6 ft. mkd: S 10 CS BT.

Note - Corner lies approx. 375 ft. E. of creek, course N. on flat bench.

91

Section Corner to Sections 3 - 4 - 9 - 10.
Found - GLO Brass Cap mkd. 1943, with steel fence post alongside, and following BT's. recorded in Ren. #5.
8", now 13" D. Fir S. 58 1/2° W. 23.8 ft., shows good scar. Do not open.
6", now 12" Hemlock N. 51° W. 3.3 ft., shows good scar. Do not open.
Maple to S.E., down. 20" Fir to S.E. gone.
Cedar Stump to N.E. very badly burned. 62" Fir to NE., now stump.
New BT's: 9" D. Fir N. 81° E. 18.4 ft. mkd: T25S R3W S 3 CS BT.
11" D. Fir S. 18° E. 31.3 ft. mkd: T25S R3W S10 CS BT.

Note - Corner lies on gentle, N. E. slope on bench.

92

Section Corner to Sections 11 - 12 - 13 - 14.
Found - GLO Brass Cap mkd. 1943, with steel fence post alongside.
Orig. 36", now 40" Fir N. 86 1/2° E. 26.4 ft., shows visible bark scribe "S12". Alive.
Orig. 20", now 23" R. Cedar S. 68 1/4° E. 15.2 ft., badly burned, Alive.
Orig. 24", now 30" Hemlock S. 53° W. 11.9 ft. Prev.opnd. Scribe vis.
Orig.N. W.BT., now stump. 1943 BT. to N.E., down & rotted.
New BT's: 30" Hemlock S. 53° W. 11.9 ft. rescrbd. "T25S R3W S14 CS BT".
6" D. Fir N. 53° W. 20.8 ft. mkd: T25S R3W S11 CS BT.
17" R.Cedar S. 41° E. 49.1 ft. mkd: T25S R3W S13 CS BT.
10" Hemlock N. 16° E. 15.5 ft. Mkd: T25S R3W S12 CS BT.

Note - Corner lies on very steep, N. W. slope.

Vernon "Ray" Tracy
Joe Brady & Jack Heritage
July and August, 1966
C. S. File No. 54/27