

Douglas County Surveyor's Record of
Government Corners Renewed

T. 25 S. T. S. R. 3 W. R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

93

Sec. Corner to Sections 23 - 22 - 15 - 14.
Found - GLO Brass Cap mkd. 1943, & steel fence post alongside.
Orig. 12", now 16" Fir N. 35° E. 27.14 ft., prev. opened & shows
"T25S RS", scribe, (now Dadd Snag)
Orig. 20", now 27" R. Fir S. 95° E. 19.8 ft., Now Stump, shows scar.
Orig. 32", now 48" Fir S. 64° W. 9.2 ft., Alive, shows good scar.
Orig. N.W. BT., now gone & 1943 BT. to N.W., now turned out stump.
New BT's; 7" Hemlock N. 36° E. 5.5 ft. mkd. T25S R3W S14 CS BT. Alive.
Orig. 16" Hemlock N. 70° W. 47.5 ft. mkd. T25S R3W S15 CS BT.
New 8" Hemlock S. 4° E. 21.7 ft. mkd. T25S R3W S23 CS BT.

94

¼ Corner to Sections 11 and 14.
Found - GLO Brass Cap mkd. 1943, & steel fence post alongside.
28", now 32" Cedar Stump S. 89° W. 38.3 ft., shows scribe.
N.E. BT., now burned & turned out stump, no scribe found.
New BT's: 6" D. Fir N. 73° E. 5.5 ft. mkd. ¼ S11 CS BT.
7" D. Fir S. 45° W. 12.9 ft. mkd. ¼ S14 CS BT.
To expose Brass Cap, we cut a 24" piece out of a log & straighten B.C.
Note - Corner lies in old logging, now grown up to very thick D. Fir
reproduction.

95

¼ Corner to Sections 5 and 4.
Found - GLO Brass Cap, 1944, with steel fence post alongside.
20", now 24" Fir Stump S. 28° E. 12.5 ft., shows healed blaze.
40" Fir Stump N. 43½° W. 23.8 ft. shows ¼ S5T25S R3W CS BT.,
on unhealed blaze. See Ren. #7.
14", now 20" Cedar Stump, N. 14½° W. 33.7 ft., shows ¼ SS BT"
scribe on partially healed blaze.
New BT's: 4" W. Fir S. 14° E. 28.0 ft. Mkd: ¼ S 4 CS BT.
6" R. Cedar S. 42° W. 16.2 ft. mkd: ¼ S 5 CS BT.
Note - This corner lies on steep S.W. slope approximately 400 ft.
North of Hinkle Creek Road.

96

¼ Corner to Section 9 and 10.
Found - GLO Brass Cap mkd. 1943, with steel fence post set alongside.
16", now 34" Fir N. 8½° W. 72.6 ft., shows very good scar.
We do not open.
S. E. BT. now gone.
New BT: 5" D. Fir S. 58° E. 9.7 ft. mkd. ¼ S10 CS BT.
Note - This corner lies on E. edge of rocked road, course S. 30° W.
& N. 30° E.

97

¼ Corner to Sections 14 and 15.
Found - GLO Brass Cap mkd. "¼ 15/14 1943" with steel fence pst. alngsd.
All BT's. are stumps except Orig. S.E. Scribe found on
1943 BT. to S. W.
New BT's: 7" D. Fir S. 37° W. 12.3 ft. mkd. ¼ S15 CS BT.
6" D. Fir S. 55° E. 15.2 ft. mkd. ¼ S14 CS BT.
Note - Corner lies in old logged unit now covered with very dense
reproduction of D. Fir - Hemlock & Cedar.

98

¼ Corner to Sections 11 and 12.
Found - GLO Brass Cap mkd. "¼ S11/S12 1943". Bent over & buried.
We dig up & straighten Brass Cap & Reset.
All BT's. destroyed by logging & fire. Scribe visible on
40" Fir Stump S. 74½° E. 29.7 ft.
New BT's: 5" D. Fir S. 40° W. 19.4 ft. mkd. ¼ S11 CS BT.
24" Cedar Stump S. 67° E. 53.3 ft. mkd. ¼ S12 CS BT. (7 ft. high)
Note - Corner lies in old logged & burned area growing up to small
fir & hemlock in heavy greasewood & willow brush.

Vernon "Ray" Tracy
Joe Brady & Jack Heritage
July & August, 1966
C. S. File No. 54/27