

Douglas County Surveyor's Record of
Government Corners Renewed

T. 25 S. T. S. R. 3 W. R.W.W.M.

105
1/4 Corner to Sections 8 and 9.
Found - GLO Brass, 1944, with steel fence post alongside.
Orig. 30", now 36" Fir N. 55° E. 13.9 ft., shows bark scribe as recorded in Ren. #9.
12", now 19" Maple S. 74 1/4° W. 33.0 ft., shows healed blaze. We do not open.
New BT's: 11" R. Cedar S. 33° W. 36.6 ft. mkd. 1/4 S 8 CS BT.
8" W. Fir N. 18° E. 39.8 ft. mkd. 1/4 S 9 CS BT.
Note - This corner lies on steep N. W. slope with blazed lines N-S-E.

106
Sec. Corner to Sections 1 - 2 - 11 - 12.
Found - GLO Brass Cap, 1943, & stumps of 1943 BT's., All are cut too low or scribe burned off.
New BT's: 6" Maple N. 60° E. 44.4 ft. mkd. S 1 CS BT.
14" Hemlock N. 32 1/2° W. 126.6 ft. mkd. T25S R3W S2 CS BT.
Remark Stump of 1943 BT: 15" Yew Stump N. 8 1/2° W. 21.8 ft. mkd. T25S R3W S 2 CS BT.
No other trees available.
Note - Corner lies on steep west slope approx. 100 ft. W. of top of Mt.

107
1/4 Corner to Sections 2 and 3.
Found - GLO Brass Cap, 1944, and Stumps of BT's. as recorded in Ren. #20 which are beginning to rot.
New BT's: 4" D. Fir S. 9° W. 12.8 ft. mkd. 1/4 S 3 CS BT.
4" Maple S. 21° E. 17.0 ft. mkd. 1/4 S 2 CS BT.
Note - This corner lies 20 ft. west of old logging road, course N.W. curving to S. W.

108
Section Corner to Sections 17 - 16 - 20 - 21.
Found - GLO Brass Cap, 1943, with steel fence post set alongside.
All BT's. called for in field notes are now destroyed by logging. Stumps & Snags remain.
New BT's: 6" D. Fir S. 35° W. 15.3 ft. mkd. T25S R3W S20 CS BT.
5" Chinq. S. 76° E. 9.6 ft. mkd. S 21 CS BT.
50" Fir Stump N. 29° E. 23.1 ft. (Orig. BT)
Rescribed "T25S R3W S16 CS BT".
No other trees suitable.

109
1/4 Corner to Sections 16 and 21.
Found - GLO Brass Cap, 1943, with steel fence post set alongside.
Both BT's. destroyed by logging.
New BT's: 7" D. Fir S. 9 1/2° E. 33.0 ft. mkd. 1/4 S21 CS BT.
9" D. Fir N. 75° E. 9.8 ft. mkd. 1/4 S16 CS BT.
13" D. Fir S. 77° W. 16.0 ft. mkd. 1/4 S21 CS BT.
Note - This corner lies on N. edge of old unused logging road, course E.-W. approx. 225 ft. East of main Hinkle Creek Road.

110
1/4 Corner to Sections 16 and 17.
Found - GLO Brass Cap mkd., 1944, with steel fence post alongside.
16", now 21" D. Fir N. 30° E. 37.0 ft., shows good scar. Do not open. Alive.
22", now 29" D. Fir N. 15° W. 12.5 ft., shows good scar. Do not open. Alive.
(Since both BT's. above are of usable size, mark new trees)
New BT's: 8" Hemlock N. 69° E. 1.3 ft. mkd. 1/4 S16 CS BT.
15" R. Cedar S. 7° W. 30.1 ft. mkd. 1/4 S17 CS BT.
Note - Corner lies on N.W. slope approx. 130 ft. south & 50 ft. East of creek, course N.E.

Vernon "Ray" Tracy
Jack Heritage
August, 1966
C. S. File No. 54/27