

Douglas County Surveyor's Record of
Government Corners Renewed

T. 25 S. T. S. R. 3 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

111

$\frac{1}{4}$ Corner to Sections 8 and 17.
Found - GLO Brass Cap mkd., 1944, with steel fence post alongside.
1944 BT's., as follows:
20", now 30" W. Fir N. 3° E. 15.2 ft. Alive, shows good scar.
We do not open.
20", now 25" W. Fir S. 25° E. 29.7 ft., now Snag, shows good scar.
New BT's: 18" Yew S. 25° W. 26.4 ft. mkd. $\frac{1}{4}$ S17 CS BT.
12" R.Cedar N. 12° E. 18.3 ft. mkd. $\frac{1}{4}$ S 8 CS BT.
Note - Corner lies on gentle N.E. slope.

112

$\frac{1}{4}$ Corner to Sections 7 and 8.
Found - Log 10 ft. long 48" diam. that undoubtedly lies on top
of corner. GLO Brass Cap is probably buried under this log.
12", now 18" Fir, now stump, S. 67° E. 32.3 ft., shows good
scar, we do not open.
30", now 46" Fir, West 29.0 ft., prev. opened & shows "7" scribe.
New BT's: 9" D. Fir N. 64° E. 33.9 ft. mkd. $\frac{1}{4}$ S 8 CS BT.
17" D. Fir N. 15° W. 21.8 ft. mkd. $\frac{1}{4}$ S 7 CS BT.
Note - This corner lies on steep, S.W. slope, approx. 120 ft. N. of bottom
of ravine, course N.W.

113

Section Corner to Sections 5 - 6 - 7 - 8.
Found - GLO Brass Cap mkd., 1944, with steel fence post alongside.
Orig. 18", now 20" Fir S. $73\frac{1}{2}^{\circ}$ W. 9.9 ft., shows old scar. Do not open.
(Rescribe "T25S R3W S 7 CS BT".
All other BT's. now stumps.
New BT's: 16" D. Fir S. 59° W. 49.3 ft. mkd. T25S R3W S7 CS BT.
18" D. Fir S. 84° E. 55.3 ft. mkd. T25S R3W S8 CS BT.
No other trees available.
Note - This corner lies on steep S. E. slope, cut off in Sec. 8.

114

$\frac{1}{4}$ Corner to Sections 21 and 22.
Found - GLO Brass Cap in mound of stone, mkd., 1943, with steel fence post
alongside & stump of one BT, as follows:
32", now 34" Fir, N. 59° E. 31.0 ft., shows " $\frac{1}{4}$ S BT", scribe on
partially healed blaze. Now Stump.
New BT's: 10" Hemlock N. 18° E. 25.8 ft. mkd. $\frac{1}{4}$ S22 CS BT.
11" Hemlock N. 70° W. 62.7 ft. mkd. $\frac{1}{4}$ S21 CS BT.

115

$\frac{1}{4}$ Corner to Sections 20 and 21.
Found - GLO Brass Cap mkd. in 1943, bent over & steel fence post alongside.
Reset - Brass Cap in proper position in Mound of Stone.
64" Fir, now Stump, S. $75\frac{1}{2}^{\circ}$ E. 37.6 ft., shows " $\frac{1}{4}$ S21 BT" scribe
on unhealed blaze.
Stump of possible BT to N.W., cut too low for scribe.
New BT's: 5" D. Fir S. 63° W. 48.8 ft. mkd. " $\frac{1}{4}$ S20 CS BT.
5" D. Fir S. 85° E. 28.6 ft. mkd. $\frac{1}{4}$ S 21 CS BT.

116

Cl. Corner to Sections 6 & 7 only, T25-2W.
Found - GLO Brass Cap mkd. in 1943.
30", now 34" Fir, 6' high stump, N. $50\frac{3}{4}^{\circ}$ E. 15.2 ft., scribe
marks visible on nearly healed blaze.
32", now 36" Fir, 6' high stump, S. $20\frac{1}{2}^{\circ}$ E. 13.9 ft., blaze
nearly healed.
New BT's: Mark only available trees.
8" Yew S. 63° E. 168.2 ft. mkd. T25S R2W S 7 CC CS BT.
12" Hemlock N. 7° E. 222.3 ft. mkd. T25S R2W S6 CC CS BT.
Note - Corner lies in old logged-off area.

Vernon "RAY" Tracy
Jack Heritage
August, 1966
C. S. File No. 54/27