

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 25 S. T. S. R. 3 W. R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

117  
Sec. Cor. to Secs. 1 & 12 only, T25-3W.  
Found - GLO Brass Cap mkd. in 1943 with steel fence post  
set alongside.

All BT's. destroyed by logging. No live trees available.

Mark stumps for New BT's:

40" Fir Stump S. 73° W. 41.2 ft. mkd. T25S R3W S12 CS BT.

43" Fir Stump N. 71° W. 46.0 ft. mkd. T25S R3W S 1 CS BT.

Note - This corner lies approx. 500 ft. North of closing corner  
of Sections 6 & 7, T25-2W, See Ren. #116, in large  
logged-off area.

118  
¼ Corner to Sections 4 and 9.

Found - GLO Brass Cap mkd. in 1944, set at the base of a dead  
Red Cedar, as recorded in Ren. #6.

8", now 11" Red Cedar N. 40° E. 4.0 ft., scribe visible on  
partially healed blaze. Tree split, will probably die.

6", now 8" Red Cedar S. 82° W. 7.3 ft., scribe visible  
on partially healed blaze, beginning to die.

New BT's: 10" Red Cedar N. 25° W. 7.8 ft. mkd. ¼ S 4 CS BT.

14" W. Fir S. 22° E. 50.3 ft. mkd. ¼ S 9 CS BT.

Note - This corner lies 20 ft. West of Hinkle Creek Road.

119  
¼ Corner to Sections 6 and 7.

Found - GLO Brass Cap mkd. in 1944.

Orig. 20", now 24" Fir, S. 81½° W. 9.9 ft., partial  
scribe visible on chopped out blaze. Alive.

46", now 48" Fir S. 23½° W. 30.4 ft., blaze pitched #134  
over, no scribe visible.

Orig. N. W. BT., now nearly rotted away, no scribe found.

1944 BT. to N. W., now stump with pitched face.

New BT: 22" I. Cedar N. 29½° W. 45.8 ft. mkd. ¼ S 6 CS BT.

Note - Corner lies on moderate S. W. slope, approx. 470 ft.  
East of Creek, course N.W.

120  
¼ Corner to Sections 15 and 22.

Found - GLO Brass Cap mkd. in 1943, with steel fence post alongside.

Both Orig. BT's. are down & out of place, scribe marks  
visible on S.W. BT.

1943 BT, gone completely.

New BT's: 5" D. Fir S. 31° E. 16.2 ft. mkd. ¼ S 22 CS BT.

5" Cedar S. 71½° W. 31.1 ft. mkd. ¼ S 22 CS BT.

8" D. Fir N. 47° W. 42.4 ft. mkd. ¼ S 15 CS BT.

Note - Corner lies on S.W. slope, 1 ch. east of small creek,  
course N. 15° W.

121  
¼ Corner to Sections 15 and 16.

Found - GLO Brass Cap mkd. in 1943 with steel fence post alongside.

Scribe Marks "¼ S15 BT" found on 1943 BT. to N.E., now  
shattered snag. Other BT's. destroyed by logging

New BT's: 5" D. Fir S. 82° E. 23.8 ft. Mkd: ¼ S15 CS BT.

7" D. Fir N. 53° E. 19.9 ft. mkd. ¼ S15 CS BT.

6" D. Fir N. 55° W. 8.1 ft. mkd. ¼ S16 CS BT.

Note - This corner lies in very dense reprod. of D. Fir, Hemlock  
& Cedar.

122  
¼ Corner to Sections 19 and 20.

Found - GLO Brass Cap mkd. in 1944. & Stumps of BT's., See Ren. #28.

14" Fir Stump, rotting badly, N. 80° E. 31.7 ft.,  
fragmentary scribing visible.

34" Fir Stump, S. 77° W. 16.5 ft., scribe visible.

42" Fir Stump, beginning to rot, N. 26° E. 39.0 ft., #143  
scribe visible, "¼ S20 CSBT".

New BT's: 4" D. Fir S. 68° W. 11.1 ft. mkd. ¼ S19 CS BT.

4" D. Fir S. 53½° E. 89.7 ft. mkd. ¼ S20 CS BT.

Note - This corner lies in N. - S. Fence.

Vernon "Ray" Tracy  
Jack Heritage &  
August & Sept. 1966  
C. S. File No. 54/27