

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 25 S. T. S. R. 3 W. R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

128

Section Corner to Sections 15 - 16 - 21 - 22.

Found - GLO Brass Cap mkd. in 1943 with steel fence post set alongside.  
16" Fir, now Snag, S. 12° E. 13.2 ft., shows scribe on unhealed blaze.  
18" Fir, now Snag, S. 61½° W. 25.1 ft., shows scribe on unhealed blaze.  
20" Fir, now shattered Snag, N. 32½° W. 4.0 ft., scribed face  
lying face down, fragmentary reverse scribe visible.  
Other Bearing Trees gone.

New BT's: 12" Red Cedar N. 5° W. 30.5 ft. mkd: T25 S R3W S16 CS BT.  
16" Hemlock N. 38° E. 38.0 ft. mkd. T25S R3W S15 CS BT.  
9" Hemlock S. 64° W. 29.5 ft. mkd. T25S R3W S21 CS BT.  
4" Hemlock S. 61° E. 15.4 ft. mkd. S22 CS BT.

129

¼ Corner to Sections 5 and 8.

Found - GLO Brass Cap mkd. in 1944.  
24"?, now 38" Fir N. 85° E. 22.4 ft., shows "¼ S5T25S R3 BT"  
and very good scar. S. E. BT. is now stump. Ren. #15.  
New BT's: 10" Hemlock S. 66½° E. 31.2 ft. mkd. ¼ S 8 CS BT.  
9" Hemlock N. 55° E. 21.9 ft. mkd: ¼ S 5 CS BT.  
Note - This corner lies on moderate N.E. slope approx. 220 ft. E.  
of top of spur, sloping North.

130

¼ Corner to Sections 18 and 19.

Found - GLO Brass Cap mkd. in 1944.  
40", now 42" D. Fir S. 67° W. 9.2 ft., shows very good scar. Alive.  
42", now 42" D. Fir N. 57½° E. 76.6 ft., now Stump, shows  
"¼ S18" scribe on unhealed blaze.  
New BT's: 7" Chinq. S. 37° E. 9.2 ft. mkd: ¼ S19 CS BT.  
6" D. Fir N. 58° W. 10.8 ft. mkd: ¼ S 18 CS BT.  
Note - This corner lies on fairly steep N. E. Slope approx. 225 ft.  
S. 75° W. of canyon.

131

¼ Corner to Sections 5 and 6.

Found - GLO Brass Cap mkd. in 1944.  
8", now 13" Fir, Alive, but badly injured, N. 7° E. 11.9 ft.,  
scribe visible on unhealed blaze.  
16", now 22" Fir, alive in good condition, N. 47½° W. 35.0 ft.,  
scribe visible on nearly healed blaze.  
New BT's: 8" Hemlock N. 38° E. 21.8 ft. mkd. ¼ S 5 CS BT.  
Note - Corner lies on S. E. slope, approx. 230 ft. South of spur, course N.E.

132

¼ Corner to Sections 4 and 3.

Found - No trace of GLO Brass Cap set in 1944 resurvey.  
10", now 16" Fir, N. 23° W. 85.f ft., found reverse scribe  
prev. removed from this BT., now rehealed, shows very  
good scar. Ren #4  
N.E. BT., now stump, shows extreme bottom of scar. No scribe.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T 25 S R 3 W  
Office, 1966 ¼ S 4/S 3.  
New BT's: 16" D. Fir N. 86° E. 35.2 ft. mkd: ¼ S 3 CS BT.  
16" D. Fir N. 28° W. 30.3 ft. mkd: ¼ S 4 CS BT.

133

¼ Corner to Sec. 5, T25-3 and Sec. 32, T24-3W.

Found - GLO Brass Cap mkd. in 1944 with steel fence post set alongside.  
40"?, now 31" Fir N. 40½° E. 92.4 ft., now rotten Stump  
with partial scribe marks visible on unhealed blaze.  
30" Fir S. 7° W. 13.2 ft., recorded S. 2° W., now Stump, REN. #14  
shows scribe marks on lower blaze.  
New BT's: 17" Hemlock S. 19½° W. 28.3 ft. mkd: ¼ S 5 CS BT.  
11" D. Fir N. 31° W. 32.7 ft. mkd: ¼ S 32 CS BT.  
Note - This corner lies on south side of very old, abandoned logging  
road, course N. E. - S. W.

Vernon "Ray" Tracy  
Jack Heritage

Sept., 1966  
C. S. File No. 54/27