

Douglas County Surveyor's Record of
Government Corners Renewed

T. 25 S. T. S. R. 3 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

134

1/4 Corner to Sections 6 and 7.
Found - 1944 G.L.O. Brass Cap, broken off 12" below cap.
Orig. 20", now 24" Fir, S. 81 1/2° W. 9.9 ft., scribe visible on chopped out blaze. Alive.
46", now 48" Fir, alive, S. 23 1/2° W. 30.4 ft., blaze pitched over, no scribe visible, 1966 CS BT.
22" I. Cedar N. 29 1/2° W. 45.8 ft. mkd. "1/4 S6 CSBT", alive & in good condition.
For other old BT's. see Ren. #119.
Set - Brass Cap at Cor. Mkd: County Surveyor's T 25 S R 3 W
(in place of remaining Office 1/4 S 6
pipe at point for 1/4 cor.) 1968 S 7
Note - This corner lies on moderate S.W. slope approx. 470 ft. E. of creek, course N.W. - Deposit old brass cap alongside.

Vernon "Ray" Tracy
& Crew
Feb. 5, 1968
C. S. File No. 54/27

L.E. Monrean, Doug. Co. Surveyors
P. L. Earle
Sept. 20, 1976
C.S. 59/24

SEPT. '68

135

1/4 Corner for Sec. 34 and Sec. 3, T26-3.
Found - 1943 GLO brass cap properly stamped.
4" now 17" Red Cedar, bears S. 17° W., 2.6 ft. Tree has well healed blaze. I do not open.
54" now 56" Fir stump, bears N. 15° W., 15.2 ft. Stump has a well healed blaze. I do not open.
A 5" Yew, now a 6" staub, bears S. 86° E., 14.3 ft. (Rec. S. 88° E., 14.5 ft. Has been hit by log. Stump is very loose.) Stump scribed "1/4 S3 BT".
Note: Orig. 6" Hemlock in NE quad. now gone.
6" Yew bearing N. 10° E., 25.1 ft. has been pushed over by cat logging.
Ren. #42
A 16" Red Cedar, now 18" bears S. 6° E., 31.4 ft. Tree double blazed and scribed "1/4 S3 CS BT". Ren. #42
New BT - A 15" Red Cedar, bears N. 79 1/2° E., 23.8 ft. Tree double blazed. scribed "1/4 S34 CS BT".

9/20/76

North 1/4 Corner for Sec. 12.
Set - A 3/4" x 36" I. Pipe.
BT's - 6" Fir, S. 89° W., 25.5 ft. to R.R. spike
8" Fir, S. 25° W., 37.7 ft. to R.R. spike.

10/77

136

Witness Corner for
Center 1/4 Corner for Sec. 12
Point for center 1/4 corner falls on side of rock bluff.
Set - 3/4" x 36" Iron pipe S. 87° 49 1/2" W., 7.7 ft. from point for center 1/4 corner as a witness corner.
BT's - 24" Cedar bears S. 30° W., 10.7 ft. to R.R. Spike
16" Hemlock bears N. 35° W., 17.7 ft. to R.R. spike.

10/77

137

1/4 Corner for SEctions 28 and 29.
Found - 1943 GLO brass cap on 1" I.P. protruding 0.5 ft. from ground with cap properly marked. Cap was found bent and loosely set. 138
Orig. 1883 48" D. Fir now a 50" stump, bears S. 71 1/2° E., 25.8 ft to face. (Orig. Rec. N. 65° E., 25.1 ft., 1943 GLO rec. S. 71 1/2° E., 25.1 ft.) 27.9 ft. to center of tree. We tagged with DCSO BT tag.
Orig. 60" Fir turned out and badly broken up, N. 54° W., 11.2 ft. (as per Ren. #71 and orig. rec. N. 70° W., 11.2 ft.) No scribing found We tagged tree with DCSO BT tag.
22" now 24" stump, S. 84 1/2° E., 29.7 ft. Shows scribing "1/4 S28 BT" on unhealed single blaze. Ren. #71. We tagged with DCSO BT tags.
32" Fir now 50" stump bearing S. 3 1/2° W., 41.6 ft.) Rec. S. 5° W., per Ren. #71. No scribing found but low cut, portion of lower blaze appears to remain. We tag tree.
20" D. Fir (rec. 24") bearing S. 31° W., 63.3 ft. (rec. S. 30° W.) marked "1/4 S29 CS BT" partially healed double blaze, barked and capped. We tagged with DCSO tag.
26" D. Fir bearing N. 38 1/2° W., 84.1 ft. marked "1/4 S29 CS BT" on single blazed and uprooted away from hole.
Set - Because GLO cap bent, we reference out, RESET and stamp "reset 1980" on existing cap. Cap protrudes 0.2 ft. from ground and is firmly set.
New accessories:
Set a 5/8" I.R. with alum. cap stamped "B.O." in a 44" Fir stump

138

Nick Juliano
For: Weyerhaeuser
Company.
Oct. Nov. Dec. 1977
M 68 - 32

Ed Monrean,
Deputy, Doug. Co.
Surveyors Office
T. Plouff; S. Means
S. Flaue; K. Mosely
May 7, 1980
C.S. 61/6

3-77

JAN 1978

1-79

OVER

OVER