

Douglas County Surveyor's Record of  
Government Corners Renewed

T 25      T. S.      R 3      R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

142

1/4 Corner for Sections 22 and 27

Found - A GLO 2½ inch bronze disk on a 1" diam. iron pipe, firmly set and protruding 8" from ground, properly marked, dated 1943. Monument is in a rough 2 ft. diam., mound of stone. Monument is not disturbed to look for remains of wooden stake.

Orig. BT, a cedar, 36" diam., now a fallen and decayed 36" diam. cedar bears N.42°W., 12.5 ft. (As per rec. 1943 resurvey and Ren. No. 74 - Orig. rec. N.35°W., 11.2 ft.) Evidence of rotted reblazed face found - No scribing found.

(No evidence of original hemlock found.)

1943 Resurvey, a fir 42" diam., now 54" diam. 1½ foot tall fir stump with no blazes or scribe marks found bears S.20°E., 10.6 ft. (as per record)

Ren. No. 74, a 9" hemlock now a 10" DBH 7 foot tall hemlock stump tipped out to north with a partially healed blaze with the scribing 1/4 S22 CS BT visible bears N.80°W., 32.2 ft. at the root crown.

Ren. No. 74, a 9" hemlock now a 10" diam., 3½ foot tall hemlock stump with a partially healed blaze with the scribing 1/4 S27 CS BT visible bears S.50°E., 26.2 ft. (as per record)

Set - Monument position accepted as being that which was established in the 1943 re-survey from evidence of the original wooden post.

New BTs- A 6" DBH Hemlock scribed 1/4 S22 CS BT on a double blaze bears N.13°E., 24.3 ft.

A 14" DBH Hemlock scribed 1/4 S22 CS BT on a double blaze bears N.63°W., 46.5 ft. distant.

Note - Monument is at north edge of recent clear cut and at south boundary of well established reproduction unit. Monument is approx. 500 ft. north of BLM Road No. 25-3-27.

Douglas County  
Surveyors Office  
Stephen Flause  
Randy Smith  
October 1, 1986  
C.S. 62/37

143

1/4 Corner for Sections 19 and 20

Found - A 2½" 1944 GLO brass cap on a 27" long 1" iron pipe out of ground bearing S.20°E., 22.5 ft. from a corner position determined by bearing trees. Note: GLO brass cap's stamping of section numbers is wrong. (reversed)

14" now 21" dia. 2½ ft. high rotted D. fir stump, no scribing found bears N.80°E., 31.7 ft. per 1944 D. resurvey.

30" now 30" dia. 6 ft. high D. fir stump scribing visible on a previously opened blaze "1/4 S19 BT" bears S.77°W., 16.5 ft. per 1944 D. resurvey.

42" now 36" dia. 2½ ft. high rotted D. fir stump, with scribing visible "¼" bears N.26°E., 39.0 ft. per Ren. #28

4" now 15" dia. D. fir with a fully healed double blaze bears S.68°W., 11.1 ft. per Ren. #122

4" now 14" dia. D. fir with a fully healed double blaze bears S.55½°E., 89.7 ft. (Rec. S.53½°E., 89.7 ft.) per Ren. 122

Set - A corner position was determined from bearing trees. A 2 3/8" dia. DCSO brass cap on a 1 3/8" O.D. by 32" long iron pipe is set and protrudes 7" above ground. Cap mkd. "Douglas County Surveyors T25S ¼ S19 | S20 R3W 1989 Office"  
1944 GLO BC/IP is set along North edge of new DCSO BC/IP and protrudes 3" above ground.

New BT - 11" dia. D. fir double blazed and scribed "1/4 S20 CS BT" bears N.59°E. 7.0 ft.

Corner lies in an old deteriorated, partially down northerly-southerly running barbed wire fence line.

Douglas County  
Surveyors  
Office  
R.W. Smith  
and  
S.J. Flause  
March 28, 1989  
C.S. 62/61

3/28/89