

Douglas County Surveyor's Record of
Government Corners Renewed

T 25 T. S. 5 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

75

G. Robert Lecklider
For Bernard Grubbe
September 1961
Map File M 21 - 29.

1/4 Corner to Sections 26 and 35.

Set by Proportionate Measurement.

Set: 3/4" Bolt from which bears:
22" Fir S.27°E. 80.5 ft.
10" Fir S.30°W. 62.8 ft.

RENEWED SEE CORNER NO. 78

76

1/4 Cor. to Secs. 35, T25-5W. & Sec. 2, T26-5W.

Found - Oak Stump, S.73 1/2°W. 120 lks.

B. T. destroyed by logging.

Renewed from notes I had from previous occasion.

Set - Steering Wheel Shaft.

24" P. Pine N. 07°W. 40.7 ft.

14" Fir S. 65°W. 37.4 ft.

Milo E. Godfrey
V. Tracy & C.
Putnam
Feb. 1962
C.S. 49/124

Section Corner to Sections 7 - 8 - 17 - 18

Reset - Brass Cap Set in 1960 which had been pulled out, see #137

Corner No. 65.

Set Cap 1" below ground surface.

BT's. as called for in 1960 renewal all in good condition.

18" W. Oak S. 65°W. 140.4 ft. (rescribed in 1960)

30" B. Oak N. 83°W. 81.5 ft. (Eppstein's Renewal)

14" Laurel N. 58 1/2°E. 38.5 ft. (scribed in 1960)

RENEWED

SEE CORNER NO. #137

77

Milo E. Godfrey, Deputy Co. Surv.
Michael Stone
Sept. 21, 1962
C. S. File No. 49/124

1/4 Corner to Sections 26 and 35.

Found - Both Trees mkd. by Lecklider, 1961 - See Cor. No. 75, above.

22" Fir S.27°E. 80.5 ft., scribing plainly visible. Tree in good cond.

10" Fir S.30°W. 62.8 ft., scribing plainly visible, Tree alive but badly damaged by fire.

3/4" Bolt set by Lecklider gone, in fire trail.

Set - Brass Cap at Corner Mkd: County Surveyor's T25S R5W 1/4 S26
Office, 1962 S35

New BT: 36" D. Fir N.76°E. 98.2 ft. Mkd: 1/4 S26 CS BT.

78

Witness Corner to Sections 25 - 26 - 35 - 36.

Found - 40" Fir (30" When mkd.) previously opened on S.E. face, scribing visible "T25SR5WS36" scars vis. on N.E., N.W., & S.W. faces.

Set - Brass Cap at Cor. Mkd: County Surveyor's W.C. S26 | S25 T25S R5W
Office, 1962 S35 | S36

12 ft. N. to Cor. 12 ft. South of Corner Tree.

New BT's: 16" D. Fir S.7°E. 7.3 ft. mkd: T25S R5W WC S36 CS BT.

24" D. Fir S.57°W. 19.8 ft. mkd: T25S R5W WC S35 CS BT.

8" Hemlock N.22°W. 46.6 ft. Mkd: T25S R5W WC S26 CS BT.

No trees available to N.E. Corner lies approx. 25 ft. West of steep draw sloping North & approx. 10 ft. West of N. & E. fence line, on very steep N.E. slope.

79

Milo E. Godfrey
Deputy Co/S.
Mike Stone
Aug. 1963
C. S. File No. 49/123

1/4 Section Cor. to Sec. 31, T25-5W. & Sec. 36, T25-6W.

Found - County Surveyor's Brass Cap set in 1959.

(See Corner No. 45)

10", now 12" D. Fir N.46°E. 68.6 ft. Blazes not grown over, portions of scribing visible through pitched over face.

20" Fir S.77°W. 7.9 ft. is uprooted & down.

New BT: 15" D. Fir N.13°W. 16.0 ft. Mkd: 1/4 S36 CS BT.

9/86 FD OR REC BEITZ m102 48

80

1/4 Corner to Sec. 30, T25-5W. & Sec. 25, T25-6W.

Found - County Surveyor's Brass Cap set in May, 1960 (Cor. No. 62)

Both BT's. mkd. at that time are now dead and down, as follows:

11" Fir N.24°E. 20.2 ft., uprooted, scribing all visible.

10" Fir S.58°W. 35.2 ft. is also uproot & has been sawed off below

New BT's: 9" W. Oak N.20 1/2°E. 58.1 ft. Mkd: 1/4 S30 CS BT.

6" W. Oak N.20°W. 66.0 ft. mkd: 1/4 S25 CS BT.

81

scrng.