

Douglas County Surveyor's Record of
Government Corners Renewed

25 T. S. 6 R. W. W. M.

NORTH SIDE OF SEC. 5
 $\frac{1}{4}$ Corner on South side of Section 32.
 Set S. Stone 5x5x18 inches from which: Alder 20 inch bears S 50°20'W 75 lks.
 (Gov. BTs gone. Old rock found set by Previous County Surveyor) W. Oak 20 inch bears N 65°45'E 115 lks.

$\frac{1}{4}$ Corner on West Boundary of Section 5.
 Set S. Stone from which: R. Fir 14 inch bears N 46°40'W 77 lks.
 (Old BT in evidence) R. Fir 34 inch bears N 47°30'E 39 lks.

Corner of Sections 5, 6, 7, & 8.
 Set W. Oak Post 4"x4"x3' from which: R. Fir 8" bears N 49°40'E 31 lks.
 (Old BT in evidence) W. Oak 6" bears N 23°45'W 48 lks.
 R. Fir 5" bears S 53°40'E 4 lks.
 R. Fir 3" bears S 28°30'W 25 lks.

$\frac{1}{4}$ Section Corner to Sections 5 & 8.
 Found Sand Stone set and one B.T. still standing on the S.W.

Center of Section 3.
 Set Rock for Corner and Marked:
 14" Fir S. 54°W. 37.7 ft.
 24" Fir S. 22°E. 62.8 ft.

$\frac{1}{4}$ Corner common to Sec. 36, T25S R6W. & Sec. 31, T25S R5W.
 Found - Both BT's. recorded by Kerr, 1951: REN. #47
 18", now 20" Fir S. 77°W. 7.9 ft. standing & in good condition, shows good scribing 11".
 Fir N. 26½°E. 31.5 ft., now down & down hill. May have been pushed down by Cat..
 No trace of Orig. N.E. BT., it also may have been pushed by Cat.
 Set Brass Cap at Corner Mkd: County Surveyor's Office, 1959
 $\frac{1}{4}$ R6W S36/S31 R5W T25S
 New BT.: 10" R. Fir bears N. 46°E. 68.6 ft. scribed $\frac{1}{4}$ S31 CS BT.
 Note - N.S. Fence is 15' West of Corner.

$\frac{1}{4}$ Section Corner to Sec. 25, T25-6W & Sec. 30, T25-5W.
 Found - I believe we have found both Orig. BT's., no scribing.
 Orig. 24", now 28" Oak Snag N. 12°W. 11.2 ft., shows good scars but old faces rotted.
 Orig. 18", now 22", now down, S. 55°E. 26.4 ft., record 59.4 ft. shows good scars but old faces rotted.
 Lower section of old pointed Stake at corner.
 Fence Corner thus:
 Set Brass Cap at Corner Mkd: County Surveyor's Office, 1960
 $\frac{1}{4}$ S25/S30 T25S
 R6W R5W
 New BT's: 11" Fir bears N. 24°E. 20.2 ft. scribed $\frac{1}{4}$ S30 CS BT.
 10" R. Fir bears S. 58°W. 35.2 ft. scribed $\frac{1}{4}$ S25 CS BT.

$\frac{1}{4}$ Section Corner to Sec. 1, T25-6W & Sec. 6, T25-5W.
 Found - Both Orig. BT's. Orig. 18", now 30" B.O. N. 22½°W. 29.0 ft., I open & find good scribing "S".
 Orig. 14", now 25" B.O. N. 60°E. 8.0 ft., shows gld scars.
 Fence Corner Thus:
 Set Brass Cap at Corner Mkd: County Surveyor's Office, 1960
 $\frac{1}{4}$ R6W S1/S6 R5W T25S
 New BT's: 10" B.O. bears N. 74°W. 42.8 ft. scribed $\frac{1}{4}$ S 1 CS BT.
 17" B.O. bears S. 41°E. 20.2 ft. scribed $\frac{1}{4}$ S 6 CS BT.

Volume 2
Page 265

M. B. Germond
March, 1909
Vol. 2, Pg. 157

G. G. Stewart
3/22/22
Vol. 3,
Pg. 112

James W. Byron
S. A. Bilow
April 28, 1959
C.S. File No. 49/123

James W. Byron, Deputy County Surveyor
Milo Gedfrey
Clete Putnam
May 19, 1960
C.S. File No. 49/124

James W. Byron, Deputy County Surveyor

SEE CORNER NO. 38 + 114 50

RE-RENEWED, SEE CORNER NO. 93

RE-RENEWED, SEE CORNER NO. 104

RE-RENEWED, SEE CORNER NO. 151

RE-RENEWED, SEE CORNER NO. 152

See. Fd. O.K.
8-8-63 M.E.G.