

Douglas County Surveyor's Record of
Government Corners Renewed

25 T. S. 6 R. W. W. M.

KOIKE-CHAPMAN CO., EUGENE, ORE. 21891

James W. Byron
Milo Godfrey
Cl. Putnam
Dec. 8, 1959
C.S. File
No. 52/5
M 16-59

old renewal # 26
Sec. Cor. Secs. 31 & 32, T25S R6W. & Secs. 5 & 6, T26S R6W. #185 66
Found - Stone as recorded, CS chisled on North face.
 $\frac{3}{4}$ " Iron Rod alongside Stone.
New BT's: 4" W. Oak bears S.72°E. 11.1 ft. scribed S5 CS BT.
10" B. Oak bears N. 7°E. 61.3 ft. scribed S32 T25SR6W CS BT.
10" Laurel " S.79°W. 46.6 ft. scribed S 6 T26S R6W CS BT.
6" Laurel " N.36°W. 38.8 ft. scribed S31 CS BT.

RE-RENEWED, SEE CORNER NO. 185

James W. Byron, Deputy
Milo Godfrey
Clete Putnam
March 17, 1960
C.S. File No. 49/124

Township Corner

S36	S31	T24S
R6W	S 1	S 6 R5W T25S.

Found - Remains of all 4 Original B.T.'s:
S.W. & N.E., now down, S.E. BT., now snag, outside rotted off.
N.W. BT., standing, center rotted.
All check record, no scribing found.

Set Brass Cap at Corner Mdk:

S36	S31	T24S
R6W	S 1	S 6 R5W T25S

 County Surveyor's Office, 1960
New BT's: 13" Laurel bears S.59°W. 51.6 ft. scribed S 1 T25S R6W CS BT.
6" B. Oak bears S.64°E. 18.9 ft. scribed S 6 T25S R5W CS BT.
14" Laurel bears N.19°E. 20.1 ft. scribed S31 T24S R5W CS BT.
26" W. Oak (Orig) N.69°W. 50.8 ft. scribed S36 T24S R6W CS BT.
Note - See signed statement by Harry Bainbridge in file.

Township Corner to Sections

S36	S31	T25S
S 1	S 6	T26S

Found: $1\frac{1}{2}$ " Iron Pipe at fence int. Use $1\frac{1}{2}$ " I. P. for Sec. Cor.
All Original Bearing Trees gone.
Blazed & Scribed: 10" R. Fir N.17°E. 146.0 ft. S31 T26S R5W CS BT.
16" R. Fir (Stool of) 600.0 ft. S.84°E. S6T26S R5W CS BT.
No other Trees near.

James W. Byron
For Ed Russell
April 1955
C.S. File
No. 47/12

Renew Meander Corner North Line of D. L. C. No. 38.
Found - B.B.I. 19" B. Oak, now 22", shows good scars. I do not open.
Note - Corner falls on steep bank slope. I do not find $1\frac{1}{2}$ " Pipe
Set by B. B. I.
Set - Brass Cap in Fence Line & 44.0 ft. West of Corner Mkd:
W. C. 44' East to MC - DLC 38
T25S S25 County Surveyor's Office, 1958
New BT's: Rescribe 22" B. Oak N.15°E. 13.0 ft. W.C. MC S30 S25 CS BT.

James W. Byron
Milo Godfrey
S. A. Bilow
Aug. 22, 1958
C. S. File No. 49/76

G.G. Stewart
Bartrum &
Shook, Wit.
3/27/22
C.S. Vol. 3, Page 115

$\frac{1}{4}$ Sec. Cor. btwn. Sec. 4, T25S R6W. & Sec. 33, T24S R6W.
Reestablish midway between section corners.
Set Iron Pipe for Corner and Marked: THIS COR. NOT FOUND M.E.G.
30" Fir S.26°E. 12.4 feet.
48" Fir N.17°E. 50.0 feet.

A. R. Evans
B. Matthews &
E. Jennie,
Witnesses
Nov. 1949
C.S. M16-25

$\frac{1}{4}$ Section Corner Sec. 34, T25S R6W & Sec. 3, T26S R6W.
Found: 36" Fir Line Tree called for in notes, measured called distance. Location fits Laurel Tree for direction and distance. Laurel blazed but blaze rotted out.
Set : $\frac{3}{4}$ " Iron Rod from which:
12" Fir bears S.88°E. 17.9 ft. mkd. $\frac{1}{4}$ S 3 CS BT.
No suitable tree available in Section 34.

JUNE '63
SEARCHED FOR
NOT FOUND
M.E.G.
C.S. 49/123

H.L. Eppstein,
Co. Surveyor
Sept 9, 1930
C.S. FILE 14/61

Section Corner
Township Line

S33	S34	T25S R6W
S 4	S 3	T26S R6W

Set Corner from old Oak B.T. in fair condition. Scribe marks plain.
Set: 3 x 3 x 36" Post and marked new Bearing Trees:
24" B. Oak S.64 $\frac{1}{2}$ °W. 7 $\frac{1}{2}$ feet,
20 Fir N.19°E. 22.4 ft. 20" Fir N.56 $\frac{1}{2}$ °W. 25 ft.
14" Fir S.12°E. 9.0 ft.

RE-RENEWED, SEE CORNER NO. 134