

Douglas County Surveyor's Record of
Government Corners Renewed

T. 25 S. T. S. R. 6 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Milo E. Godfrey, Deputy County Surveyor
Vernon Tracy
Mike Stone
November 1962
C. S. File No. 49/123

$\frac{1}{4}$ Corner to Sections 5 and 4. 109
Found - $1\frac{1}{4}$ " I. Rod set by Boyer, 1942. REN. #39
B. Oak, now 26", S. 27° E. 131.5 ft., shows good scar. Tree alive.
24" W. Oak N. 88° E., not N. $85\frac{1}{2}^{\circ}$ E.) 145.0 ft. dead & broken off. BT. visible.
Rotten Fragment of Oak Stump N. 38° W. 17.8 ft. (Orig. BT.) No marks fd.
Depression in ground, possible stump hole, S. 82° E. 35.6 ft.
New BT's: 10" W. Oak N. 86° E. 164.0 ft. Mkd: " $\frac{1}{4}$ S 4 CS BT".
7" W. Oak S. 19° W. 37.0 ft. Mkd: " $\frac{1}{4}$ S 5 CS BT".
Corner is in fence corner. Fences North, South, East and West.

$\frac{1}{4}$ Corner to Secs. 4 and 9. 110
Found - Old Oak, down & pushed out of position, S. 40° E. 14.5 ft., good reverse scribing found. " $\frac{1}{4}$ SBT" Diam. when mkd. approx. 16", the main body of this tree has been pushed out of position where it fell, but a portion of the top appears to be in position. From location of top & length of main trunk, found depression in ground which I believe to be the stump hole.
No trace of 8" Oak North of corner.
Set - Brass Cap at Cor. Mkd: County Surveyor's T25S R6W $\frac{1}{4}$ S 4
(From Stump Hole) Office, 1962 S 9
New BT's: 10" D. Fir N. 40° E. 83.1 ft. Mkd: $\frac{1}{4}$ S4 CS BT.
20" Madrone S. 14° E. 45.2 ft. Mkd: $\frac{1}{4}$ S9 CS BT.
A brick chimney on a white house visible from corner bears N. 71° W. approximately $\frac{1}{2}$ mile distance.

Section Corner to Sections 5 - 4 - 8 - 9. 111
Found - Brass Cap set by Co. Surv. in 1958. REN. #62
14" W. Oak S. 46° E. 58.3 ft., scribing visible, tree alive.
24" W. Oak S. 32° W. 52.0 ft., scribing visible, tree standing but dead.
10" W. Oak N. 49° W. 17.9 ft., scribing visible, tree standing but dead.
7" Fir N. 10° E. 55.4 ft., scribing visible, dead and down.
New BT's: 8" W. Oak S. $25\frac{1}{2}^{\circ}$ W. 74.5 ft. Mkd: T25S R6W S8 CS BT.
6" D. Fir N. 80° W. 71.9 ft. Mkd: S5 CS BT.
7" Madrone N. 23° E. 73.5 ft. Mkd: T25S R6W S4 CS BT.

Center of Section 5. 112
Found - $\frac{1}{2}$ " Iron Pipe set by Boyer, 1942. REN. #40
Rotten & burned fir stump S. 8° E. 72.2 ft., charred old face visible.
Rotten & burned Fir Stump N. $37\frac{1}{2}^{\circ}$ E. 63.0 ft. No markings found.
Set - Brass Cap alongside Pipe Mkd: County Surveyor's Office, 1962
T25S R6W Center $\frac{1}{4}$ S 5.
New BT: 17" D. Fir N. 40° W. 188.2 ft. Mkd: C $\frac{1}{4}$ S5 OS BT.
No other trees near.
Fence corner, fences East & North, bears East 1 foot.

Sec. Cor. to Secs. 5 & 6, T25-6W. & Secs. 31 & 32, T24-6W. 113
Found - Scribed Cedar Stake. & 19" Fir Snag N. 75° E. 28.0 ft., good bark scribing, plainly visible, "T24S R6W S32 CS BT". -REN. #43
18" Fir S. 37° E. 68.0 ft., shows 2 very plain axe scars, trees nearly dead.
21" Fir S. 6° W. (not S. 4° W.) 64.6 ft., to face, shows 2 very plain axe scars, tree alive & in good condition.
Fir Stump N. 1° W. 60.0 ft., shows good axe scar.
Set - Brass Cap at Cor. Mkd: County Surveyor's

S31	S32	T24S
S 6	S 5	T25S R6W

 Office, 1962
Drive Scribed Cedar Stake Alongside.
New BT's: 21" D. Fir S. 77° E. 53.4 ft. Mkd: T25S R6W S5 CS BT.
31" D. Fir N. 66° W. 53.8 ft. Mkd: T24S R6W S31 CS BT.
7" D. Fir N. 20° E. 117.3 ft. Mkd: T24S R6W S32 CS BT.
Fence Corner, fences North, South & East, bears N. 60° W. 23 feet.