

Douglas County Surveyor's Record of
Government Corners Renewed

T. 25 S. T. S. R. 6. W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Milo E. Godfrey, Deputy
Vern. Tracy & Mike Stone
August 1963
C. S. File No. 49/123

$\frac{1}{4}$ Corner to Section 25, T25-6W. & Sec. 30, T25-5W. 152
Found - County Surveyor's Brass Cap set in May 1960. (See Cor. No. 50D)
Both BT's. mkd. at that time are now dead & down, as follows:
11" Fir N.24°E. 20.2 ft., uprooted, scribing all visible.
10" Fir S.58°W. 35.2 ft. is also uproot & has been sawed off below scribing.
New BT's: 9" W.Oak N.20 $\frac{1}{2}$ °E. 58.1 ft. Mkd: $\frac{1}{4}$ S30 CS BT.
6" W.Oak N.20°W. 66.1 ft. Mkd: $\frac{1}{4}$ S25 CS BT.

Township Corner T24S R6W S 36 / S 31 S 1 / S 6 R5W 153

Found - Brass Cap, out of ground, leaning against corner post of fence.
All 4 BT's. mkd. in 1960 are alive & standing, vis: REN.#67
13" Laurel S.59°W. 51.6 ft., scribing visible.
14" Laurel N.19°E. 20.4 ft., scribing visible.
26" W.Oak (Orig. BT.) N.69°W. 50.8 ft., renewal scribing visible.
6" Bl.Oak S.64°E. 18.9 ft., scribing visible, tree standing & alive, but top broken out.
Reset - Brass Cap at Corner - Top flush with surface of ground.
New BT: 19" D.Fir S.11°E. 49.2 ft. Mkd: T25S R5W S6 CS BT.

Milo E. Godfrey
V. Tracy
Aug. 8, 1963
C. S. File No. 49/123

$\frac{1}{4}$ Section Corner to Sections 27 and 26. 154
Found - Old, rotten Oak Snag S.3 $\frac{1}{2}$ °W. 675.8 ft. Has been chopped open previously & upper face completely rotted away. Cut open & found reverse scribing "BT".
2 small Maple Trees in immediate vicinity of location for S.E. Bearing Tree (12" Maple S.72 $\frac{1}{4}$ °E. 515 lks.), No stump hole nor any portion of Original tree remains.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963
T25S R6W $\frac{1}{4}$ S27/S26
New BT: 18" White Oak S.45°E. 227.9 ft. Mkd: $\frac{1}{4}$ S26 CSBT.
Note - The power pole at the intersection of Hardin-Davis Hill Road and D.L.C. Line road bears S.54°W. 161.8 ft. No other trees near.
1-26-71 - FOUND O.K. V.R.T. - C.S. 49/123

Milo E. Godfrey, Deputy Co. Surveyor
Wm. Stoffel - M. Stone - M. Darby
April 1964
C. S. File No. 49/123

Mst. Northerly N.W. Corner D.L.C. No. 48. 155
Interior "L" Corner D.L.C. No. 47.
Found - $\frac{3}{4}$ " Iron Pipe at Corner, Ren. No. 30. + #52 *FD. 7/83 R. Dolan M 9/4-50*
46" White Oak S.60°W. 44.0 ft., small portion of scribe mark visible in not completely covered blaze.
New BT: 18" White Oak N.74°W. 71.1 ft. Mkd: "Int. "L" DLC 47 CS BT".
Note - Corner is in E. & W. Fence Line 5 ft. east of fence corner, fences east, west and south.

S. W. Corner D. L. C. No. 54. 156
Found - Iron Bar set by Frear in 1919, Ren. No. 5. *FD. Dec. 1982 by Dolan M 5/8/219*
Stump of 12" White Oak N.47°E. 9.2 ft., shows scar.
Stump of 14" White Oak S.37°E. 23.8 ft., reverse scribing visible on overgrowth of old face, through hole in top of stump.
New BT's: 22" White Oak S.15 $\frac{1}{2}$ °E. 80.4 ft. Mkd: "SW DLC 54 CS BT.
16" White Oak S. 4 $\frac{1}{2}$ °E. 95.0 ft. Mkd: SW DLC 54 CS BT.
Note - Corner is in N. & S. fence line approx. 200 ft. N. of county road.

N. E. Corner D. L. C. No. 40. 157
Found - Steel Axle 1 1/8" diam., See Ren. No. 22.
16" W. Oak S.55°E. 62.0 ft., shows very plain scar.
14" Bl.Oak N.84°W. 5.9 ft., scar open & center rotted away.
New BT: 9" Madrone N.58°E. 20.8 ft. Mkd: N.E. DLC 40 CS BT.

S. W. Corner J. H. Medley D.L.C. No. 46. 158
Found - $\frac{3}{4}$ " Iron Pipe (now bent over) set by B.B. Irving, See Ren. #37.
14" White Oak N.8°E. 94.0 ft., shows very plain scar.
New BT: 24" Bl. Oak N.27°E. 130.0 ft. Mkd: SW DLC 46 CS BT.
Note - Corner is 9.5 ft. East of N. & S. Fenc Line.