

Douglas County Surveyor's Record of  
Government Corners Renewed

T 25 S T. S. R 7 W R. W. W. M.

Jan 19 1944  
A Boyer Dep  
Hap. Oliver Jr  
Dude Powell

Cor 14, 15, 22, 23- Reset from one O.B.T. W.Oak N55°W 62.2  
New Trees 15" W.O N 21 1/2° W 58 Links -  
18" Ced. S 65 1/2° W 34 1/2  
24" Laurel S 66° E 2-2  
Set Post at Cor  
**SEE CORNER NO. 57**

B.B.Irving  
1-15-45  
C.S. File  
38-5

Meander CORNER BETWEEN SECTIONS 25 & 30 T. 25 S., R. 6 & 8 W.  
Set 1 1/2" x 42" Iron Pipe.  
Marked a 19" B.Oak N.73° W. 41.7 ft. M.C.S. 25 C.L. No 38  
C.S.B.T.  
**SEE CORNER NO. 54**

F.C. FREAR  
Dep. Co. Sur.  
Wit. J.I. Chapman  
J.B. Lorge  
Aug. 18, 1919

NORTHWEST CORNER WILLOUGHBY CHURCHILL D.L.C. NO 38.  
Drove Auto Axle in old skein. Set 21.0 ft. from fence  
corner in County Road. 3" Underground.  
**RE-RENEWED SEE CORNER NO. 89**

J.W. Cole Deputy  
Wit. L.H. Smick  
Creed Conn  
Jan, 1921  
Jed in C.S. File 2/11  
No Notes on Field Work.

COR. BETWEEN SECS. 24 and 25. Renewed as per old B.T.s by  
setting a 3"x36" Fir Stake from which  
A 40" B. Oak bears N. 82 1/2° W., 1.17 ch.  
A 12" W. Oak bears S. 3 1/2° W., 1.40 chs.  
**SEE CORNER NO. #18**

G.G. Stewart Dep.  
Wit. J.S. Germond  
H.F. Roeder  
N.E. Richardson  
Nov. 14, 1921

COR. BET. SECS. 26 and 27.  
Renewed corner from original B.T. N. 0° 15' E., 625.7 ft.  
no trace of other B.T. Set 1" x 1 1/2" Iron bar marked new tree  
An Oak 14" S. 89° W., 683 ft. (Boyer Apple 20' S 11° W 395.5')  
1944  
See File 37/35 221 10-11-5

Geo. E. Streese  
Wit. H.F. Roeder  
Herman Itreesen  
Frank Garnel  
Otto Moore  
Nov. 14, 1921

COR. TO SECS. 22-23-26-27.  
Renewed Cor. from original B.T. N. 30° W. G. 160.4 ft.  
Mark new tree  
A B. Oak 24" dia. N. 39° 15' E., 221.3 ft.  
**SEE CORNER NO. 87**

Ed Mosher  
K. Emmett  
C.S. Vol. 3, P. 175

MEANDER COR. S. SOUTH UMPQUA RIVER ON LINE BET. 22-23.  
Set an Oak Post 4"x 4" x 40" also Iron Bar 1/2"x 1 1/2"x 36"  
Mark new trees  
A Maple 36" dia. S. 43° W., 7 ft.  
A B. Oak 15" dia. S. 78° E., 192 ft. Jan. 1968 - REACHED FOR - NOT FOUND  
C.S. 54/10 V.R.T.

COR. TO 29-30-31-32.  
Put Iron Pipe for Cor. Cor. was pile rocks placed by  
J. S. Germond around original stake which had burned off.  
Marked new trees.  
30" Fir N. 34° E., 59.5 ft.  
12" Alder S. 25° 30' W., 42.0 ft.  
10" Maple S. 50° W., 5.7 ft.  
10" Maple N. 38° W., 9.1 ft.  
Original trees destroyed by fire.  
**SEE CORNER NO. 40**

COR. BET. 29 and 30.  
Decayed stake and one B.T. found. Put 1" Round Eye Bar for  
corner. New B.T. Marked  
24" Fir S. 43° W., 35 links. R. DOLAN  
18" Fir (original) N. 45° E., 57 links. FD OK 12190 M 111-28

COR. BET. 29 and 32. Corrected 10-26-50  
Found 6" Laurel, ant eaten and dying. Had been scribed.  
Other B.T. gone. Found 6" Fir, had been blazed for corner  
but no scribe marks. Marked Fir 1/4 Sec. Cor. Marked 99 B.T.  
10" Fir S. 7° E., 35.2 ft.  
24" Fir N. 86° E., 17 ft.

COR. BET. SECS. 8-9.  
Renewed corner from original bearing trees which are standing  
but nearly dead. I set a 1 1/2" x 24 inch pipe and a 4 x 4 x 30  
inch Cedar post from which old B.T.s  
30" Oak S. 10° E., 191.4 ft.  
15" Oak scarred bears S. 1° 30' W., 834 ft.  
Marked new trees  
W. Oak 12" N. 47° 00' E., 119.5 ft.  
W. Oak 16" S. 64° 15' W., 81.8 ft.  
**RE-RENEWED SEE CORNER NO. 63**