

Douglas County Surveyor's Record of
Government Corners Renewed

25 T. S. 7 R. W. W. M.

Ben B. Irving D.C.S.
Dec. 12, 1932
Witness
N.E. Richardson
R.L. Irving

A. Boyer D.C.S. C.C. Boyer
April 25, 1936 May 2, 1913
Witness Henry Teller
George Gurney.

Bert W. Udell
H. E. Taylor -Witness
Sept. 3-4, 1948
Dec. 15, 1948
Percy Armstrong
Sept. 17, 1949

C.S. FILE 37/82
C.S. FILE 20/39
C.S. FILE 23/25 No. Ref. Found
C.S. FILE 30/39
C.S. FILE 40/114
C.S. FILE 40/227

1/4 COR. BETWEEN SECS. 24 and 25.
Renewed from B.T.'s as recorded (See P. 57) Drove an Iron
Pin 1" dia. for corner. **RE-RENEWED, SEE CORNER NO. 37, 79**
O.B.T. 12" white Oak S. 8° 24' W., 1.40 chs.
O.B.T. 40" Black Oak N. 81° 52' W., 1.17 chs. I reblazed
and scribed this tree 1/4 S. C.S. B.T. **REN #3**

18

MEANDER CORNER RIGHT BANK OF UMPQUA RIVER BETWEEN SECS. 24 & 25.
From measurement from 1/4 Sec. corner and O.B.T. as originally
recorded in gov't. field notes. Drove a 1 x 48" Iron Pipe
and remarked the O.B.T. 40" Black Oak N. 26° E., 16 lks.
Note:--This tree is the same as is used as a B.T. for the
1/4 Sec. Corner. **FD. TREE O.K.
PIPE WASHED OUT.
AUG. 5, 1963 M. G.**

19

N.E. COR. D.L.C. 47
Begin at N.E. cor. cl. 47 which is a rock that I identify as
correct from B.T.
A Black Oak 12" dia. bearing S. 84° W., 140 lks. **80**

20

S.E. COR. D.L.C. 48 - SEARCHED FOR, NOT FOUND - 4-15-66
Old trees destroyed. Marked new trees **e.l. 54/10**
A White Oak 6" dia. N. 85° W., 26.85 ft. marked
C. 48 T. 25 S. R. 7 W. B.T. **M. G. 50.**

21

COR. BET. SECS. 20 and 29.
Renewed from dead fir stump to the S.E. and from fir stump
to the N.W. which is not dead but scribe marks, which were
undoubtedly originally made on the bark, were gone-- this
stump is cut high. Drove 1 x 20" round Steel Bar for
cor, which is in fence Cor. on S. side post, from which
An 8" Black Oak bears N. 42° E., 28.1 ft.
A 13" White Oak bears S. 26° W., 42.0 ft.

22

MOST WESTERLY N.W. COR. D.L.C. 49 (Mary Pierce)
Found original S.S. Rock 6 x 12 x 18" (approx.) firmly set
in ground, drove 1" pipe beside S. side of rock from
which
A Round Oak Roller 30" long with rd. 1/2" steel rod
in center bears S. 50 1/2° W. (No trees available). **#121**

23

1/4 COR. ON N. LINE OF Sec. 4.
Found "1/4 S" scribed on remains of 12" Fir. This tree is rotten and
broken. 30" Fir at S 67 E is in good shape. Scars show plainly. **#82**
I set stake at corner and marked new trees.
34" Fir at N 52° E 30.5 ft. from corner. Mkd. "CS BT"
"CS 1/4"

24

N E COR. SEC. 4.
All trees standing and in good condition. Stake at corner. **#106**
Fir 14" S 66° E 19 lks.
Cedar 18" S 65° W 19 lks.
Fir 14" N 43° E 22 lks. **SEE FILE 40-1-7 4 1958 GLO
BRASS CAP
Vol. 29 76 12/02**

25

1/4 COR. BETWEEN SECS. 4-5
O. B. T.'s.
24" Fir, N 2° W 36 lks. - Tree standing
1/4 S marked on bark, scar does not show. **92**
18" Fir S 2° E 16 lks. - Tree blown down, chopped out B T.
Marked new a 30" Fir, S 41° W 18.5 ft., Set post at corner

26

MEANDER CORNER & EAST BANK OF RIVER- BETWEEN SECS. 16-21
Find a rotted Oak stump with I believe to be witness tree. From
this evidence I drive a 3/4" x 54" rod at the point believed to be
the original location of corner. Marked following B. T.'s.
18" Oak S 41° E 9.5 ft.;
8" Oak East 108.1 ft.
See File 40/227 for method used in resetting before using corner.

27