

Douglas County Surveyor's Record of  
Government Corners Renewed

25 T. S. 7 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97196

37

1/4 sec. cor. bet. secs. 24 and 25  
Set a fir post, from which a bl. oak 36" diam. bears N 82 1/2°  
W. 117 lks. distant  
A white oak 8" diam bears S. 31° W 140 lks distant.  
March 9, 1900. Present. Fred Whitbeck, Frank Smith. Only one  
old tree corresponding to description could be found, the old  
marks appear to have been cut away, I go to the S E cor. of  
section 24 and run W. and at 40.20 chains strike the point,  
given by the supposed B. T. it also agrees with the distance to  
meander corner.

RE-RENEWED CORNER NO. 18 #3

1/4 COR. BET. 16-21

Set sandstone 18 x 8 x 4 inches  
See Bk 2 page 81.3 Reset Dec. 18, 1899

37-A

RE-RENEWED CORNER NO. #139

Vol. 2 p. 83

38

The following quarter section corner between secs. 30 and 31,  
T 25 S; R. 7 W; W.M. on the south side of Hubbard Creek was  
renewed from the following.

On May 6, 7 & 11th of this year, a line was run from known  
corners for the full length of the north side of sec. 31, 25/7.,  
and it was found that this line is 5334.0 ft long and bears S. 87° 03' W  
from sec. corner to sec. corner. The work was done for Mr. Sullivan.  
The terrain is very rough and brushy but the work was well done.  
AT a point 70 ft. W. of the point midwaybet. the two section corners  
there was a brace post set in a fence line which was the proper  
distance and bearing from a badly rotted stump of a fir tree which  
had been broken off about six feet above the ground surf. This  
stump showed signs of having been blazed on its south east side  
and fit the witness tree given in the orig. govt notes as being  
N. 40° E. 25 lks from this cor. although it was blazed on the S. E.  
face of the tree which would have made it N. 70° E. After looking  
around for the party who set the fence and the brace post, Charles  
Germond was found and he stated that he set this post with instructions  
from his brother Milton Germond who found this stump referred to above  
and found scribe marks on the bark of this tree. I should add that  
this brace post is 70. ft. W. and 35 ft. N. of the midway point bet.  
the two sec. cors. Attached is a statement from Mr. Charles or C. H.  
Germond that he set this brace post as given above.

From the information given I marked two trees for this cor. after  
driving a 3/4 inch iron pipe at the brace post. The trees are both  
in sec. 31. The trees are close in sec. 30. A 6" chink. S. 34° W. 18 ft.  
marked 1/4 S. 31 1581 B. T. 25/7.  
A 8" chink. S. 89° E. 12 ft. marked 1/4 S. 31 1581 B. T. 25/7

I also found the old stump of the tree in sec. 30 in the position  
as given in the orig. notes.

This cor. is abt. 300 ft. over the top of the ridge coming in from  
the W. it is on the north face of the hill on abt. a 15° slope.

RE-RENEWED CORNER NO. #119

Arthur Boyer - - June 1, 1953 Ted Schattenkirk (witness)-Renewal of  
quarter corner between secs. 30 and 31, T 25 S, R 7 W., W. M. on the  
south side of Hubbard Creek.

Filed in Vol. 41, Env. 162.

39

1/4 corner secs. 16 and 17.  
Found 1 O. B. T. - 24" Fir, N. 38° W., 46 lks.  
Set 4" x 4" Fir Stake.

SEE ALSO COR. # 3397

A. R. Evans  
June 1954.  
Done for E.  
L. Branton,  
File 41/313.

40

Renew Section Corner to Sections 29, 30, 31, & 32.  
Found- 1 inch iron pipe 6 inch under at corner & 4 BTs. as renewed by  
Stewart, 1921: The 10 inch Maple S. 50° W., and the 10 inch Maple now  
18 inch, N. 38° W. show good healed blazes. I do not open. The 12 inch  
now 18 inch Alder S. 25 1/2° E. shows good but partly rotted scribing.  
The N.E. BT now 36 inch rotted stump. 30/29 T. 25 S, R. 7 W.  
Set Brass Cap alongside 1 inch iron pipe marked 31/32 County Surv. Off., 1957  
New Bearing Trees: 14 inch R. Fir S. 53° E 30.1 ft. scribed T25S, R7W. S. 32. CS. BT.  
16 inch R. Fir N. 28° E 66.8 ft. scribed T25S, R7W. S. 29. CS. BT.

James W. Byron  
M. Godfrey  
Sept. 10, 1957  
C.S. File No. 49/10

FD-1/24/79  
K. Reed - Co. Surveyor's Office  
c.s. 60/24