

Douglas County Surveyor's Record of
Government Corners Renewed

T 25 S. T. S. R 7 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21891

Interior "L" Corner D.L.C. No. 49.

60

Found - Rotted portions of Oak roller with $\frac{1}{2}$ " iron rod in each end as set by Boyer in 1937. *SEE C.S. 30/39 REN. #17*

Rock 9" x 11" x 12" above ground, set alongside.

White Oak, now 30", S.87 $\frac{1}{2}$ °E. 56.8 ft., shows good axe scar. Tree in good condition.

White Oak, now 22", S.44°W. 39.5 ft. Scar has been opened previously, good scribing "Cl 9", visible in opening, old face rotting. Reblaze & scribe this tree.

At point where lower end of roller set in ground Set Iron Pipe with Brass Cap Mkd: County Surveyor's Office, 1961 T25S R7W Int. L. D.L.C. 49.

Milo Godfrey
V. Tracy & Cl Putnam
October 19, 1961
C.S. File No. 49/76

Witness Corner to $\frac{1}{4}$ Corner to Sections 7 and 8.

61

Found - Rock Mound set by Cole in 1923. *REN. #11*

Myrtle, now 24", S.69°W., not N.69°W. 13.2 ft., chopped open & found good scribing "WC CS".

Clump of Small Myrtles bears S.75 $\frac{1}{2}$ °E. 23.3 ft., stooled out from larger myrtle which once stood there.

Note - The stumps of both Orig. Fir BT's. to the $\frac{1}{4}$ Cor. are still in existence, although badly rotted.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1961

W. C. $\frac{1}{4}$ S7/S8 49.3 ft. S. to $\frac{1}{4}$ Cor.

New BT's: 14" D.Fir N.69°W. 16.2 ft. Mkd: W.C $\frac{1}{4}$ S7 CS BT.

9" Myrtle N.87 $\frac{1}{2}$ °E. 45.7 ft. Mkd: W.C $\frac{1}{4}$ S8 CS BT.

Section Corner to Sections 5 - 6 - 7 - 8.

62

Found - Badly rotted Fir Stump N.55°E., good reverse scribing, dist. 42.9 ft.

Fir, now 36", N.5°W. 247.5 ft., uprooted & down. Do not open.

No other Bearing Trees found.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1961

T25S R7W $\frac{S6}{S7} \frac{S5}{S8}$

New BT's: 16" Laurel N.81°E. 18.0 ft. Mkd: T25SR7W S5 CS BT.

38" D.Fir N.48°W. 19.0 ft. Mkd: T25SR7W S6 CS BT.

7" D.Fir S.32 $\frac{1}{2}$ °E. 24.0 ft. Mkd: T25SR7W S8 CSBT.

8" D.Fir S.22 $\frac{1}{2}$ °W. 49.7 ft. Mkd: T25SR7W S7 CS BT.

Corner falls in fence corner. Remains of old fences run South & West from corner.

Milo E. Godfrey, Deputy County Surveyor
Vernon Tracy and Clete Putnam
December 1961
C. S. File No. 49/76

$\frac{1}{4}$ Section Corner to Sections 8 and 9. *(REN. #10)*

63

Found - $1\frac{1}{2}$ " Iron Pipe set by Streese. W. Oak, now 20", N.47°E. 110.1 ft.,

(instead of 119.5 ft) has been previously opened, scribing visible " $\frac{1}{4}$ S BT". This tree is now hollow, condition poor.

Probably scribing will not be visible many more years.

W. Oak, now 26", S.64 $\frac{1}{4}$ °W. 81.8 ft. Axe scars faintly visible.

Tree is in good condition, Did not open.

New BT's: 12" D.Fir S.36°E. 13.5 ft. Mkd: " $\frac{1}{4}$ S9 CS BT."

12" D.Fir N.82°W. 19.7 ft. Mkd: " $\frac{1}{4}$ S8 CS BT."

FD PIPE &
S6 BT.
3/65
M98-42
R. DOLAN

$\frac{1}{4}$ Corner to Sec. 7, R7W. & Sec. 12, R8W.

64

Found - Old W. Oak, now 48", N.8 $\frac{1}{2}$ °W, (instead of 6 $\frac{1}{2}$ °) 534.6 ft.

(Orig. tree rescribed by Kerr, 1954, still in good condition) *REN. #35*

Old Oak Stump, now 24", S.33°E., not 31°, 243.3 ft. Cut open & find good reverse scribing "BT".

~~24" W.Oak Mkd. by Kerr, bears S.69°E. 232.5 ft. Portions of scribing still visible in nearly closed scars.~~ *3/12/63 DESTROYED BY ROAD CONST.*

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1961

T25S R8W $\frac{1}{4}$ S12/S7 R7W

Iron Pipe set by Kerr for corner bears S.80°W. 7.8 ft.

3/12/63 NEW BT: 20" W.OAK N.87°E. 255.9 ft. MKD. " $\frac{1}{4}$ S7 C.S. BT."

RENEWED, SEE CORNER NO. 71