

Douglas County Surveyor's Record of
Government Corners Renewed

T. 25 S. T. S. R. 7 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Witness Corner to Section 7, T25-7W. & Sec. 12, T25-8W. 69
Found - Stake set by Kerr, 1954, fallen over & downhill from corner.
18" R.Cedar N.55°W. 19.0 ft. Kerr's scribing still visible
in partly healed over scars. REN.#36
50" Fir S.80°E. 6.6 ft. Old axe blazes visible in bark, faint
traces of possible scribing visible in scars.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1962
T25S R8W W.C. S12/S 7 R7W.
New BT: 6" Myrtle S.50°E. 16.0 ft. Mkd: T25S R7W W.C. S7 CS BT.
Corner lies on precipitous North slope, approx. 300 ft. South of River.

Milo E. Godfrey, Deputy
Mike Stone, Chairman
October 24, 1962
C.S. File No. 49/76

70

1/4 Corner to Sections 22 and 27.
Found - Rotten Fir Stump, broken off too low to find scars or scrbing.
36" Fir Snag N.45°W. 7.9 ft., shows good scar, impossible
to open, log lies almost against face, still alive but
broken off.
Fir Tree S.50°W. 24.8 ft., uprooted & down, not recent, has
slid about 20 ft. downhill, bark scrbing. vis. on under side.
Set - Wit. Cor: 5 ft. East of 1/4 Cor. Brass Cap Mkd: WC 1/4 S22 5' W. to Cor.
County Surveyor's Office S27 T25S R7W
New BT's: 32" D.Fir N.21°W. 20.3 ft. Mkd: WC 1/4 S22 CS BT.
6" W.Fir S.12°E. 27.6 ft. Mkd: WC 1/4 S27 CS BT.
Corner lies on precipitous North slope, approx. 300 ft. South of River.
Dec. 26, 1962

71

1/4 Corner to Sec. 12, T25-8W. and Sec. 7, T25-7W.
The S. E. Bearing Tree has been destroyed by Road
Brass Cap & N.W. BT. in good condition. Construction.
Mark one Bearing Tree to replace tree destroyed: (See Ren.#64)
20" White Oak N.87°E. 255.9 ft. Mkd: 1/4 S 7 CS BT.

Godfrey &
Crew
March 1963
C. S. File
No. 49/76

72

1/4 Cor. to Sec. 12, T25-7W. & Sec. 7, T25-6W.
Found - 50" Fir Stump N.55°W.; 62.0 ft., old & badly charred & rotten.
Two old axe faces on bark, scribe mark upper half of "S".
Cedar, down 7 half-burned away, N.83°E. 46.2 ft. No.mks.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963
T25S 1/4 R7W S12/S 7 R6W
New BT's: 15" D.Fir N.55°E. 24.8 ft. Mkd: 1/4 S7 CS BT.
10" D.Fir N. 2°W. 19.2 ft. Mkd: 1/4 S12 CS BT.
Corner lies on very steep & rocky north slope, approx. 50 ft.
south of small draw sloping east, at foot of slope.
27" I.Cedar with Grant & Evans' yellow tag bears N.70°E. 100.6 ft.
(formerly used as NE. BT.)

Milo E. Godfrey, Deputy County Surveyor
Vernon Tracy and Mike Stone
July 1963
C. S. File No. 49/123

73

West 1/4 Corner to Section 6 only, T25-6W. (E.line Sec. 1, T25-7W.)
Found - 32" Fir S.57°W.(not S.67°W.) 71.9 ft. Has been prev. open.
scribing visible on old face. Tree alive & in good cond.
36" Rotten Fir Snag S.38°E. 42.2 ft. Scribe mks. vis. on
portions of old faces. Part of "S" & part of "W".
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963
T25S R7W W1/2 S6 R6W
New BT's: 5" D.Fir S.27°E. 21.3 ft. Mkd: 1/4 S 6 CS BT.
5" D.Fir N.75°E. 12.1 ft. Mkd: 1/4 S 6 CS BT.

RE-RENEWED CORNER NO. #138

74

Sec. Cor. to Sec. 1 & 12, T25-7W. & Sec. 7 & 6, T25-6W.
Found - 38" Fir S.2°W. 11.9 ft., faint bark scrbing. vis. Axe mks. vis. at
location for BT.
36" Fir S.2°E. 17.2 ft., old axe mks. vis. on bark(2 scars) No scbg.
24" Fir N.40°W. 3.3 ft., illegible scribe marks visible on bark.
24" Fir N.60°E. 3.3 ft., good axe scar visible. Did not open.
(Distances are all from face of tree.)
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963
T25S R7W S1/S 6 R6W
S12/S 7

RE-RENEWED CORNER NO. #137

(continued next page)