

Douglas County Surveyor's Record of  
Government Corners Renewed

T 25 T. S. R 7 R. W. W. M.

142

KOKE-CHAPMAN CO., EUGENE, ORE. 91891

Cont. from prev. pg. ---

Douglas County  
Surveyors Office  
Larry E. Monrean  
Randall Smith  
April 6, 1990  
C.S. 64/6

12" now 22" dia. W. oak with a fully healed double blaze bears S.3 3/4°W., 93.1 ft. (Rec. S.3 3/4°W., 92.4 ft. dist. is a face measurement) Ren. No. 3  
13" W. oak bearing N.k8 1/2°W., 125.1 ft. from Ren. No. 79 is gone.  
Set - Plumb position of DCSO BC/IP is referenced, BC/IP is removed and straightened (measures 36" long). The stamping "RESET 1990" is added to brass cap. BC/IP is set flush with ground at referenced position. 1" I. Bar is set along south side 4" below ground. A 6" dia. concrete collar which is filled with concrete is set around BC/IP and I. bar collar is flush with ground.

New Accessories:

2" dia. brass cap stamped "BM D6 LS 1076 1983" set in concrete, bears N.30 1/2°E., 183.7 ft.  
SW corner of house is a brick column which bears N.12°W, 74.3  
4/6/90

WITNESS CORNER TO

Section Corner for Sections 6 and 5 ; and 31 and 32 of T.24-7

143

CONDITION REPORT ONLY

Found - A 2 1/2" dia. brass cap on a 1 1/4" O.D. iron pipe is firmly set and protrudes approx. 10" from a rough low mound of stone. Ren. #93  
All accessories found as noted in Ren. #128 EXCEPT 11" Willow BT which is now dead.

Monument is at bottom of fill slope on West side of County Rd. #33 and is approx. 650 ft. North from the Tyee Access Bridge (USFS Rd. #25-7-5.1)

7/30/90

Douglas County  
Surveyors Office  
Stephen Flause  
Terrie Franssen  
July 30, 1990  
C.S. 64/10

Section Corner for Sections 21, 22, 27 & 28

144

Found - A 1968 D.C.S.O. 2 1/2" dia. brass cap properly marked on a 1 3/8" O.D. I.P. firmly set & protruding 10" above ground. Ren. # 88  
B.T.s - 19" fir (dbh) 40' tall rotted fir snag with scribe marks "T25SR7WS28CSBT" visible on open upper and lower blazes. S.46°W., 15.2 ft. (as per record) original BT.  
15" fir, now a shattered, fallen and rotted stump with no visible scribe marks, bears S.20 1/2°E., 21.8 ft. (record S.22°E., 21.8 ft.) original BT.  
20" fir now a 37" fir (dbh) with a healed lower blaze and the bark scribing "T25SR7WS21" visible above, bears N.52°W., 21.0 ft. (record N.52°W., 19.8 ft) Appears to be a face meas. Orig. BT.  
12" fir now a 19" (dbh) with a fully healed double blaze bears N.20°E., 16.5 ft. (record N.20°E., 23.1 ft.) Orig. BT.  
11" D. fir now an 11" (dbh) 10' tall snag, with healed single blaze. Bears S.21°W., 24.8 ft. (as per record) Ren. # 88

New BT's-21" (dbh) cedar with 2 square blaze scars (tree is tagged but otherwise unrecorded) bears N.81 1/2°E., 17.5 ft.

4" (dbh) D. fir, double blazed and scribed "X" BT" bears S.58° E., 19.3 ft.

Located approximately 400 ft. east from logging road turnout. Corner is in old growth timber just east of north south cutting line

1/18/91

Section Corner for Sections 15, 16, 21 & 22.

145

Found - A 3 1/2" diam. 1968 BLM brass cap, on 2 1/2" O.D.I.P. protruding 7" above ground.  
B.T.s - 13" fir now 19" with a fully healed single blaze, bears N.62 1/2°E., 14.8 ft. (record N.77 1/2°E., 14.8 ft. bearing is a probable error in reading compass.)  
8" fir now 15" with a fully healed single blaze, bears S.32°E., 5.9 ft. (agrees with record.)  
10" d. fir now 19" with a fully healed single blaze, bears S.14°W., 19.8 ft. (record S12°W., 19.8 ft.)  
15" d. fir now 22" with a fully healed single blaze, bears N.2 3/4°W., 49.8 ft. (agrees with record.)

No new monuments or accessories. See vicinity sketch in C.S. file.

1/23/91

Douglas County  
Surveyors Office  
Stephen Flause  
Terrie Franssen  
Randall Smith (PC)  
Jan. 23 1991  
C.S. 64/13

FD. 1/92  
G. Bausman  
M112-43