

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 25 S. T. S. R. 8 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

19

Section Corner to Sections 11 - 12 - 13 - 14.  
Found - 36" Fir S.35°W. 6 ft. Old bark scribing visible "14" & "R".  
Illegible traces of more bark scribing visible, more recent bark scribing found "BT".  
22" Fir N.45°W. 10.6 ft. Old bark scribing visible, T25S & S11.  
More recent bark scribing "BT".  
No trace found of N.E. & S.E. BT's.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T25S R8W 

S11	S12
S14	S13

 Office, 1962  
Blaze & Rescribe (in wood): 36" D. Fir S.35°W. 6.0 ft. Mkd: T25SR8W S14 CS BT.  
\* 22" D. Fir N.45°W. 10.6 ft. Mkd: T25S R8W S11 CS BT.  
New BT's: 32" D. Fir S.79°E. 27.0 ft. Mkd: T25S R8W S13 CS BT. (in wood)  
45" D. Fir N.48°E. 28.0 ft. Mkd: T25S R8W S12 CS BT.  
Corner lies on very steep N.E. slope, approx. 600 ft. East of Road along top of ridge.

FD-OK 2/2/83  
H. JOHNSTON  
M 94-76  
\* FD To Be  
N. 55°W

20

Section Corner to Sections 22 - 23 - 26 - 27.  
Found - 1" Iron Pipe and following Bearing Trees:  
38" Fir N.73°E. 16.5 ft. (to old face) Bark scribing (looks like Flint's scribing) "T25S R8". Gov't. notes call for this BT. to be N.53°E. 16.5 ft.  
Fir Snag, broken off in Oct. 12th windstorm, now 33" diam., S.19°E. 17.2 ft. (to old face) Old bark scribing "T2", rest of face destroyed. Gov't. notes call for this BT. to be S.33°E. 17.2 ft.  
No trace of N.W. Or S.W. BT's., impossible to get bearings & distances to fit Gov't. notes on 2 BT's. found.  
DID NOT SET BRASS CAP.  
Reblaze & Scribe 38" D. Fir N.73°E. 17.5 ft. (to center) Mkd: T25SR8WS23 CS BT.  
New BT's: 5" Hemlock S.44°E. 34.4 ft. Mkd: "S26 CS BT."  
7" Hemlock N.54°W. 4.1 ft. Mkd: "T25S R8W S22 CS BT".  
6" Hemlock S.61°W. 38.0 ft. Mkd: "T25S R8W S27 CS BT".  
Corner lies on very steep N.E. slope.

Milo E. Godfrey, Deputy County Surveyor  
Vernon Tracy and Mike Stone  
October & November 1962  
C.S. File No. 49/88

21

Sec. Cor. to Secs. 1 & 2, T25-8W. & Sec. 35 & 36, T24-8W.  
Found - Brass Cap at Corner, CS 1958, See Ren. 8.  
20" Cedar, now snag, N.38°W. 24.9 ft., full scribing visible.  
11" R. Fir N.65½°E. 53.3 ft., scribing visible.  
Other BT's. down.  
New BT's: 7" D. Fir N.63°W. 22.3 ft. Mkd: T24S R8W S35 CS BT.  
5" W. Fir S.35°W. 20.3 ft. Mkd: T25S R8W S2 CS BT.  
8" D. Fir S.77°E. 10.5 ft. Mkd: T25S R8W S1 CS BT.

Bruce R. Roger, Deputy  
Mike Stone  
April 15, 1965  
C. S. File No. 49/84

22

¼ Corner to Sec. 2, T25-8W. & Sec. 35, T24-8W.  
Found - Brass Cap at Corner, CS 1958, See Ren. 8.  
20" Cedar, now snag, S.70°W. 38.0 ft., full scribing visible.  
36" R. Fir, down, N.8°W. 18.5 ft., bark scribing visible.  
New BT's: 5" W. Fir S.86°W. 45.0 ft. Mkd: ¼ S 2 CS BT.  
8" Cedar N.31°E. 53.0 ft. Mkd: ¼ S35.

23

Section Corner to Sections 2 - 3 - 10 - 11.  
Found - Orig. 36" Burned Fir N.16°E. 31.0 ft.  
shows "T25S R8W S2 BT" scribe on unhealed face, now down.  
Stumps of N.W. & S.W. BT's. (Probable) Badly Rotted.  
No trace of S. E. BT.  
Set - Brass Cap at Cor. Mkd: County Surveyor's 

S 3	S 2
S 10	S 11

 Office, 1966  
New BT's: 9" D. Fir N. 39° E. 27.5 ft. Mkd: T25S R8W S2 CS BT.  
10" D. Fir N. 6° W. 6.9 ft. Mkd: T25SR8W S3 CS BT.  
11" D. Fir S. 72° W. 20.3 ft. Mkd: T25S R8W S10 CS BT.  
14" D. Fir S. 27° E. 32.2 ft. Mkd: T25S R8W S11 CS BT.  
Note - This corner lies approx. 120 ft. N. of "Little Wolf Creek".

Vernon "Ray"  
Tracy  
T25S & R8W Crew  
4/18/66  
C.S.  
File 49/88

FD-OK 7-6-67 - V.R.T. - April 18, 1966  
COR. REF. OUT FOR RD. CONSTRUCTION - J. POWELL - 5/23/72