

**Douglas County Surveyor's Record of
Government Corners Renewed**

T 25

T. S.

R 8

R. W. W. M.

MOKE-CHAPMAN CO., EUGENE, ORE. 21891

Howard Johnstone
For: Roseburg Lbr. Co.
Sept. 2, 1983
M 94 - 76

FD. OK BY D. EDWARDS Nov. 2002 - M 141-24

110

Center 1/4 corner for Section 14
Set - 5/8" x 36" iron rod and alum. cap marked LS 498.
Scribed: 14" maple, S.68°W., 27.9 ft.
32" fir, N.84°E., 23.7 ft.

1/4 Corner for Secs. 11 and 14.

111

Found - 1965 Cadastral brass cap
16" hemlock (fir) N.14 1/2° W., 15.8 ft. healed.
12" fir, S.11°W., 31.7 ft. down.
New BT - 17" hemlock, S.16°W., 15.8 ft.

1/4 Corner for Sections 18 and 19.

112

CORNER REPORT ONLY

Found - 3/4" iron pipe.
18" hemlock stump, Weyco tag and "W" nail, bears N.47°E., 16.6 ft.
16" hemlock stump, Weyco tag and "W" nail, bears S.01°W., 19.6 ft.
Area logged in 1985. (See M 64-59 and C.S. 58/139 for information from
Michael S.McDowell, April, 1977)

Center 1/4 Corner Section 10

113

Set : A 5/8" x 30" Iron Rod with aluminum cap .
New Bt's : A 20" Fir bears S36°W, 11.7 ft. Scribed/Washer/Painted.
A 22" Fir, bears S77°E, 8.5 ft. (Scribed/Washer/Painted).
Set fence post with land survey monument sign wired to, beside aluminum cap.
Corner lies on south slope about 340 ft. south of ridge. Ridge bears
S70°E. and N70°E.

Section corner for Sections 28 and 33 only.

114

Found - 1968 County 2 1/2" brass cap on a 1 1/2" O.D. iron pipe that measures
36" long, is laying on top of ground, out of position. Ren. #59
24" now 27" dia. rotted 5 ft. high D. fir stump with scribing
visible on upper blaze "5 8 R8" bears N.70°E., 31.0 ft. (agrees
with record). 1911 resurvey BT. A BT tag on stump with initials
H.W.T. shows a bearing of N.82°W., 23 ft. Source unknown.
29" now 39" dia. 4 ft. high D. fir stump with illegible scribing
visible in a previously opened upper blaze, bears N.88°E., 40.3 f
(Rec. N.88°E., 42.4 ft. is a slope measurement from Ren. #59)
Agrees well with 1972 resurvey.) 1911 resurvey BT.

Set - Position of corner determined from two 1911 resurvey BTs at bearing
and distances as found. Position is referenced and 1968 DCSO
BC/IP with marks "RESET 1988" added is set. A 2 ft. dia. mound
of sand stone is placed around BC. BC protrudes 4" above mound
os sandstone.

New BTS - 6" hemlock double blazed and scribed "T25S R8W S33 CS BT" bears
S.70 1/2°E., 49.2 ft.

5" cedar double blazed and scribed "X BT" bears N.31°E., 50.6
Corner lies on a steep north slope at the west edge of a northerly
running ravine, in a recently logged clear cut.

FD OK 10/94 M119-41

115

Closing corner for Sections 29 and 32.

Found - 1968 County brass cap on a 1 1/2" O.D. iron pipe 36" long out of
ground and out of position on a steep hillside. Monument set in
Ren. #58. No evidence of 1911 cedar post found.

Orig. BT, a 30" fir, now a 36" DBH D. fir snag with a previously
opened blaze, showing a "2" and other illegible scribing, bears
S.80°W., 5.3 ft. (per orig. rec.) Other OBT not found.

A 13" Hemlock now a 16" DBH hemlock with a partially healed single
blaze revealing illegible scribe marks bears N.38°W., 21.8 ft.
(as per BLM resurvey record) Ren. No. 58

A 7" Hemlock now an 8" DBH Hemlock with a fully healed single blaze
bears S.54°W., 20.8 ft. (as per Ren. #58)

A previously unrecorded bearing tree found in BLM resurvey, bearing
N.19°W., is gone, possible removed by logging.

Les Roberts
For: International
Paper Co.
Dec. 15, 1987
M103 - 37/C.S.63/46

Douglas County Surveyors Office
R. W. Smith - Stephen J. Flause
Oct. 12, 1988
C.S. 62/59