

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 26 S. T. S. R. 1 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21981

Cor. to Sections 13 and 24 only, T26-2W. - West line Sec. 18, T26-1W.  
Found - Pile of Rocks, chisel mark " --" on one of them.

20" Fir N.67°W., not N.60°W., 9.2 ft. Cut open & fd. good scrbing. Milo E.  
20" Fir S.27°W., not S.14°W., 7.9 ft. Opened & fd. old face Godfrey &  
badly rotted. No scribing visible. This tree was opened #110 Crew  
approx. 50 yrs. ago & looked as if scribing was chopped off. 3/29/63  
at that time. C. S. File  
No trace Orig. NE. BT Or SE. BT. No. 52/77

Set - Brass Cap at Cor. Mkd: County Surveyor's T26S R2W S13 | RLW  
Pile Rocks around cor. Office, 1963 S24 |

New BT's: 9" D. Fir S.63°W. 11.4 ft. Mkd: T26S R2W S24 CS BT.

Rescribed: 20" D. Fir N.67°W. 9.2 ft. Mkd: T26S R2W S13 CS BT.

Note - Corner lies approx. 130 ft. North of N. Umpqua Highway.

Section Corner common to Sections 5 - 4 - 8 - 9.

Found - Orig. D. Fir Corner Tree, now 30", with old faces on all  
sides, from which tree a:

14" D. Fir, Orig. BT. with scribes visible, bears N.31°E. 7.3 ft.

Small D. Fir Stump, probable Orig. BT., bears S.63°E. 6.6 ft.

All other Orig. BT's. now missing.

New BT's: 30" D. Fir scribed "T26S RLW S9 BT, bears S.71°E. 31.0 ft.

6" D. Fir, scribed "T26S RLW S8 BT" bears S.52°W. 29.6 ft.

26" D. Fir, scribed "T26S RLW S5 BT" bears N.62°W. 61.0 ft.

Dec. 1964

Bruce A. Shaner  
For U. S.  
Forest Service  
Dec. 1964  
C. S. File  
No. 51/281

Section Corner to Sections 12 & 13 only, T26-2W.

Found - Mound of Stone as recorded in Ren. # 3, T26-2W.

Orig. 48" Fir S. 85° W. 27.1 ft. (face) now burned Snag,  
no scribing found.

Orig. 24", now 30", Fir N. 55° W. 36.3 ft. (face slope), Alive  
and Orig. bark scribe "12" and rescribed "T26W S12 CS BT"

8", now 11", Fir S. 40° W. 13.9 ft. (slope), not S. 36° W.,

Good scars, we do not open.

Set - Brass Cap in Mound of Stone & Mkd: T26S R2W S 12 | RLW  
County Surveyor's Office, 1966 S 13 |

All Bearing Trees in good condition, Did not mark new ones.

Vernon "Ray"  
Tracy  
M. Stone &  
J. Heritage  
March 5, 1966  
C. S. File  
No. 52/77

1/4 Corner to Section 30 only, T26-1W.

Found - Orig. 18", now 20" Cedar, N. 49° E. 16.5 ft. Alive & shows  
old "1/4 S30 BT" scribe on unhealed blaze.

No trace of S. E. BT. due to cat. logging.

No trace of stone called for.

Set - Brass Cap at Cor. Mkd: County Surveyor's T26S R2W 1/4 S 30 | RLW  
Office, 1966

New BT's: 28" D. Fir S. 27 1/2° E. 66.7 ft. Mkd: 1/4 S30 CS BT.

8" Hemlock S. 77° E. 94.5 ft. Mkd: 1/4 S30 CS BT.

Note - This corner lies approx. 60 ft. south of Thunder Mt. Road.

Vernon "Ray"  
Tracy & Crew  
May 19, 1966  
C. S.  
File  
No. 52/77

Township Corner - T25S R2W S 36 | RLW  
T26S S 1 |

Found - Orig. 16", now 30" Pine S. 60° W. 43.6 ft., scribe visible on  
prev. opened scar.

Orig. 16", now 30" Pine S. 55° E. 29.7 ft., shows old scar.

Recorded as marks obliterated.

Orig. 30", now 40" Fir N. 85° E. 76.6 ft., shows frag. bark  
scribe, recorded as being obliterated.

N. W. BT. gone. - Did not find Stone as called for.

Set - Brass Cap at Cor. Mkd: County Surveyor's T25S R2W S 36 | RLW  
Office, 1966 T26S S 1 |

New BT's: 7" D. Fir N. 56° W. 28.2 ft. Mkd: T25SR2W S36 CS BT.

15" Hemlock S. 50° W. 8.1 ft. Mkd: T26S R2W S1 CS BT.

note - Corner lies on N. & E. slope in mound of stone, 12" high.

June 9, 1966

C.  
S.  
F  
I  
L  
E  
No. 52/77