

Douglas County Surveyor's Record of
Government Corners Renewed

T. 26 S. T. S. R. 1 W. R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

51

Section Corner to Sections 31 and 32 only, T26-1W.
Set from rod set as reference pins, See Ren. #39, & notes
in C. S. File. This corner lies 25 ft. north of new road.
Also 116.4 ft. east of Sec. Cor. To Secs. 5 & 6 only, T27-1W.
Reset Brass Cap in Proper Location, from Bearing Trees:
36" Cedar N.34*E. 7.9 ft. scribed "T26S RLW S31 CS BT".
15" Hemlock N.19*W. 21.8 ft. scribed T26S RLW S31 CS BT".
11/13/70

John M.
Powell & Crew
C.S. File No.
54/94

52

Section Cor. to Sections 12 & 13 only, T26-1W.
Found: 1928 GLO Brass Cap properly mkd., firmly in ground at proper
dist. 6.85 chs., 752.10 ft. from closing cor.
Also found possible rock mound S. 60° W. (rec. S. 40° W.) 6.6 ft.
No other means of identification.
New BT's: 11" D. Fir, N. 12° W., 37.8 ft. scribed T26S RLW S12 CS BT.
PK Nail in outcrop south 14.4 ft. PK Nail approx 8.0 ft. above
ground on NW end of rock.
Note: Rock outcrop bears south 14.4 ft. Set PK Nail. Rock approx 8.0 ft.
high, 20.0 ft. long. Cor. lies on steep SW slope in opening,
on SW edge of brush patch.

MARCH 71

Aug. 16, 1971

53

Closing Corner to Sections 7 and 18 only. T 26 S R 1 E.
Found: GLO Brass Cap, 1928, at closing corner properly mkd.
8" D. Fir now 10", S 31° E., 25.7 ft. Shows good scar.
18" D. Fir now snag, N. 42° E., 78.5 ft. Shows good scar
New BT's: 13" D. Fir, N. 22° E., 16.8 ft. Scribed T26S R1E S7 CC CS BT.
Note: SE BT ok and tagged.

John M. Powell
W. Penley
J. Heritage
J. Byron
August 13, 1971

Aug. 16, 1971

54

1/4 Corner to Sections 33 and 34.
Found: 10" D. Fir, now snag, N. 65° E., 11.2 ft. scribe visible 1/4
S34 BT.
30" W. Fir, now snag, N. 21° W., 30.4 ft. Scribe visible
1/4 S33 BT.
Also stone at 1/4 Cor. mkd. 1/4 & + on top.
Set: 5/8" I. Rod along side stone. (As this area is to be thinned,
Brass Cap would probably be lost through logging.)
New BT's: 33" D. Fir, S. 81° E., 12.0 ft. Scribed 1/4 S34 CS BT.
16" D. Fir, N. 56° W., 29.7 ft. Scribed 1/4 S33 CS BT.

C. S. File 54/94

JAN. 1972

55

1/4 Corner to Sections 17 and 18.
Found - Orig. 48", now 50" Fir, alive, S. 3-1/2° E. 29.0',
open to axe blaze, no scribe visible, partially
decayed.
Orig. 28", now 30" Fir sawed stump, N. 81° W. 39.6',
scribe visible on opened blaze.
No trace of Basalt Corner Stone Found.
Set-Brass Cap at Cor. Mkd: County Surveyor's T26S RLW
Office, 1972 1/4 S 18 | S 17
New BT's: 9" D. Fir N. 51° E. 24.2 ft. scribed "1/4 S17 CS BT"
6" D. Fir N. 89° W. 9.2 ft. scribed "1/4 S18 CS BT"
This corner lies approx. 100' above N. Ump. Hwy. on very
steep, south slope.

T
R
A
C
Y,
V.
R.
C.S. File
No. 52/77

4/11/72

56

Township Corner thus:

RLW S36	S 31	T 26S
	S 6	R1E T 27S
1927		

Found - 1927 GLO Brass Cap on ground 13 ft. E. of corner.
Reset Brass Cap at Twp. Corner mkd. as shown above.
Found - 17" D. Fir, now stump, N. 16° E. (Rec. N. 19° E.) 104.3 ft., scribe
visible.
40" D. Fir, now stump, S. 59° E. 54.1 ft., opened for scribe.
New BT's- 6" D. Fir, S. 64° E., 58.1 ft. mkd. S6 CC CS BT.
4" D. Fir, S. 18° E., 7.0 ft. mkd. S6 CC CS BT.
4" D. Fir, N. 36° W., 7.0 ft. mkd. S36 CS BT.

John M. Powell
F. Jones, W. Penley
October, 1969
C.S. File 54/94

This corner lies in clear cut unit about 90 ft. W. of ridge, running N-S.
10/29/69