

Douglas County Surveyor's Record of
Government Corners Renewed

T 26

T. S.

R 1

R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97501

Maurice E. Farr
U. S. Forest
Service
Leonard Herzstein
Dave Burr
May 12, 1988
C. S. 63/73

Closing Corner for Sections 1 and 2.

115

CORNER REPORT ONLY

Found - 18" x 9" x 5" water-worn stone laying on the ground with marks "X" on east side (top of stone); (CC" on north side; one groove on top; and 5 grooves on bottom.

I was unable to locate the hole the stone came out of. I use the center of the stone as the position for the corner point.

A 20" madrone stump, bears S.13°E., 27.7 ft. (Rec. S.21°E., 42 lks.) with no marks visible on partially healed decayed blaze.

A 30" D. fir stump, S.40°W., 20.2 ft. (Rec. S.44°W., 31 lks. with healed blaze. I chop open and find scribe marks "W" at 8" diameter.

I place bearing tree tags on both BT stumps.

Corner is about 150 ft. south of timber inside a clearcut and 50 ft. east of a small creek on a steep west slope. To reach corner from forest service Rd. No. 3800-010, turn west onto Rd. No. 3800-017, drive 1.0 mi. and turn left onto Rd. No. 3800-026, drive 0.5 miles to location poster at clearcut. Corner is approx. 1050 ft. west of location poster, at the bottom of the clearcut, 1000 ft. lower than road.

5/12/88

East 1/4 Corner Section 12 only.

116

Found - 18" x 12" stone with a chiseled "+" on top, protruding 6" above ground. (original) Stone is firmly set.

No original BTs found.

6" now 33" dia. d. fir with a fully healed double blaze bears S.45°W., 35.3 ft. (Rec. S.45°W., 34.3 ft.) (1928 Dep. survey)

6" now 23" dia. D. fir with a fully healed single blaze bears N.25°W., 28.4 ft. (agrees w/rec.) (1928 dep. Resurvey)

Set - Original stone is in good shape, goes into ground and gets larger, does not appear to be easily moved. We did not set a brass cap for corner.

New BTs - 8" dia. D. fir double blazed and scribed "1/4 S12 CS BT" bears N.83½°W., 9.8 ft.

7" dia. D. fir double blazed and scribed "1/4 S12 CS BT" bears S.35°W., 8.2 ft.

Corner lies on a westerly slope.

4/4/91

West 1/4 Corner Section 7 only of T.26-1E

117

Found - 1928 2½" dia. GLO brass cap on a 1" O.D. iron pipe protruding 11" above ground. A 2 ft. dia. mound of stone is found along East edge of BC/IP (Rec. raised mound of stone 3 ft., 2 ft. high E. of cor.) (original cor.)

20" now 39: dia. D. fir with a fully healed single blaze, bears N.56°E., 19.1 ft. (Rec. N.60°E., 19.1 ft)(Orig. BT.)

New BTs - 14" dia. D. fir double blazed and scribed "1/4 S7 CS BT" bears S.28°E., 4.6 ft.

15" dia. D. fir double blazed and scribed "1/4 S7 CS BT" bears S.2°E., 34.8 ft.

8" dia. D. fir double blazed and scribed "1/4 S7 CS BT" bears N.71°E., 32.7 ft.

Corner lies on a westerly slope.

4/4/91

1/4 Corner for Sections 1 and 12

118

Found - Original stone, top measures 10" x 5", protruding 5" above ground, chiseled "1/4" on north side.

36" now 38" dia. tipped out of ground burnt cedar, no scribing or blazes found, root hole bears S.37°W., 31.7 ft. (agrees with record) Original BT.

Original NW BT not found.

Set - Orig. stone is referenced, stone measures 10" x 5" x 9" with smaller fractured pieces near. (Rec. 12" x 10" x 8").

A 2 3/8" dia. DCSO brass cap on a 1 3/8" O.D. x 32" long iron pipe is set at referenced position & protrudes 12" above ground. A 2 ft. dia. mound of stones is placed around base of BC/IP with marked original stone along north edge of BC/IP. "1/4" faces North. BC/IP protrudes 5" above mound of stone. Cap mkd: Douglas County Surveyors T26S ¼ S1 S12 R1W 1991 Office.

Douglas County Surveyors Office
Randall Smith, Deputy
Stephen Flause
Terrie Franssen
April, 1991
C.S. 64/13