

Douglas County Surveyor's Record of
Government Corners Renewed

26 T. S. 2 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21681

G. Robert Lecklider
July 30, 1959
C. S. File
No. 51/35.

North $\frac{1}{4}$ Corner of Section 3.
FOUND: A Stone 16" x 10" x 8" marked " $\frac{1}{4}$ " on South
face (Both BT's, referring to this corner
are gone.)
Set : $\frac{3}{4}$ " Iron Rod next to Stone from which:
I scribed a 26" Douglas Fir which bears
S. 55°W. 78.8 feet,

18

G. R. Lecklider
For Mrs. O. J. A. Messing
December, 1959
Map File No. M 16 - 68

$\frac{1}{4}$ Section Corner to Sections 10 and 11.
Found : No evidence of Original Corner.
Set : By proportionate measurement.
Steel Tube with survey cap.
14" Fir N. 50°E. 15.4 feet.
11" Fir N. 60°W. 13.3 feet.

SEE REN. NO. 95
FOR $\frac{1}{4}$ COR. SET.
NORTH 19.71' - JULY, 1969
M 38-25

19

Marvin C. Ramsey
For J. H. Baxter &
Co.
March 29, 1960
C. S. File
No. 51/86

Center $\frac{1}{4}$ Corner to Section 10.
Set: Steel Tube with Survey Cap.
16" Fir N. 7°W. 55.2 feet.
18" Fir S. 35°E. 23.8 feet.

19A

Center of Section 8.

Point for center $\frac{1}{4}$ sec. cor. at intersection with the East & West
center line.

Set an iron pipe 3 ft. long & diam 28" in the ground mkd. RS404 BT.
From which:
10" Maple bears N. 19°E. 59 lks. dist. mkd. C $\frac{1}{4}$ S8 RS404 BT.
14" Maple bears S. 58°E. 60 lks. dist. mkd. C $\frac{1}{4}$ S8 RS404 BT.
14" Mad. bears S. 10°W. 18 lks. dist. mkd. C $\frac{1}{4}$ S8 RS404 BT.
12" Cedar bears N. 7°W. 123 lks. dist. mkd. C $\frac{1}{4}$ S8 BT.

RE-RENEWED, SEE CORNER NO. #117

20

Weyerhaeuser
Timber co.
Lester E.
Calder
April 1960
C. S. File No.
51/87

$\frac{1}{4}$ Corner common to Sec. 19, T26-2W. & Sec. 24, T26-3W.
GLO Survey Record: Post, down, decayed, scribed.
10" Laurel S. 25°W. 10 lks. - Fd. in 1950-51 survey, gone in '59 Survey.
10" Laurel N. 69°E. 13 lks. - Okay.
Found corner reformed previously by Curtis Price with plate & "W" REN. #7
nail on one tree & plate only on other tree. Destroyed these
references & re-fer as follows: 30" Fir S. 55°E. 17.4 ft.
20" Hem. Stump S. 24°W. 7.2 ft.

RE-RENEWED, SEE CORNER NO. #113

21

$\frac{1}{4}$ Corner to Sec. 6, T26-2W and Sec. 1, T26-3W.

Set one new tree:

40" Fir N. 24.3 ft. Mkd. $\frac{1}{4}$ S. CS BT.

Set by A. Boyer, May 22, 1937

RE-RENEWED
COR. NO. 78

22

East $\frac{1}{4}$ Corner of Section 1.

Found - Stone Mkd: " $\frac{1}{4}$ " on West face.

Shattered Stump of Hemlock N. 89°W. 5.9 ft., scribe Mk. "S",
plainly visible.

All trace of S.W. BT. gone. (CORNER FOUND O.K. JUNE, 1966 - V.R.T.)

Set - Iron Pipe with Brass Cap Mkd: County Surveyor's Office, 1961
T26S R2W $\frac{1}{4}$ S1

New BT's: 11" Hemlock S. 56 $\frac{1}{2}$ °E. 11.4 ft. Mkd: E $\frac{1}{4}$ S1 CS BT. (Land has been logged
8" Hemlock N. 36°E. 7.5 ft. Mkd: E $\frac{1}{4}$ S1 CS BT. to West)

East $\frac{1}{4}$ Corner of Section 12.

Found - Rock at Corner, no markings on Rock, crumbly.

Stump of 70" Fir S. 21°W. 26.4 ft., no scribing.

Cedar, now 18", N. 77°W. 17.8 ft. Blaze still open, scrbing
visible " $\frac{1}{4}$ S". Tree still in good condition.

Set - Iron Pipe with Brass Cap Mkd: County Surveyor's Office, 1961
T26S R 2 W $\frac{1}{4}$ S12

New BT: 12" D. Fir S. 43°W. 61.0 ft. Mkd: $\frac{1}{4}$ S12 CS BT.

24

Mile Godfrey
Clete Putnam
April 17, 1961
C. S. File No. 52/77

C. S. FILE 50/214