

Douglas County Surveyor's Record of
Government Corners Renewed

T. 26 S. T. S. R. 2 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

35

Sec. Cor. to Sections 12 & 13 only.

Found - Mound of Stone.

Orig. 48" Fir S. 85° W. 27.1 ft. (face), now burned snag, no scribing found.

Orig. 24", now 30", Fir N. 55° W. 36.3 ft. (face slope), Alive & Orig. bark scribe "12", & rescribed, "T26S S12 R2W CS BT. See Ren. #3.

8", now 11" Fir S. 40° W. 13.9 ft. (slope), not S. 36° W., Good scars, we do not open. *REN. #3*

Set - Brass Cap in Mound of Stone & Mkd: T26S $\frac{S}{R2W} \frac{12}{13} | RLW$
County Surveyor's Office, 1966

All Bearing Trees in good condition. Do not mark any new trees.

Vernon "Ray" Tracy
Mike Stone & J. Heritage
March 5, 1966.
C. S. File No. 52/77

36

$\frac{1}{4}$ Corner to Section 30 only, T26-1W.

Found - Orig. 18", now 20" Cedar, N. 49° E. 16.5 ft. Alive & shows old " $\frac{1}{4}$ S30 BT" scribe on unhealed blaze.

No. trace of S. E. BT. due to cat. logging.

No trace of Stone called for.

Set - Brass Cap at Cor. Mkd: County Surveyor's T26S R2W $\frac{1}{4}$ S 30 RLW
Office, 1966

New BT's: 28" D. Fir S. 27 $\frac{1}{2}$ ° E. 66.7 ft. Mkd: $\frac{1}{4}$ S30 CS BT.

8" Hemlock S. 77° E. 94.5 ft. Mkd: $\frac{1}{4}$ S30 CS BT.

Note - This corner lies approx. 60 ft. south of Thunder Mt. Road.

May 19, 1966

C.

Township Corner - T25S R2W $\frac{S}{T26S} \frac{36}{1} | RLW$

37

Found - Orig. 16", now 30" Pine S. 60° W. 43.6 ft., scribe visible on prev. opened scar.

Orig. 16", now 30" Pine S. 55° E. 29.7 ft., shows old scar.

Recorded as marks obliterated.

Orig. 30", now 40" Fir N. 85° E. 76.6 ft., shows frag. bark scribe, recorded as being obliterated.

N. W. BT. gone. - Did not find Stone as called for.

Set - Brass Cap at Cor. Mkd: County Surveyor's T25S R2W $\frac{S}{T26S} \frac{36}{1} | RLW$
Office, 1966

New BT's: 7" D. Fir N. 56° W. 28.2 ft. Mkd: T25SR2W S36 CS BT.

15" Hemlock S. 50° W. 8.1 ft. Mkd: T26S R2W S1 CS BT.

note - Corner lies on N. & E. slope in mound of stone, 12" high.

June 9, 1966

S.

F

I

L

E

No. 52/77

38

Closing corner of Sections 19 & 30, T26-1W.

Found - Both Orig. BT's. in excellent condition, as follows:

Orig. 30", now 38" Fir N. 58° E. 9.2 ft., shows good scar. Do not open.

Orig. 18", now 22" Cedar S. 81° E. 15.2 ft., shows "T26S RLW S30 CC BT" on unhealed face.

Set - Brass Cap at Cor. Mkd: County Surveyor's T26S R2W CC $\frac{S}{S} \frac{19}{30} | RLW$
Office, 1966

Do not mark new BT's as both Originals are O. K.

Corner lies on very steep N. E. slope.

*FD. OK 2/81 M 84-48
G. GRUBB*
June 22, 1966

C.

S.

File

No.

52/77

39

$\frac{1}{4}$ Corner to Sections 35 and 36.

Found - Orig. 16", now 20" Fir, S. 80° E. 17.2 ft., now Stump buried to top of scar in old slide.

Orig. 10", now 18" Cedar, N. 48° W. 37.0 ft. Alive, we open & find "BT" scribe and reverse.

No trace of Brass Cap set by Mensch in 1916.

Set - Brass Cap at Cor. Mkd: County Surveyor's T 26 S R 2 W
Office, 1967 $\frac{1}{4} S 35 | S 36$

New BT's: 14" Cedar S. 23° W. 15.0 ft. mkd. "S35 CS BT.

8" Cedar N. 80° E. 8.9 ft. mkd. " $\frac{1}{4}$ S36 CS BT.

Note - This corner lies in small ravine, course E.

Vernon "Ray" Tracy
J. Heritage & E. West
March 9, 1967
C.S. File No. 54/40