

Douglas County Surveyor's Record of
Government Corners Renewed

T. 26 S. T. S. R. 2 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

3 Corner of Tract 38. *FOUND OK BY HOSTETTER, OCT. 2002 M 141-16* **66**
 Found - 1918 G.L.O. Brass Cap, firmly set, properly marked and
 T in good condition.
 The BT for this corner was apparently destroyed in recent logging.
 New BT: 10" Cedar N. 74° E. 95.7 ft. mkd. " 3 TR 38 CS BT.
 Note - The Brass Cap for the $\frac{1}{4}$ Corner of Sections 34 & 35 bears North 12.5 ft., as called for in field notes.
 This corner lies on steep east slope, 100 ft. west of temporary logging road.

NORTH $\frac{1}{4}$ Corner to Section 6 only, T26-2W. **67**
 Found - Remains of very old cedar post, badly decayed, no scribing. *#107*
 Orig. 40", now 60" Fir S. 31° E. 25.7 ft., alive, shows good scar.
 Orig. 36", now 50" Fir S. 54° W. 23.8 ft., alive, Open & find "B".
 Set - Brass Cap at Cor. Mkd: County Surveyor's $\frac{1}{4}$ T25S R2W
 Office, 1967 S 6 T26S
 New BT's: 7" D. Fir S. 32° W. 14.3 ft. mkd. $\frac{1}{4}$ S6 CS BT.
 14" D. Fir S. 54° E. 15.2 ft. mkd. $\frac{1}{4}$ S6 CS BT.
 Note - This corner lies on S.W. slope.
FD. OK - 3/76 BY E. BAUGHMAN C.S. 58/100

Sec. corner to Sections 25 and 36 only, T26-2W. **68**
 Found - 1916 GLO Brass Cap, firmly set, properly marked. *#145*
 Orig. 30", now 32" Fir Stump, down, 20.5 ft., shows scar.
 Orig. 48", now 50" Cedar, down, 11.9 ft., shows scribe marks on notched side.
 New BT's: 50" Cedar S. 84° W. 23.4 ft. mkd. T26S R2W S36 CS BT.
 34" D. Fir N. 76° W. 37.1 ft. mkd. T26S R2W S25 CS BT.
 Note - This corner lies on top of spur, sloping SW. at old cutting corner. Cut off in section 36.

$\frac{1}{4}$ Corner for Sec. 31, T26-1W. **69**
 Found - Orig. Corner Stone 12"x8"x6" in place mkd: " $\frac{1}{4}$ " on E. side.
 Orig. 18", now 28" Fir, N.12°E. 37.0 ft. Alive, shows good scar.
 Orig. 30", now 40" Fir, S.27°E. 12.5 ft., alive, shows good scar.
 Set - Brass Cap at Cor. Mkd: County Surveyors T26S R2W $\frac{1}{4}$ S31 R1W
 Office, 1967
 Reset Stone alongside in Mound of Stone.
 Note - This corner lies on steep southerly slope 87.8 ft. S. of $\frac{1}{4}$ cor. of sec. 36, T26-2W. No new BT's. marked.

Closing Corner for Secs. 30 & 31, T26-1W. **70**
 Found - No trace of Corner Stone or N.E. BT.
 Orig. 8", now 16" Hemlock, S.27°E. 15.2 ft., Alive, open & find scribe
 Set - Brass Cap at Cor. Mkd: County Surveyors T26S R2W S30 R1W
 Office, 1967 R2W S 31
 New BT's: 44" D. Fir N. 40° E. 32.0 ft. mkd. T26S R1W S30 CC CS BT.
 14" Hemlock S. 32° E. 34.7 ft. mkd. T26S R1W S31 CC CS BT.
 Note - This corner lies on N. side of Dry Creek bottom, course W. *#149*

Township Corner. - T26S. & T27S., R's. 1 & 2 W. **71**
 Found - No trace Original Corner Stone or other obliterated BT.
 Orig. 40", now 48" Fir, down, S.74°W. 16.5 ft., open & shows scribe.
 Orig. 24", now down & almost completely buried Fir, N.3°W. 15.2 ft.
 Orig. 6", now 16" Fir, down, S.60°E. 20.5 ft., open & find obliterated blaze as called for.
 Set - Brass Cap at Cor. Mkd: County Surveyors T26S R2W S 36 R1W
 Office, 1967 T27S S 1
 New BT's: 10" Cedar N. 70° W. 36.5 ft. mkd. T26S R2W S36 CS BT.
 18" D. Fir S. 88° W. 41.7 ft. mkd. T27S R2W S1 CS BT.
 Note - This corner lies on southerly slope.

Vernon "Ray" Tracy
 Jack Heritage & E. West
 August 10, 1967
 C.S. File 54/40