

Douglas County Surveyor's Record of
Government Corners Renewed

T. 26 S. T. S. R. 2 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

72

Closing Corner of Townships.
Found - Corner Stone mkd: "CC" & 6 notches on N. & S. edges.
Orig. 28", now 38" Cedar, S. 62° E. 21.1 ft., alive, scribe vsble. on unhealed blz.
(We rescribe "T27S RLW S 6 CC CS BT")
Orig. 12", now 22" W. Fir, N. 80° E. 25.7 ft. Alive, scribe vis. on unhealed blaze.
(We rescribe "T26S RLW S31 CC CS BT")
Set - Brass Cap at Cor. Mkd: County Surveyors T26S R2W CC $\frac{S}{S} \frac{31}{6}$ RLW
Office, 1967 T27S
New BT: 14" W. Fir S. 35° E. 30.9 ft. mkd. T27S RLW S6 CC CS BT.
Note - This corner lies on steep north slope approx. 450 ft. S. of
E Mile Creek.

73

$\frac{1}{4}$ Corner to Sections 23 and 24.
Found - 1916 G.L.O. Brass Cap, properly marked.
Orig. 48", now 54" Fir, N. 50° E. 4.0 ft., alive, shows good scar. Do not open.
Orig. 10", now 14" Maple, S. 38° W. 1918 ft., alive, shows scribe on
decaying blaze.
New BT's: 10" Cedar S. 2 $\frac{1}{2}$ ° E. 30.1 ft. mkd. $\frac{1}{4}$ S24 CS BT.
8" Hemlock N. 66° W. 27.0 ft. mkd. $\frac{1}{4}$ S23 CS BT.
Note - This corner lies on very steep N.E. slope at N.W. corner of
very old cut-off unit.

74

$\frac{1}{4}$ Corner to Sections 23 and 26.
Found - 1916 G.L.O. Brass Cap, properly marked.
Orig. 24" Cedar, now shattered stump, S. 25° E. 3.3 ft., no scribe found.
No trace N.E. BT., both BT's. were probably destroyed by logging
several years ago.
New BT's: 28" Cedar N. 23° W. 60.1 ft. mkd. $\frac{1}{4}$ S23 CS BT.
39" Cedar S. 85° E. 116.6 ft. mkd. $\frac{1}{4}$ S26 CS BT.
Note - This corner lies on N.W. slope in N.E. corner of cut off unit.

75

Sec. Corner to Sections 23 and 26 only.
Found - 1918 G.L.O. Brass Cap, properly marked.
Orig. 18", now 22" Fir Snag, N. 43° E. 7.3 ft., shows good scar.
No trace of Orig. BT. in section 26.
New BT's: 8" Hemlock S. 38° E. 3.2 ft. mkd. T26S R2W S26 CS BT.
7" W. Fir N. 55° E. 13.7 ft. mkd. T26S R2W S23 CS BT.
Note - This corner lies on large flat bench in very old logged-off
unit. Obliterated O.B.T. to SW. alive.

76

$\frac{1}{4}$ Corner to Section 22 only. (SOUTH $\frac{1}{4}$) *FD. OK, FEB. 2004*
D. EDWARDS - M143-66
Found - 1918 G.L.O. Brass Cap, firmly set, & properly marked.
Orig. 8", now 14" Fir, turned out, N. 31° W. 15.8 ft., prev. opened & shows scri
No trace of N. E. Bearing Tree.
New BT's: 9" Hemlock N. 29° W. 21.7 ft. mkd. $\frac{1}{4}$ S22 CS BT.
15" Cedar N. 87° E. 44.9 ft. mkd. $\frac{1}{4}$ S22 CS BT.
Note - This corner lies on N.E. slope approx. 125 ft. W. of old log access Rd.

77

$\frac{1}{4}$ Corner to Sec. 36, T26-2W. & Sec. 1, T27-2W.
Found - Unrecorded 1" Iron Pipe, firmly set.
Orig. 16", now 24" Cedar, N. 30° W. 23.1 ft., now turned out stump,
prev. opened & shows "S36" scribe.
No trace Other Orig. BT.
DO NOT SET BRASS CAP.
New BT's: 7" W. Fir N. 26° W. 18.4 ft. mkd. $\frac{1}{4}$ S36 CS BT.
7" Hemlock S. 77° E. 33.8 ft. mkd. $\frac{1}{4}$ S1 CS BT.
Note - This corner lies on southerly slope in dense brush.

Vernon "Ray" Tracy
Jack Heritage - E. West
August, 1967
C. S. File No. 54/40