

Douglas County Surveyor's Record of
Government Corners Renewed

T. 26 S. T. S. R. 2 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21081

84
1/4 Corner to Sections 24 and 25.
Found - 1916 G.L.O. Brass Cap, firmly set & properly marked.
Orig. 36", now 40" Fir north 10.6 ft., Alive, burned, shows scar, do not open
1916-18", now 22" Cedar, S. 20° E. 31.7 ft., alive, scribe visible on
unhealed blaze. This BT. in good condition.
New BT: 10" Cedar N. 23° W. 27.9 ft. mkd. 1/4 S24 CS BT.
Note - This corner lies on west slope approx. 175 ft. N. of dry ravine
& 340 ft. west of top of spur, sloping N.W. on old E-W cutting
line, cut-off to north.

85
1/4 Corner to Sections 25 and 36.
Found - 1916 G.L.O. Brass Cap, properly marked.
Orig. 10", now 13" Laurel N. 24° E. 11.9 ft., alive, scribe marks
visible on nearly healed blaze.
1916 S.W. BT., gone, only shattered stump remains.
New BT's: 8" D. Fir N. 6° E. 4.4 ft. mkd. 1/4 S25 CS BT.
8" D. Fir S. 7° W. 14.9 ft. mkd. 1/4 S36 CS BT.
Note - This corner lies on westerly slope approx. 60 ft. W. of top
of spur, ridge sloping S.W. Sec. 36 cut off many years ago.

WEST 86
1/4 Corner to Section 26 only.
Found - 1916 G.L.O. Brass Cap, properly marked. *FD. OK L/83 R. Gasler M 94-80*
Orig. 6", now 16" Fir, N. 38° E. (record N. 28° E.) 11.9 ft., alive, shows
(Rescribe: "1/4 S26 CS BT") good scar. Do not open.
Orig. 6", now 12" Fir, S. 43 1/2° E. 42.2 ft., alive, shows goodd scar,
Do not open. (Rescribe: "1/4 S26 CS BT")
Note - This corner lies on top of rounded spur, sloping N. approx. 700
ft. north of Thunder Mt. Road.

87
1/4 Corner to Sections 21 and 28. *Re-Renewed sec #164*
Found - Unrecorded 3/4" Iron Rod for corner.
Orig. 10", now 24" Cedar, alive, S. 14° E. 9.9 ft., shows "1/4 S28"
scribe on prev. opened blaze. (Rescribe: "1/4 S28 CSBT".)
No trace of Corner Stone nor N.W. BT.
New BT: 8" D. Fir N. 47° E. 18.7 ft. mkd. 1/4 S21 CS BT.
Note - This corner lies on west slope & N.-S. cutting line, cut off
to west.
DO NOT SET BRASS CAP.

88
S. E. Corner Tract 37.
Found - 1918 G.L.O. Brass Cap, properly marked. *Tract (Cor. No. 7)*
Orig. 6", now 18" Cedar, alive, N. 21° W. 50.2 ft., scribe visible
on previously opened blaze.
New BT's: 10" D. Fir N. 46° W. 20.9 ft. mkd. 7 Tr 37 CS BT.
22" Cedar N. 46° E. 12.5 ft. mkd. 7 Tr 37 CS BT.
Note - This corner lies 10.0 ft. west of dry creek bed, 4 ft. wide, course N.

89
Renew # 6 Corner of Tract 37, T26-2W.
Found - 1916 G.L.O. Brass Cap, mkd. "6 Tr 37", firmly set.
No trace of Original Bearing Trees.
The creek call to east 1.02 chains fits real well.
New BT's: 8" W. Fir S. 29° W. 14.6 ft. mkd. "6 TR37 CS BT".
8" Hemlock N. 15° E. 30.9 ft. mkd. "6 TR37 CS BT".
Note - This corner lies 5.0 ft. S. of old unusable logging road on
moderate easterly slope.

90
Renew Corner #4 or S. W. Corner Tract 37.
Found - Orig. 40", now 48" Fir, alive, N. 19° E. 35.6 ft., shows good scar.
After much excavation in area of large turned-out fir, we find
I.P. & Brass Cap, 1918, out of position in good condition:
Reset - Brass Cap, properly mkd. in 1918 in proper locus.
New BT: 5" W. Fir N. 65° E. 18.5 ft. mkd: 4 TR 37 CS BT.
Note - Corner lies on steep east slope in heavy timber.

Vernon "Ray" Tracy
Jack Heritage & E. West
August, 1967
C. S. File No. 54/40