

Douglas County Surveyor's Record of
Government Corners Renewed

T 26

T. S.

R 2

R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

C O N T:

Douglas County Surveyors
1978

T 26 S

S 24 | S 19

R 3 W 1/4 R 2 W

New BT's - A 32" D. Fir, scribed "1/4 S19 CS BT" on a double blaze bears S.52°E., 16.7 ft.

A 16" D. Fir scribed "1/4 S24 CS BT" on a double blaze, bears S.71°W., 33.6 ft.

Our new SE bearing tree, a 32" D. Fir was previously used as a reference point by Weyerhaeuser, new measurements to "W nail" S.53 1/2°E., 15.3 ft.

We search for evidence in a 20" Hemlock stump bearing S.38°W., 8.1' on the suspicion that this may be the orig. 1855 SW bearing tree, a 15" Spruce". No evidence found. This stump was used by Weyerhaeuser to reference this corner. We remove the "W-nail" in the course of our search.

113

Gary Langlitz
F.C. Silagy
Doug. Co. Survey-
ors office
Witness: Glen
McChesney,
Weyerhaeuser
Timber Company
July 20, 1978
C.S. 60/11

1-29

7/20/78

1/4 Corner for Secs. 33 and 34.

Found - 24" D. Fir, S.64°W., 38.3 ft.

Set - 2 1/2" Alum cap.

BT - 18" D. Fir, S.26°E., 28.6 ft.

Note: 1/4 Corner set from bearing tree established by Gibbs in 1909.

FD OK
B. Shoner

114

1-2001

CS 65/36-2 C

Thomas E. Shrum Jr.
For: Champion
International Co.
Feb. 1, 1979
M 76 - 56

Center 1/4 Corner for Section 34.

Set - 2 1/2" Alum. cap.

BT's- 5" White Oak bears S.33°E., 12.7 ft.

5" W. Oak bears N.19°E., 15.3 ft.

FD OK

115

B. Shoner

1-2001

CS 65/36-2 H

- Added
2.6ft Alum post +
west 1ft east 1ft

Sec. Cor. for Sec. 19&30; Sec. 24&25 of T26-3

Found - 8"x10"x14" granite stone, 4 notches on north, 2 notches on south lying on top of ground. (Rec. buried 10" below ground) (1902 Res.)

No trace of original BT's

8" Fir, now 22", bears N.58°E., 17.5 ft. (Rec. N.52°E., 17.8ft; 1902; N.55°E.; 16.7 ft. to face Ren#6) with well healed blaze

8" Fir, now 18" bears S.14°E., 17.6 ft, with healed blaze (Rec. S.16°E., 16.9 ft.), to face.

6" Fir, now 15" bears N.25°W., 12.4 ft. visible scribing in chopped out blaze "S24 BT" (Rec. N.18°W., 11.9 ft., 1902; N.20°W., 11.8 ft. to face Ren# 6)

16" Fir, bears S.51°W., 18.3 ft. with healed blaze. (Rec. S.56°W. 17.6 ft. to face. Ren# 6)

Set - 1" x 36" I.P. with brass cap marked "Douglas Co. Surveyors" Protruding 6" above ground and stone 14" in ground on west side of cap.

T 26 S
R S 24 | S 19 R
3 S 25 | S 30 2
W 1979 W

116

Karen Reed
P.L. Earle
Douglas Co. Surveyor
Office
May 9, 1979
C.S. 60/24

Note: Bearings and distances did not hit one spot - Placed cap at appropriate distance securing a bearing to the 18" Fir, bearing S. 14°E.

5/9/79

Center 1/4 Corner for Section 8

Found - 1 1/2" Iron pipe (disc gone) by M Ramsey RS 404, 1960. Ren. #20

14" Maple, scribing visible, N.19 1/2°E. 37.8 ft..

14" Maple stump, scribing visible, S.58°E., 38.6 ft. with Weyerhaeuser plate & W nail intact.

12" Cedar, scribing visible; Weyerhaeuser plate & W nail intact, bears N.06°W., 81.2 ft.

14" x 20 ft. Madrone snag, bark scribed; Weyerhaeuser plat & nail intact, S.10°W., 11.9 ft. (not recorded)

Accessories added this date:

62" Fir, S.88°E., 17.6 ft.

38" Fir, N.27°E., 43.0 ft.

This corner is apprx. 65 ft. west and 350 ft. south of Weyerhaeuser Company's 250 road. The timber surrounding this corner will be logged soon.

1/17/77

117

Glen McChesney
For: Weyerhaeuser
Company
Jan. 17, 1977
(filed 12/80)
C.S. 58/8