

Douglas County Surveyor's Record of
Government Corners Renewed

T 26

T.S.

R 2

R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

130

1/4 Corner for Sec. 13 only. (East)
Found - 3" diam. brass cap firmly set, buried 4" in ground, properly mkd. set by D. Garrett, 1972. Ren. #99
13" D. fir, S.2°W., 128.5 ft. with healed double blaze.
A steel fence post, projecting 4 ft. above ground N.3°W., 5.0 ft. with U.S.F.S. signs #54-2 & #54-4 attached.
New Accessories: (No suitable trees in S.13)
A 6" D. fir, N.77°E., 116.5 ft. mkd. "X BT" on a single blaze.
N.E. corner of Butler's 2-story log house (appx. dimensions of 24 ft. x 40 ft.) bears S. 18 1/2° W., 180.2 ft.
Note: Corner is 1 ft. east of 3'x6'x6' high boulder (recently moved to this location) & is 18 ft. east of 30 ft. diam. pond. To locate, drive up U.S.F.S. Rd. #4710-021 to gate, thence north appx. 300 ft. to corner.

1/13/84

Maurice E. Farr
L.S. #1181
For: U.S. Forest Service
Jan. 13, 1984
C.S. 62/15

1/4 Section Corner common to Sec. 35 & Sec. 2 of T.27-2.

131

Fd - 1967 C.S. BCIP
BTs- 40" fir snag, 20-ft. tall bears N.4°W., 29.7-ft. (Orig. BT). Ren. #57.
5" fir down, & decaying, bears N.63°W., 9.2-ft. - scribing visible on open face. 1967BT.
12" fir bears S.11°W., 3.1-ft. w/closed face. 1967BT.
New BT- 6" fir bears N.38°W., 40.8-ft. scribed 1/4 S35 BT.

3/4/84

Ronald Geisler,
PLS #1988
For: Champion International
Mar.-Apr., 1984
M 90-55

Section corner for Sections 13 and 24.

132

Found - 1963 Douglas Co. brass disk on a 1" I.P. protruding 15" above ground in a 2 ft. dia. mound of stone, cap properly mkd. Ren. #30
A 16" x 10" x 8" stone found with 3 notches possible on one edge. (per 1910 resurvey)
6" now a 23" D. fir with a double well healed blaze bears N.67°W., 9.2 ft. (orig.)
10" now a 21" D. fir with one chopped out and rotted blaze, no scribing visible and a double well healed blaze bears S.27°W., 7.9 ft. (orig.)
9" now a 10" D. fir with a single well healed blaze bears S.63°W., 11.4 ft. (Ren. #30)
New BT - 8" hemlock double blazed and scribed "T26S R2W S13 CS BT" bears N.9 1/2°W., 16.5 ft.

Corner lies approx 100 ft. north of Hwy 138 on a south slope.

11/26/84

1/4 Corner for Sections 13 and 24. FD OK BY K. HOFFINE 6/07
Found - Approx. 5 x 6 x 12 inch stone from 1916 resurvey, marked "41-". Stone set on west edge of brass cap. SEE M 153-43.

133

A 1961 brass cap on an I.P. properly mkd., firmly set & protruding 12" from ground. Ren. @26
No evidence of orig. SW fir found.
Orig. Cedar, 8" now a 30" dead and fallen cedar with opened blaze, partial scribing visible. Root hole of this tree bears N.55°E., 9.9 ft.
No evidence of SW bearing tree found from 1916 resurvey. A private road has been built through this location.
11" I. cedar now 20" DBH with a well healed double blaze. No scribing visible bears N.32 1/2°E., 38.3 ft. Ren. #26
13" now 21" D. fir with a well healed double blaze. No scribing visible, bears S.12°W., 50.7 ft. Ren. #26
New BT - An 8" DBH D. fir scribed 1/4 S24 CS BT on a double blaze bears S.85°W., 95.1 ft. 45.1 ft. 7/3/07 JP (SEE CS 62/21-10)
6" DBH I. cedar scribed 1/4 S13 CS BT on a double blaze bears N.46 1/2°W., 53.7 ft.

Monument lies approx. 75 ft. west of boundary road and approx. 20 ft. north of a private road to the Circle K (K) Ranch.

12/20/84

Section corner for Secs. 13, 14, 23 and 24.

134

CORNER REPORT ONLY.

Found - 1961 DCSO disk on a I.P. protruding 6" above a 2 ft. mound of stone properly marked. Ren. #27
20" now a 38" D. fir with a double well healed blaze bears S.20°E., 21.1 ft. (Rec. 19.1 ft. is to face of blaze.) (orig.)
24" now a 30" dia. 1 ft. high decayed fir stump, no scribing or blazes found bears N.25°E., 44.9 ft. (orig.)

CORNER CONT NEXT PAGE

Randall Smith - Stephen Flause
Douglas County Surveyors Office
December, 1984
C.S. 62/21

Randall W. Smith
Stephen J. Flause
Deputies, Douglas Co.
Surveyors Office
November 26, 1984
C.S. 62/21