

Douglas County Surveyor's Record of  
Government Corners Renewed

T 26

T. S.

R 2

R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

c o n t - - -

(Sec. Cor. 14, 13, 23, 24)

134

Randall Smith  
Stephen Flause  
Doug. County Surveyors  
Office  
Dec. 19, 1984  
C.S. 62/21

No other orig BTs found.  
15" now a 20" D. fir with a well healed double blaze bears  
S.81°W., 33.7 ft. (Rec. S.83°W., 34.3 ft. per Ren. #27 is a  
slope measurement to face of blaze. (Rec. dist. 35.0 ft. per  
1975 BLM resurvey) Ren. #27  
6" now a 7" W. oak with a well healed double blaze bears  
N.86 1/2°W., 23.4 ft. (Rec. N.84 1/2°W. 24.1 ft. per Ren. #27  
dist. is a slope measurement to face of blaze.) (Rec. dist.  
24.4 ft. per 1975 BLM resurvey) Ren. #27  
7" now a 10" W. oak with a well healed double blaze bears  
S.70°E., 22.0 ft. Ren. #27  
5" now a 7" cedar with a partially healed double blaze scribe  
"X BT" bears N.66°E., 32.7 ft. per 1975 BLM resurvey.  
No new monument or accessories set. Corner lies approx 100 ft. North  
of boundary road.

12/19/84

135

Randall Smith  
Stephen Flause  
Doug. Co. Surveyors  
Office  
Dec. 19, 1984  
C.S. 62/21

Corner #2, Tract #37, Sec. 16 and 17  
Found - A 1918 U.S. GLO disk on an I.P. protruding 21 in. above ground  
properly marked.  
42" now a 31" dia. 2 1/2 ft. high decayed fir stump, no scribing  
or face found bears S.42°E., 59.4 ft. (Orig.)  
37" dia. maple with partially healed single blaze, illegible  
scribing visible bears S.33°E., 43.3 ft. Ren. #102  
Set - Set a 2 1/2 ft dia., 1 1/2 ft. high mound of stone around I.P.  
New BTs - 11" D. fir with a double blaze scribed "2 TR 37 CS BT" bears  
S.70°E., 45.2 ft.  
13" dia. D. fir with a double blaze scribed "2 TR 37 CS BT"  
bears N.43°E., 36.9 ft.  
Corner lies between North Umpqua Hwy and N. Umpqua River across Hwy from  
Frontier Store.

12/19/84

136

Douglas County  
Surveyors Office  
S.W. Flause, Party  
Chief  
R. W. Smith, Note-  
keeper.  
Oct. 11, 1985  
C.S. 62/29

East 1/16 corner between Sections 10 and 15.  
Found - 1959 BLM brass cap properly marked, firmly set 7 in. below  
gravelled road surface near east edge of traveled way.  
Orig. 9" Fir, now a 16" dia. 6" tall fir stump with evidence  
of a low blaze which is opened to reveal a face and a scribed  
" " bears N.37°E., 49.2 ft. (Rec. N.42 1/2°E., 49.5 ft.)  
(Difference in bearings apparent blunder of original survey).  
An orig. 10" Fir, now a 15" DBH D. Fir with a fully healed single  
blaze bears S.41 1/4°E., 51.5 ft. as per record.  
Set - Monument appears undisturbed despite slight distance error and  
apparent bearing blunder to original northeast bearing tree.  
Position of monument is accepted as found.  
New BTs - A bearing tree tag and boat spike are set at the new record  
bearing and distance in the north east bearing tree stump.  
An 8" DBH D. fir, scribed E 1/16 S10 CS BT on a double blaze  
bears N.49 1/2°W., 81.9 ft.  
A 7" DBH Incense cedar, scribed E 1/16 S15 CS BT on a double  
blaze, bears S.29°W., 27.2 ft.  
Note: From Diamond Lake Highway (State Hwy #138) proceed northwest  
on USFS Rd. #2-2-14, 1 + miles to Jct with USFS Rd #26-2-15. Proceed  
Northerly along this road .5 miles to monument near private driveway and  
house.

10/11/85

137

Douglas County  
Surveyors Office  
R.W. Smith  
S.J. Flause  
April 17, 1987  
C.S. 62/40

Section corner for Sections 1 and 12 only.  
Found - 1961 County brass cap on a 1" I.P. surrounded by a small mound  
of stones, protrudes 12" above ground. Cap mkd. with 1/4.  
4" now 15" Dia. D. fir with a fully healed single blaze bears  
N.33°W., 21.5 ft. (agrees with M47-7, 1910 resurvey and Ren. #25  
distance is 20.5 ft.) Orig. BT.  
36" now root hole with a tipped out 36" dia. D. fir that has a  
fully healed single blaze, root hole bears S.72°W., 29.0 ft.  
(Agrees with record) 1910 Resurvey.  
U.S.F.S. witness post and sign bears South, 5.3 ft. previously un-  
recorded, source unknown.