

Douglas County Surveyor's Record of
Government Corners Renewed

26 T.S. 2 R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Douglas Co. Surveyors Office - Stephen J. Flause - John Pike -
5/12/2005 - C.S. File 67/10-24

1/4 Cor. Secs. 7 & 8

161

Found - 2 1/2" dia., BC on 1" O.D. iron pipe projecting 1 ft. above
ground, loose, in low mound of rocks. BC (properly mkd)
is dated 1918
16" now 20" D.Fir bears N.33 1/2°W., 8.6 ft. (rec. N.35 1/2°W. 7.9
ft. 1918) orig. BT. Fully healed single blaze is faint.
35" now 39" D.Fir bears N.59 1/4°E., 9.9 ft. agrees w/rec.,
fully healed single blaze vis. illegible bark scribe
also visible. 1918 BT.
A rotted Fir snag 17" dia., approx 11 ft. tall healed blaze
vis. bears S.72°E., 6.1 ft. (rec. S.72°E., 5.3 ft.
1918) Orig. BT. Fits as face meas.
New - 8" dia., I.Cedar, pistol butted, double blazed & scribed "1/4
S8 CS BT" bears N.47°E., 32.4 ft.
8" dia., D.Fir, double blazed & scribed "1/4 S7 CS BT" bears
S.43 1/2°W., 17.9 ft.
Note - Corner lies on steep SE'ly facing slope.
Compass decl. 16 1/4°E.

Douglas Co. Surveyors Office - Stephen J. Flause - John Pike -
5/17/2005 - C.S. File 67/10-25

Cor. Secs. 7, 8, 17, & 18

162

Found - 3" BC on 2 1/2" IP projects 5" above ground US BLM cap dated
1959 (properly mkd)
12" now 15" hemlock, partially healed single blaze with
illegible scribing visible bears N.48°E., 42.6 ft.
(rec. N.51°E., 43.6 ft.)
12" now 18" R.Cedar partially healed single blaze with
scribing "S2W S17 BT" visible bears S.54°E., 40.4 ft.
(rec. S.54°E., 40.9 ft.)
8" now 12" Hemlock, now tipped onto rotted face no scribing
visible, tree is still alive, bears N.33°W., 36.3 ft.
to root hole.
SW BT gone.
New - 13" Chinquapin double blazed & scribed "T26S R2W S8 CS BT"
bears N.89°E., 23.3 ft.
23" Madrone, bark scribed "T26S R2W S7 CS BT" N.78°W. 1.5 ft
Note - Corner is at base of 23" dia., Madrone on bench area of NE
facing slope.

Cor. Secs. 14, 15, 22, & 23

163

Found - A granite stone measuring approx. 6x10x15" with 2
notches & 3 notches marked on the appropriate
faces (1909 Gibb resurvey) is fd loose, & out
of position, on ground surface. Stone is near
a hole with dimensions similar to base of
stone. 1957 DCSO brass cap not fd. (len #10)
Accessories fd bearings & distances are measured from
westerly edge of fd hole; most fd evidence indicates
this was the set position for the 1957 brass cap
from which the DCSO & 1959 BLM bearings & distances
were measured. The fd. evidence also indicates the
center of the fd. stone when properly oriented in
the above fd hole is the corner position established
in 1909 by Gibb.
Fd BTs- One orig. BT fd., A 12" fir now a 27" DBH D.Fir
with fully healed single blaze bears S.71 1/2°W.,
34.7' dist. (rec. S.70°W. 35.6') Possible root
hole of NW OBT fd no other orig evidence remains.
From the 1916 Mensch resurvey 3 renewal BTs are fd
(Following 3 bearings & distances noted as record
would be to center of 1909 stone monument)

continued next page

Douglas Co.
Surveyors Office
Stephen J. Flause
John Pike
1/6/2004
C.S. File 67/13-6