

Douglas County Surveyor's Record of
Government Corners Renewed

26 T. S. 3 R. W. W. M.

KECK-CHAPMAN CO., EUGENE, ORE. 21981

Renew $\frac{1}{4}$ corner to Section 8 and 17, 72
Set 1 inch X 36 inch iron pipe with Brass Cap marked County Surveyor, 1955.
From which: $\frac{1}{4}$ S 8 T 26 S. R3W.
Mt. Scott Lookout bears N. 12° $\frac{1}{2}$ ft. E
18 inch Apple bears N. 21° W. 21.0 marked $\frac{1}{4}$ S 8 CS BT.

James Byron
R. Irving
J. Fee
June, 1955
C.S. File No. 46/154

~~Center West 1/16 Corner.
Set 5/8 inch Iron Rod by Sec. Sub.
From which:
10 inch W.O. bears N. 25° E. 42.6 feet, scribed SW 1/16 CS BT.
10 inch W.O. bears N. 29° W. 33.8 feet, scribed SW 1/16 CS BT.~~

Center $\frac{1}{4}$ corner Section 17. 73
Set by Sec. Sub. from which a: 24 inch W.O. bears N. 45° W 35.5 feet
Set $\frac{3}{4}$ inch Iron Rod marked C $\frac{1}{4}$ S CS BT.
Found $1\frac{1}{2}$ Iron Pipe, Smith Acres 12 inch W.O. Bears N. 85° W. 79.0 feet
marked C $\frac{1}{4}$ S CS BT.

Renew N. E. Ext. L. Corner, D.L.C. 43. 74
Found - Buggy hub at corner and Eppstein's 12 inch now 14 inch W. Oak,
N. 53° W., 35.0 feet. Shows good scar but face rotted, not scribing
found. I also find Cole's 10 inch now 14 inch W. Oak S. 56° 30' W.
44.3 feet. Shows good scar face rotted. I do not open BTs. REN #9
Check for bearings & distances.
Set Brass Cap alongside Buggy Hub at corner marked: County Surveyor's Office
1957, N.E. Ext. L. D.L.C. 43 T.26 S., R.3 W.
New BTs: 12 inch R. Fir bears N. 32° W., 34.8 ft. scribed N.E. CL 43 CS BT.
7 inch W. Oak bears S. 49° E., 21.2 ft. scribed N.E. CL 43 CS BT.
Sept. 26, 1957

James W. Byron
M. Godfrey
S. Blaw
Sept. 26, 1957
C. S. File No. 49/18

$\frac{1}{4}$ Section Corner to Sections 19 & 20.
Found - Base of 30" Pine stump of original N. W. BT.
S. E. Original BT. now 36" B. O. down & partly rotted. I open
and find scribe marks near base. Both BTs. check for
bearing & distance.
1" Shaft in N. S. Fence Line set by Armstrong. REN #42
New Bearing Trees: 14" W. O. S. $56\frac{1}{2}^{\circ}$ W. 24.5 ft. $\frac{1}{4}$ S19 CS BT (Blaze & Scribe)
18" Pine N. 83° E. 44.8 ft. $\frac{1}{4}$ S20 CS BT (Blaze & Scribe)
Note: At $\frac{1}{4}$ corner there is parts of old North South Rail Fence 12 ft.
East of present wire fence. There having been an old fence
running parallel & 12 ft. East of existing fence line for a dist.
of 1000 ft.+ - North of $\frac{1}{4}$ Corner 19/20. Evidence based on trees
& brush growth. Mrs. Jones states Fence (existing) was West of
old line. Present wire fence seems to be at least 20 years old.

75
FD OK
4-4-4
K. DEB
1000/23/53
C.S. File No.

James W. Byron
M. Godfrey
J. Fee
For Hugh Jones
May 24, 1957
C. S. File No. 47/182

$\frac{1}{4}$ Section Corner to Sections 1 & 12. 76
Corner Renewed by Rerun of Tie shown on Plan C.S. File No. 47/112.
 $\frac{1}{4}$ Corner at shoulder of new North Ump. Hwy. All BTs. now gone,
taken out during construction of road. REN #26
Set Brass Cap at corner marked $\frac{1}{4}$ S 1 T26S R3W, County Surveyor's
S12 Office, 1957
New BTs: 12" R. Fir bears S. $38\frac{1}{2}^{\circ}$ E. 123.1 ft. scribed $\frac{1}{4}$ S12 CS BT.
36" Cedar bears N. 46° E. 80.5 ft. scribed $\frac{1}{4}$ S1 CS BT.

James W. Byron
M. Godfrey
S. Blaw
Dec. 18, 1957
C.S. File No. 49/48

Section Corner to Secs. 19, 30, R3W., & Secs. 24 & 25, R.4W. 77
Found - BT's. as recorded by Cole, 1916: REN #7
30", now 30" down Oak N. 61° W. 88.4 ft., I open & find
good scribing "BT".
All other BT's. down.
I do not find Drill Steel at Corner.
Note - Section Corner at - - - - -
Set Brass Cap at Section Corner Mkd: County Surveyor's Office, 1959

S24	S19
S25	S30

 T.26S.
R4W R3W
New BT's: 16" Laurel bears N. 4° W. 223.0 ft. scribed S24 T26S R4W CS BT.
3" Laurel bears N. 42° E. 37.0 ft. scribed CS BT.
12" R. Fir bears S. 68° E. 125.8 ft. scribed S30 T26S R3W CS BT.

James W. Byron, Deputy
M. Godfrey
S. A. Blaw
March 19, 1959
C. S. File No. 49/48

RENEWED CORNER NO. 170