

Douglas County Surveyor's Record of  
Government Corners Renewed

26 T. S. 3 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

98

$\frac{1}{4}$  Corner Sections 1 and 2.  
Found Shotgun Barrel at Corner & Both BT's., now stumps,  
show good scars, check bearings & distances. REN. #39  
New BT's: 7" R. Fir bears S.73°W. 3.6 ft. scribed  $\frac{1}{4}$  S 2 CS BT.  
18" R. Fir bears S.39 $\frac{1}{2}$ °E. 20 ft. scribed  $\frac{1}{4}$  S 1 CS BT.

C. S.  
File  
No.  
52/58

99

$\frac{1}{4}$  Corner to Sec. 1, T26-3W and Sec. 36, T25-3W.  
At this  $\frac{1}{4}$  corner I found the brass cap monument destroyed &  
the two bearing trees had been felled.  
I determined the true point of the corner from the stumps  
of these trees, and at this point I drove a 2" iron pipe  
30" long, 18" in the ground, from which:  
30" Hemlock bears N.53°E. 17.6 ft. mkd:  $\frac{1}{4}$  S 36 253 B.T.  
6" Tan-Oak bears S.19°E. 20.9 ft. mkd:  $\frac{1}{4}$  S 1 253 B.T.

V. W.  
Hosford  
Dec. 29,  
1960  
C. S. File  
# 51/161

Fd. by:  
R. WARE  
Oct. 1982  
M 93-26A/B

100

Witness Corner to  $\frac{1}{4}$  Corner Sections 18 and 19.  
Found - Gun Barrel set for  $\frac{1}{4}$  Corner.  
Set - Brass Cap at Corner Mkd: County Surveyor's W.C. 30' South  
Office, 1961 to  $\frac{1}{4}$  S18 T26S R3W Road Dept.  
For:  
S19  
26" Dbl. W.Oak bears N.26°E. 23.0 ft. scribed W.C.  $\frac{1}{4}$  S18 CS BT. C.S. 38/164  
FD OK - 4/75 G. BAUGHMAN M55-64 Nov. 1961

RM 1-27  
By James W.  
Byron  
C.S. 38/164

Fd. 2/84  
by R. WARE  
M 96-16

RE-RENEWED, SEE CORNER NO. #237

101

$\frac{1}{4}$  Cor. to Sec. 6, T26-3W. & Sec. 31, T25-3W. REN. #16A  
Found - Iron Pipe with Brass Cap Mkd: "U.S. General Land Office  
1943  $\frac{1}{4}$  S 31"  
S 6"  
Fir Stump, 21", S.61°W. 4 ft., scribing still visible in  
partly closed scar. "S6 BT".  
20" Fir Stump N.26°E. 7.3 ft., scribing visible in open  
scar " $\frac{1}{4}$  S31 BT".  
New BT's: 11" D.Fir S.11°E. 12.8 ft. Mkd:  $\frac{1}{4}$  S6 CS BT.  
13" D.Fir N.4°W. 17.4 ft. Mkd:  $\frac{1}{4}$  S31 CS BT.  
Corner is 70 feet North of a Fence Line running E. & W.

Milo E. Godfrey, Deputy  
Vernon Tracy  
Mike Stone  
July 31, 1962  
D.S. File No. 49/102

RE-RENEWED, SEE CORNER NO. 145

102

Section Corner: Sections 25, 26, 35, 36.  
Found - 25" D.Fir, S.46° W., 9.8 feet.  
36" D.Fir Stump N. 23° W., 25.5 ft.  
Set - 2 $\frac{1}{2}$ " Aluminum Cap.  
10" Maple S. 74° E., 46.2 ft. Mkd: S36 BT.  
18" Cedar N. 78 $\frac{1}{2}$ ° W., 31.0 ft. Mkd: S26 BT.  
8" Yew, N. 52° E., 31.2 ft. Mkd: S25 BT.

Thomas E.  
Shrum, Jr.  
U.S. Plywood  
U. S.  
File  
No. 51/254

November 1962

103

$\frac{1}{4}$  Center of Section 2.  
Set -  $\frac{1}{2}$ " monel pipe.  
Referenced by Glen McChesney (Plates & "W" nails only)  
Decl. 20°  
28" W.Fir St. N.55°W. 28.7 feet.  
48" I.Cedar St. S.57°W. 24.9 feet.

Weyerhaeuser  
Co.  
By L. Calder  
Aug. 1943  
C.S. File  
No. 51/87

RE-RENEWED, SEE CORNER NO. #204

104

Section Corner to Sections 16 - 17 - 20 - 21.  
Found - Rotten Fir Stump N.44°W. 51.5 ft., good scribing fd., "BT".  
Rotten Fir Stump S.76°W. 33.7 ft., fragments of scribing visible.  
Rotten Fir Stump S.32°E. 39.6 ft., shows good scar, Didn't open.  
Rotten Fir Stump N.68°E. 22.4 ft. (34 lks., not 24 lks.)  
Good scribing visible on previously opened face.  
Note - These are all trees mkd. by Eppstein in 1928,  
See Renewal No. 27.  
36" Fir Stump fits approx. location for Germond's N.E.  
Tree, no marks found on stump. (See Ren. No. 82.)  
No Original Bearing Trees found.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T26S R3W S17/S16  
Office, 1963 S20/S21  
New BT's: 14" D.Fir N.72 $\frac{1}{2}$ °E. 132.6 ft. Mkd: T26S R3W S16 CS BT.  
22" Madrone N.32 $\frac{1}{2}$ °W. 300.0 ft. Mkd: T26S R3W S17 CS BT.  
NO OTHER TREES AVAILABLE - CORNER LIES IN FENCE CORNER.

Milo E. Godfrey & Crew  
Sept. 1963  
S. S. FILE  
No. 53/34

FD. OK 3/92  
G. BAUGHMAN M 114-72

FD OK PER BAUGHMAN  
4-88 M 106-1