

Douglas County Surveyor's Record of
Government Corners Renewed

T. 26. S. T. S. R. 3 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Milo E. Godfrey & Crew
Octo. 22, 1963
C. S. File No. 53/33

Milo E. Godfrey, Deputy Co. Surv.
Wm. Stoffel & Mike Stone
December 1963
C. S. File No. 53/34

Township Corner - T26S
R4W S 36 | S 31 R3W
S 1 | S 6
T27S
105
RE-RENEWED CORNER NO. #241 (#27 in T. 26-4)
Found - Iron Pipe with Brass Cap set by Richardson in 1947. (See Cor. No. 94)
35" W. Oak N.15°W. 231.5 ft., shows good scar. Tree alive & gd. cond.
10" W. Oak S.81°W. 195.8 ft., now dead snag, all scribing visible.
Stump of 36" Fir S.6°E. 543.8 ft., bark scribing visible.
New BT's: 12" D. Fir S.28°E. 444.6 ft. Mkd: T27S R3W S6 CS BT.
26" W. Oak S.76°W. 175.7 ft. Mkd: T27S R4W S1 CS BT.
This tree was marked as BT. in 1917 survey, scar previously opened and old face rotted away, new scribing above old face.
Note - Corner is approx. 6" North of E. & W. fence line & 200 ft. East of Buckhorn Road.

1/4 Section Corner to Sections 30 and 29. 106
Found - 10" Fir (dead) N.83°E. 24.7 ft., previously opnd, good scribing, "1/4 SCS" visible on partially rotted face, (Eppstein's) Ren. #11.
20" W. Oak S.71°W. 35.9 ft., prev. opnd., scrbng. vis. "B". on badly rotted face. (Germond's BT.)
Did not find Iron Pipe set by Eppstein.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963
T26S R3W 1/4 S30/S29
New BT's: 10" D. Fir N.37°W. 24.6 ft. Mkd: 1/4 S30 CS BT.
24" D. Fir N.54°E. 27.0 ft. Mkd: 1/4 S29 CS BT.
Note - Corner is 2.5 ft. South of E. & W. Fence. Line.

Section Corner to Secs. 29 - 30 - 31 - 32. 107
Found - 36" Bl. Oak N.62°W. 21.8 ft., prev. opnd, good scrbng. on old face. (See Ren. No. 12)
29" Bl. Oak N.44°E. 128.0 ft., Top broken out of this tree, but still alive, prev. opnd., both old faces visible, but scrbng. gone.
30" Bl. Oak N.80°W. 19.8 ft., opened many years ago & face rotted away (Orig. BT).
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963
T26S R3W S30 | S29
S31 | S32
New BT's: 8" Madrone S.49°E. 47.2 ft. Mkd: T26S R3W S32 CS BT.
8" Madrone S.82°W. 47.0 ft. Mkd: T26S R3W S31 CS BT.
25" Bl. Oak N. 8°W. 45.4 ft. Mkd: T26S R3W S30 CS BT.
16" Bl. Oak N.25°E. 88.5 ft. Mkd: T26S R3W S29 CS BT.
Note - Fence Corner (fences S. & E.) bears S.70°W. 4 feet.

1/4 Corner to Sections 31 and 32. 108
Found - Rock Mkd: "1/4 S" on E. face, also cedar stake rotted off & lying on ground beside Rock. See Ren. No. 19
28" B. Oak S.33°E. 83.3 ft., has been opened prev. & face badly rotted, Portion of reverse scribing on overgrowth.
Stump Hole & rotted remnants of Oak Stump N.35°E. 21.8 ft. (Orig. BT)
No trace of Orig. N. W. Bearing Tree.
Set - Brass Cap alongside Rock at Cor. Mkd: County Surveyor's Office, 1963
T26S R3W 1/4 S31/S32
New BT's: 16" D. Fir S.70°E. 33.8 ft. Mkd: 1/4 S32 CS BT.
12" D. Fir N.49°E. 26.8 ft. Mkd: 1/4 S32 CS BT.
No trees avail. W. of Line. Cor. lies 4.6' E. of N-S Fence Line.

1/4 Corner to Sections 30 and 29. 109
Found - 10" Fir (dead) N.83°E. 24.7 ft., prev. opnd, good scribing, "1/4 S CS", visible on partially rotted face. (Eppstein's BT) Ren. No. 11.
20" W. Oak S.71°W. 35.9 ft., prev. opnd. (Germond's BT).
Did not find Iron Pipe set by Eppstein.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963
T26S R3W 1/4 S30/S29.
New BT's: 10" D. Fir N.37°W. 24.6 ft. Mkd: 1/4 S30 CS BT.
24" D. Fir N.54°E. 27.0 ft. Mkd: 1/4 S29 CS BT.
Note - Corner is 2.5 ft. South of E. & W. Fence Line.