

Douglas County Surveyor's Record of
Government Corners Renewed

T 26 S. T. S. R. 3 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

121
 $\frac{1}{4}$ Corner Sec. 2, T26-3W. & Sec. 35, T25-3W.
 Found - 1943 GLO Brass Cap set by prop. measurement.
 22" White Fir N. $22\frac{1}{2}^{\circ}$ E. 15.2 ft., scribing on down
 26" White Fir.
 50" D. Fir S. 51° W. 35.6 ft., stump of recently
 felled 50" Fir Snag, part of scribed face vis.
 New BT's: 18" White Fir N. 20° E. 12.3 ft. "W" Nail & Plate.
 38" Cedar N. 52° W. 42.0 ft. added "W" Nail & Plate."
 50" Fir Stump S. 51° W. 34.0 ft. "W" Nail & Plate.
 Note - Old growth to North, recently logged to South.

Glen McChesney,
 Weyerhaeuser Co.
 March 10, 1964
 C. S. File
 No. 53/115

122
 $\frac{1}{4}$ Corner to Sec. 36, T26-3 & Sec. 31, T26-2.
 Found - Very old 4"x4" sq. post scribed "S31" on E. & " $\frac{1}{4}$ S36" on W. face.
 6", now 10" Cedar Stub 4' high, S. 83° W. 5.3 ft., open &
 shows part of " $\frac{1}{4}$ " & all of "S36BT". (Orig. BT.)
 24", now 34" Fir, down, N. 50° E. 15.8 ft., shows scar.
 Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1966
 T26S $\frac{1}{4}$ R3W S 36 / S 31 R2W
 New BT's: 5" D. Fir S. 47° E. 24.5 ft. Mkd: $\frac{1}{4}$ S31 CS BT.
 12" R. Cedar N. 9° W. 29.6 ft. Mkd: $\frac{1}{4}$ S36 CS BT.

123
 Section Corner to Secs. 25 & 36, R3W. & Sec. 30 & 31, R2W.
 Found - Orig. 26" D. Fir S. 45° E. 21.8 ft., prev. opened &
 shows good "S" scribe.
 No trace of S.W. BT. & N. E. BT. could be spotted log laying
 in approximate location.
 Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1966

R3W	S 25	S 30	R2W
	S 36	S 31	

 New BT's: 6" D. Fir N. 61° E. 4.5 ft. Mkd: T26S R2W S30 CS BT.
 6" D. Fir N. 5° W. 16.4 ft. Mkd: T26SR3W S25 CS BT.
 7" D. Fir S. 37° W. 7.5 ft. Mkd: T26S R3W S36 CS BT.

Vernon "Ray" Tracy
 Mike Stone & Jerry Layne
 January 1966
 C. S. File No. 54/7

124
 WEST Center 1/16 of Section 9.
 Found - 1924 GLO Brass Cap Mkd: "W1/16 S9".
 14", now 26", Ash N. 21° E. 8.6 ft., down & dead. Do not open.
 S. W. Bearing Tree gone.
 New BT's: 15" Ash S. 56° W. 66.6 ft. Mkd: "C W 1/16 S9 CS BT".
 12" B. Oak N. 85° E. 63.6 ft. Mkd: "G W 1/16 S9 CS BT".
 This corner lies 25 ft. East of small creek, course S. W.

125
 South C.1/16 of Section 9.
 Found - 1924 GLO Brass Cap Mkd: "S 1/16 S9".
 20" Cedar Stump N. 50° E. 5.3 ft., badly rotted, no scribing
 found.
 S. W. BT. gone.
 New BT. - 8" D. Fir N. 6° E. 56.4 ft. Mkd: "S 1/16 S9 CS BT".
 We use S. E. Corner of "Royal Coachman Cafe" as bearing
 object, bears N. 88° W. 23.5 ft.
 Power Pole bears S. 34° W. 10.2 ft.
 Corner lies at end of old wire fences approx. 50 ft. off N. Ump. Hwy.

126
 S.W. 1/16 of Section 9.
 Found - 1924 GLO Brass Cap Mkd: "SW 1/16 S9".
 7", now 20", Cedar S. 5° E. 7.9 ft., recorded S. 55° E. Open
 & find reverse "W" scribe.
 Stump Hole bears N. 2° W. 16.5 ft.
 New BT's: 17" D. Fir N. 77° W. 36.9 ft. Mkd: SW 1/16 S9 CS BT.
 11" W. Oak S. 9° E. 48.6 ft. Mkd: S W 1/16 S9 CS BT.
 This corner lies at fence corner with fences E. - W. & S.