

Douglas County Surveyor's Record of  
Government Corners Renewed

T 26

T. S.

R 3

R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

215

Section Corner for Secs. 1 and 12; and Secs. 6 & 7 of T26-2.  
Found - 1959 Cadastral brass cap on a 2 1/2" I.P. 7" above ground properly marked.  
A 15" now 36" Cedar stump is pushed over. Orig. position bears approx. S.60°W., 19.8 ft. but no visible blaze. (OBT).  
Remains of a Fir stump bears N.46°W., 58.1 ft. (OBT)  
A 12" now 13" Cedar snag bears S.73°E., 27.1 ft. with scribing "T26S R2W S7 BT" in single blaze. (1959 resurvey).  
A 50" Fir stump with a Weyerhaeuser tag and blaze bears S.60°W., 35.0 ft.  
A 28" Fir stump with a Weyerhaeuser tag and blaze bears N.59°W., 47.4 ft.  
New BT's- A 13" Cedar with "MR" carved in West face bears N.83°E., 20.0 ft. double blazed and scribed "T26S R2W S6 CS BT".  
A 10" D. Fir bears S.20 1/2°E., 124.1 ft. double blazed and scribed "T26S R2W S7 CS BT".  
A 3" "X" chiseled 3 ft. above ground in a 20 ft. x 20 ft. boulder bears S.88 1/2°W., 32.0 ft.  
A 6" Chinkapin bears N.50°W., 71.8 ft. double blazed and scribed "T26S R3W S1 CS BT".  
Corner is 30 ft. north of road.

R. B. Kimberling  
P.L. Earle  
S.J. Flause  
Doug. Co. Surveyors  
Office  
Jan. 10, 1978  
C.S. 59/46

1/10/78

216

Witness Corner to Sec. Corner for 11, 12, 13 and 14.  
Found - 1" I.P. approx 10" above ground attached cap marked 1964 County Surveyor W.C. T26S S11 S12 S14 S13 70 ft. E to Cor. Found no trace of orig. corner or bearing trees. Corner falls in road. Ren. #111  
A Red Cedar 23" now 25", alive with broken top bears N.5°E., 35.4' Found scribing on double blaz. "WC T26S R3W S12 CS BT" partially healed.  
A Red Cedar 39" now a 40" windfall bears S.51°W., approx 37 ft. Tree scribed "WC T26S R3W S13 CS BT" on double blaze.  
A Red Cedar 38" now 40" broken stump bears S.75°E., 15.0 ft. scribing visible on partially healed double blaze. "WC T26S R3W S13 CS BT".  
A 14" Hemlock found cut and uprooted has been displaced from orig. position. Scribing found "CS BT".  
No new monument set.  
New BT - A Red Cedar 12" bears N.88°W., 42.6 ft. tree scribed "WC S11 CS BT" Corner lies approx 40 ft. SW of road and approx 40 ft. NW of a draw running NE. This corner lies in a clear cut area.

Gary L. Langlitz  
L.E. Monrean  
Frank Silagy  
Doug. Co. Surveyors  
Office  
March 15, 1978

3/15/78

217

Center 1/4 Corner for Sec. 12  
Found - A partially rotten squared wooden post, (see C.S. 53/115) bears S.58°W., 1.7 ft. from the center 1/4 corner as established in this renewal.  
From the found wooden post, a 30" Red Cedar bears N.16°W., 3.3 ft. with Weyerhaeuser tag.  
A 40" D. Fir now a windfall bears S.15 1/2°E., 16.4 ft. with Weyerhaeuser tag. (note: our distance measurements extend to the center of these trees.)  
Set - Corner location determined by survey. (M 65 - 73) At the corner point, WE SET a 1" x 30" I.P. 28" in the ground with brass cap attached marked: Douglas County Surveyor T 26 S  
1978 C 1/4 S 12  
R 3 W  
New BT's-A 30" Red Cedar, scribed "C 1/4 S12 CS BT" on a double blaze bears N.35 1/2°W., 3.4 ft.  
A 6" Grand Fir scribed "C 1/4 S12 CS BT" on a double blaze bears N.48°E., 9.4 ft.  
Corner located at NE corner of recent clearcut unit.

3/9/78

Gary L. Langlitz  
Larry E. Monrean  
Stephen J. Flause  
Douglas County Surveyors Office  
M 65 - 73 C.S. 60/7  
March 1978