

Douglas County Surveyor's Record of  
Government Corners Renewed

T 26

T. S.

R 3

R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

223

Gary Langlitz  
Frank Silagy  
Doug. Co. Surveyors  
Office  
Witness: Glen  
McChesney,  
Weyerhaeuser Timber  
Co.  
July 20, 1978  
C.S. 60/11

1/4 Corner for Sec. 24 and Sec. 19 of T26-2  
Found - No trace of orig. 1855 or 1910 corner posts.  
No trace of orig. 1855 BT's. Ren. #92  
From 1910 retracement, we find: A 10" now 13" Laurel (Madrone)  
alive with fragmentary reverse scribing found on unhealed  
blaze, bears N.69°E., 8.6 ft.  
A 10" now 15" Laurel (Madrone) alive with well healed blaze  
which we open and find good face but no scribing, bears  
S.24°W., 6.6 ft. (Rec. S.21°W., 6.6 ft.)  
Set - At a location which agrees with measurements shown to the  
previously described resurvey bearing trees, WE SET: a 1" x 30"  
Iron pipe, 27" in the ground with brass cap attached marked:  
Douglas County Surveyor T 26 S  
1978 S 24 | S 19  
R3W 1/4 R2W  
New BT's- A 32" D. Fir, scribed "1/4 S19 CS BT" on a double blaze, bears  
S.52°E., 16.7 ft.  
A 16" D. Fir scribed "1/4 S24 CS BT" on a double blaze, bears  
S.71°W., 33.6 ft.  
Our new SE bearing tree, a 32" D. Fir was previously used as a  
reference point by Weyerhaeuser, (Ren. #58 and 92), new  
measurements to "W" nail, S.53 1/2°E., 15.3 ft.  
We search for evidence in a 20" Hemlock stump bearing S.38°W., 8.1 ft. on the  
suspicion that this may be the orig. 1855 SW bearing tree, A "15 Spruce".  
No evidence found. This stump was used by Weyerhaeuser to reference this  
corner. We remove the "W-nail" in the course of our search

1-79

1/4 Corner for Sec. 24 and Sec. 25 of T26-3  
Found - 1" x 36" I.P. with brass cap marked "County Surveyors Office"  
T26S R3W 1/4 S24 S25 1957 protruding 12" above ground 224  
20" Fir, now 34" bears N.10°E., 19.9 Ft. to center (Rec. N.40°E.,  
15.2 ft.) Traces of bark scribing (orig.) Ren# 91  
Root Crown bears S.10°E., 9.9 ft., with a down Fir alongside "BT"  
visible. (orig.) (Ren#62)  
10" Sugar Pine, now 14", bears S.78°E., 31.9 ft., with healed blaze.  
12" Fir, now 18", bears N.89°E., 3.3 ft. with well healed blaze (Ren.62)  
No new monument set.  
New BT's- 25" trunk of a triple trunk Cedar bears S.34°W., 85.7 ft with  
scribing "1/4 S25 CS BT" in a double blaze. 7/20 /78

SEE C.S. 58/146  
for a 1984 CONDITION  
REPORT

Karen Reed  
P.L. Earle  
Douglas Co. Surveyors Office  
May 9, 1979  
C.S. 60/24

Sec. Cor. for Sec. 24&25; Sec. 19&30 of T26-2  
Found - 8"x10"x14" granite stone, 4 notches on north, 2 notches on south  
lying on top of ground. (Rec. buried 10" below ground) (1902 Res)  
No trace of original BT's  
8" Fir, now 22", bears N.58°E., 17.5 ft. (Rec. N.52°E., 17.8 ft;  
1902; N.55°E; 16.7 ft to face Ren#57) with well healed blaze.  
8" Fir, now 18" bears S.14°E., 17.6 ft. with healed blaze  
(Rec. S.16°E., 16.9 ft) to face.  
6" Fir, now 15" bears N.25°W., 12.4ft. visible scribing in  
chopped out blaze "S24 BT" (Rec. N.18°W., 11.9 ft., 1902;  
N.20°W., 11.8ft. to face Ren#57)  
16" Fir, bears S.51°W., 18.3 ft. with healed blaze. (Rec.S.56°W.,  
17.6 ft. to face. Ren#57)  
Set - 1" x 36" I.P. with brass cap marked "Douglas County Surveyor"  
Protruding 6" above ground T 26 S  
and stone 14" in ground on R S 24 | S 19 R  
west side of cap. 3 S 25 | S 30 2  
W 1979 W

Note: Bearings and distances did not hit one spot - Placed cap at  
appropriate distance securing a bearing to the 18" Fir, S.14°E.

5/9/79

225