

Douglas County Surveyor's Record of
Government Corners Renewed

T 26 T. S. R 3 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

240

Witness corner for 1/4 Corner for Sections 10 and 11.
Found - 1977 County brass cap 2 1/2" dia. on a 1 1/4" I.P., firmly set,
protruding 4" above ground, properly mkd. Ren. #208
A 5/8" I.R. is set protruding 3" above ground at North edge of
above brass cap monument. Ren. #201
Remaining BTs from Renewals #23 and 61 have effaced blazes,
bearing and distances of these trees relate only to erroneous
corner position (See C.S. File 59/21). They are not checked.
7" Oak now a 10" D.B.H. W. oak with well healed double blaze
bears S.80°E., 12.3 ft. (Rec. S.75°E., 12.3 ft.) Scribing
& blaze from 1957 removed previously. Ren. #201
8" Oak, now a double trunk W. oak with the most easterly &
blazed trunk measuring 6" D.B.H.; has a partially healed
double blaze with scribing WC 1/4 S10 BT visible and bears
S.60°W., 18.9 ft. (Rec. S.58°W., 18.6 ft.) This measurement
is good to center of blazed trunk at breast height. Ren. #201
A 5/8" Dia. I.R. (marking position of 1957 brass cap) bears
N.77°E., 84.0 ft. (Rec. N.80°E., 84.0 ft.) firmly set and
protruding 3" from ground. Ren. #208
New B.O.- A 1/2" Dia. I.R. firmly set & protruding 6" above ground bears
S.66°W., 23.0 ft. (Rec. S.67 1/2°W., 23.15 ft. M85-58). This
Monument is the most easterly southeast corner of parcel #1
DCSO map file M 59 - 8.
Monument is located 8.3 ft. south of south guard rail of Hwy 138 and just
north of high bank of N. Umpqua River.

Larry E. Monrean
Douglas County
Surveyors Office
S. J. Flause
R. W. Smith
Dec. 21, 1984
C.S. 62/21

12/21/84

241

Township corner for Sec. 31; Sec. 36, T.26-4; Sec. 1, T27-4; Sec. 6, T27-3.
Found - A 2 1/2" County brass disk on a 2" I.P., protrudes 4" above
ground, properly mkd. Ren. #94
10" now 32" dia. W. oak with a previously opened now rotted face
and a single well healed blaze per Ren. #105 bears S.76°W.,
175.7 ft. 1917 resurvey
36" now a 48" dia. 3 ft. high D. fir stump with bark scribing
"S BT" bears S.6°E., 543.8 ft. Ren. #94
30" now a 30", 2 ft. high W. oak stump with a possible blaze,
bears N.15 1/2°W., 233.1 ft. (Rec. 231.5 ft. to face) Ren. # 94
12" now a 22" D. fir with a well healed double blaze bears
S.26 1/2°E., 443.8 ft. (Rec. S.28°E., 444.6 ft.) Ren. #105
No original BTs found and the SW BT gone from 1947.
New BT - 6" dia. W. oak double blazed and scribed "T26S R3W S31 CS BT"
bears N.53 3/4°E., 293.1 ft.
Corner lies 6" north of an E-W fence line and approx 200 ft. east of
Buckhorn Road in a pasture.

Randall Smith
Stephen Flause
Douglas County
Surveyors Office
January 9, 1985
C.S. 62/25

1/9/85

242

Angle Point #18, Section 9
Found - 1972 BLM brass cap NOT FOUND. The location of the corner
and one of the BTs fall in a slide area.
We establish a temporary point from undisturbed BT as follows:
A 20" dia. fir with well healed blaze and BT tag bears
N.11°W., 63.4 ft. This tree appears to be undisturbed.
A 15" now 18" fir with a well healed single blaze is dislodge
by slide activity, bears N.23 1/2°E., 49.5 ft. (Rec.
N.20°E., 35 ft.) Tree is still standing but leaning.
New BT - 17" fir double blazed and scribed "AP 18 S9 CS BT" bears
N.85 1/2°E., 115.0 ft.

Larry E. Monrean
Deputy, Douglas Co.
Surveyors Office
Randy Smith
Jan. 25, 1985
C.S. 62/25

243

Angle Point #19, Section 9 CORNER REPORT ONLY
Found - 1972 BLM brass cap monument set flush with surface in road fill.
A fir, 10" now 15" dia. has well healed blaze bears North 31.0 ft.
An 8" dia. fir with healed blaze bears N.29°W., 45.5 ft.
(Rec. 46.9 ft.)
A 1/2" Iron pipe bears N.20°W., 8.2 ft.
A 5/8" dia. iron rod in fence corner bears N.1°E., 7.7 ft.