

Douglas County Surveyor's Record of  
Government Corners Renewed

T 26

T. S.

R 3

R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97101

Larry E. Monrean  
Deputy, Douglas  
County Surveyors  
Office -  
R. Smith  
1/25/85  
C.S. 62/25

Witness Point for 1/4 Corner, Sections 9 and 10  
CORNER REPORT ONLY

244

Found - 1972 BLM iron pipe with brass cap attached, firmly set.  
A 10" fir now 13" dia. bears S.52°E., 31.1 ft. (Rec. S.56°E.,  
31.7 ft.) Tree has partially healed lower blaze with some  
scribing visible, well healed upper blaze.  
A 8" fir, now 10" with partially healed blaze bears S.65°W.,  
8.5 ft. (Rec. 9.2 ft.)

Romanso E. Ware  
RPLS #1005  
12/85  
M 100 - 7

Center 1/4 Section Corner for Sec. 20

Set - 5/8" x 30" iron rod, with cap marked "R.E. WARE L.S. 1005"  
BT's - A 42" Triple Oak, bears S.2°E., 54.5 ft. dist., scribed C1/4  
S20 BT.  
A 6" D. Fir., bears N.71°E., 113.4 ft. dist., scribed C1/4 S20  
BT.

245

Douglas County Surveyor  
Office  
Stephen J. Flause  
R. W. Smith  
Carol Owre  
December 19, 1985  
C.S. 62/29

1/4 Corner for Sections 2 and 11

Found - DCSO brass cap on an iron pipe, properly marked, firmly set and  
protruding 4 inches above ground. Ren. #205  
5/8" dia. iron rod firmly set and protruding 10 inches from ground  
on NW edge of DCSO brass cap. Ren. #200  
12" D. fir now a 13" DBH D. fir with a fully healed double blaze  
bears N.11°W., 24.0 ft. (Rec. N.8°W., 24.0 ft.) Ren. #200  
24" D. fir now a 26" DBH D. fir with a fully healed double blaze  
bears S.11°E., 25.7 ft. (Rec. S.8°E., 25.7 ft.) Ren. #200  
5/8" dia. I.R. marking position of Eppstein's 1/4 corner for  
sections 2 & 11 (see Ren. #'s 5, 54, 113, 164) is firmly set  
and protruding 6 inches above ground bears N.28 3/4°E., 119.9 ft.  
(as per rec. Ren. #205)

246

Monument position is accepted as found. Magnetic bearing and taped distance  
agree with traverse bearing and dist. recorded by Eppsteins 1/4 corner in  
Renewal #205. An error in declination is apparently repeated in measurement  
to the bearing trees in Renewal #'s 200 and 205.  
Corner lies on small bench near top of a steep southerly slope and is  
approx. 1700 ft. northeast of the point where Kimmel Lane turns west in  
T26S, R3W S11.

12/19/85

Ronald Geisler  
For: Champion  
International  
Field Crew:  
Lynn Sibley  
Dean Turner  
June 30, 1987  
C. S. 63/60

Section corner for Secs. 25 and 36; and Secs. 30 & 31 of T.26-2  
Found - 1966 County 2 1/2" brass cap on a 1" iron pipe extends 12"  
above ground. Ren. #123

9" D. fir bears S.37°W., 7.5 ft. Healed face. (1966)  
9" D. fir bears N.5°W., 16.4 ft. Healed face. (1966)  
36" D. fir bears N.45°W., 21.8 ft. Chopped face. Brag marks  
visible. (original)  
8" D. fir now down and uprooted bears N.61°E., 4.5 ft. (1966)  
New BT - 5" D. fir bears N.74°E., 23.3 ft. scribed "T26S R2W S30 BT".

247

6/30/87

248

1/4 Corner for Sections 11 and 12

Found - A 2" O.D. alum. pipe protruding 12" above ground. Source unknown.  
A position at record (S.44°W., 56.1 ft.) was occupied from 23"  
Cedar BT (Ren. No. 36), no other evidence of record found to  
place monument at this position.  
36" now approx 38" dia. 3 1/2 ft. high rotted D. fir stump, no blazes  
or scribing found bears S.15°W., 7.6 ft. Agrees with record  
per Ren. #212 (orig. record is S.10°W., 6.6 ft.; dist. is a  
possible face measurement) Possible Orig. BT.  
15" now 23" dia. cedar with a partially healed upper and fully  
healed lower blaze, scribing visible in upper blaze "S11CS"  
bears S.59°W., 56.1 ft. agrees with record per Ren. No. 212.  
(Rec. from Ren. No. 36 15" fir, S.44°W., 56.1 ft.) note tree  
species is a cedar in BB Irving field book. Per Ren. #36.  
18" dia. Fir per Ren. #36 gone, possible stump hole found bearing  
S.41 1/2°E., 29.7 ft. (Rec. S.28°E., 29.7 ft.) per Ren. #36.

Note: bearings on BTs from Ren. #36 are north of their record position by  
approx. the same angle.

Douglas County  
Surveyors Office  
Randall Smith  
Stephen J. Flause  
May 18, 1988  
C.S. 62/52